

STATE OF NEW MEXICO
ENERGY AND MINERALS DEPARTMENT

OIL CONSERVATION DIVISION
P. O. BOX 2088
SANTA FE, NEW MEXICO 87501

Form C-103
Revised 10-1-78

NO. OF COPIES RECEIVED	
DISTRIBUTION	
SANTA FE	
FILE	
U.S.G.S.	
LAND OFFICE	
OPERATOR	

5a. Indicate Type of Lease	
State ☐	Fee ☒
5. State Oil & Gas Lease No.	

SUNDRY NOTICES AND REPORTS ON WELLS

(DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A DIFFERENT RESERVOIR. USE "APPLICATION FOR PERMIT" (FORM C-101) FOR SUCH PROPOSALS.)

CIL WELL ☒ GAS WELL ☐ OTHER ☐		7. Unit Agreement Name N. HOBBS (G/SA) UNIT
Name of Operator SHELL WESTERN E&P INC.		8. Form or Lease Name SECTION 32
Address of Operator P. O. BOX 576, HOUSTON, TEXAS 77001 (WCK 4435)		9. Well No. 231
Location of Well UNIT LETTER K 2310 FEET FROM THE SOUTH LINE AND 2310 FEET FROM THE WEST LINE, SECTION 32 TOWNSHIP 18S RANGE 38E NMPM.		10. Field and Pool, or Widest HOBBS (G/SA)
11. Elevation (Show whether DF, RT, GR, etc.) 3632' GR		12. County LEA

Check Appropriate Box To Indicate Nature of Notice, Report or Other Data.

NOTICE OF INTENTION TO:

SUBSEQUENT REPORT OF:

PERFORM REMEDIAL WORK ☐	PLUG AND ABANDON ☐	REMEDIAL WORK ☐	ALTERING CASING ☐
TEMPORARILY ABANDON ☐	CHANGE PLANS ☐	COMMENCE DRILLING OPERATIONS ☐	PLUG AND ABANDONMENT ☐
PULL OR ALTER CASING ☐	OTHER ☐	CASING TEST AND CEMENT JOB ☐	OTHER ☒ wso, perf & acidz

17. Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work) SEE RULE 1103.

6-15 to 6-28-88:

POH w/prod equip. Tagged btm @ 4135'. DO hydromite plug & CIBP @ 4168', Knocked to btm @ 4230'. Set cmt ret @ 4004'. Attempted to sqz San Andres perms 4109'-92' & OH 4194'-4230' w/125 sx Cls "C" cmt + 2% CaCl₂ + 1.5% Howco suds + 0.75% HC-2 + 200 scf N₂/bbl followed by 150 sx Cls "C" cmt + 2% CaCl₂. DO cmt (& cmt ret @ 4004') 3360' - 4190'. Set pkr @ 3850'. Sqzd w/50 sx Cls "C" cmt + 2% CaCl₂. DO cmt 3850' - 4147'. Pres tstd sqz to 500#, held OK. DO cmt to 4230'. Perf'd 4185' - 88' (2 SSPF). Tagged @ 4205'. Circ'd dwn to 4225'. Perf'd OH 4194' - 4222'. Acid perms 4185' - 88' & OH 4194' - 4225' w/1500 gals 15% HCl-NEA + 400# rock salt. Installed prod equip & ret'd well to prod.

I hereby certify that the information above is true and complete to the best of my knowledge and belief.

SIGNED <u>A. J. FORE</u>	TITLE <u>SUPERVISOR REG. & PERMITTING</u>	DATE <u>10-31-88</u>
ORIGINAL SIGNED BY JERRY SEXTON DISTRICT 1 SUPERVISOR		
APPROVED BY _____	TITLE _____	DATE _____