

STATE OF NEW MEXICO
ENERGY AND MINERALS DEPARTMENT

OIL CONSERVATION DIVISION

P. O. BOX 2088

SANTA FE, NEW MEXICO 87501

Form C-103
Revised 10-1-79

NO. OF COPIES RECEIVED	
DISTRIBUTION	
SANTA FE	
FILE	
U.S.G.S.	
LAND OFFICE	
OPERATOR	

5a. Indicate Type of Lease
State ☐ Fee ☒
5. State Oil & Gas Lease No.

SUNDRY NOTICES AND REPORTS ON WELLS

(DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A DIFFERENT RESERVOIR. USE "APPLICATION FOR PERMIT -" (FORM C-101) FOR SUCH PROPOSALS.)

1. OIL WELL <input checked="" type="checkbox"/> GAS WELL <input type="checkbox"/> OTHER <input type="checkbox"/>	7. Unit Agreement Name N. HOBBS (G/SA) UNIT
2. Name of Operator SHELL OIL COMPANY	8. Farm or Lease Name SECTION 33
3. Address of Operator P. O. BOX 991, HOUSTON, TEXAS 77001	9. Well No. 421
4. Location of Well UNIT LETTER H, 1980 FEET FROM THE NORTH LINE AND 660 FEET FROM THE EAST LINE, SECTION 33 TOWNSHIP 18-S RANGE 38-E NMPM.	10. Field and Pool, or Wildcat HOBBS (G/SA)
15. Elevation (Show whether DF, RT, GR, etc.) 3642' DF	12. County LEA

Check Appropriate Box To Indicate Nature of Notice, Report or Other Data
NOTICE OF INTENTION TO: SUBSEQUENT REPORT OF:

PERFORM REMEDIAL WORK <input type="checkbox"/>	PLUG AND ABANDON <input type="checkbox"/>	REMEDIAL WORK <input type="checkbox"/>	ALTERING CASING <input type="checkbox"/>
TEMPORARILY ABANDON <input type="checkbox"/>	CHANGE PLANS <input type="checkbox"/>	COMMENCE DRILLING OPNS. <input type="checkbox"/>	PLUG AND ABANDONMENT <input type="checkbox"/>
PULL OR ALTER CASING <input type="checkbox"/>	OTHER OPEN ADDITIONAL PAY AND ACIDIZE <input checked="" type="checkbox"/>	CASING TEST AND CEMENT JOBS <input type="checkbox"/>	OTHER <input type="checkbox"/>

17. Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work) SEE RULE 1103.

- Spot 250 gals 15% HCl NEA. Perforate the following intervals from top/down: 4063' - 75', 4094' - 98', 4108' - 12', and 4116' - 23'.
- Acidize perfs 4138' - 46', 4157' - 63' and OH w/3500 gals 15% HCl-NEA.
- Acidize perfs 4063' - 4128' w/1800 gals 15% HCl-NEA.
- Run production equipment and return well to production.

18. I hereby certify that the information above is true and complete to the best of my knowledge and belief.

Signed Jerry Sexton for A. J. FORE TITLE SUPV. REG. & PERMITTING DATE OCTOBER 14, 1982
ORIGINAL SIGNED BY JERRY SEXTON
APPROVED BY DISTRICT 1 SUPR. TITLE DATE OCT 19 1982
CONDITIONS OF APPROVAL, IF ANY: