

UNITED STATES
DEPARTMENT OF THE INTERIOR
BUREAU OF LAND MANAGEMENT

SUBMIT IN TRI
(Other instructions
verse side)

Budget Bureau No. 1004-0113
Expires August 31, 1985

SUNDRY NOTICES AND REPORTS ON WELLS

(Do not use this form for proposals to drill or to deepen or plug back to a different reservoir.
Use "APPLICATION FOR PERMIT—" for such proposals.)

1. OIL WELL <input checked="" type="checkbox"/> GAS WELL <input type="checkbox"/> OTHER <input type="checkbox"/>		7. UNIT AGREEMENT NAME N. HOBBS (G/SA) UNIT	
2. NAME OF OPERATOR SHELL WESTERN E&P INC.		8. FARM OR LEASE NAME SECTION 30	
3. ADDRESS OF OPERATOR P. O. BOX 576, HOUSTON, TEXAS 77001 (WCK 4435)		9. WELL NO. 342	
4. LOCATION OF WELL (Report location clearly and in accordance with any State requirements. See also space 17 below.) At surface UNIT LTR 0, 440' FSL & 2310' FEL		10. FIELD AND POOL, OR WILDCAT HOBBS (G/SA)	
14. PERMIT NO. NA		15. ELEVATIONS (Show whether DF, RT, GR, etc.) 3654' DF	
		12. COUNTY OR PARISH LEA	
		13. STATE NM	

16. Check Appropriate Box To Indicate Nature of Notice, Report, or Other Data

NOTICE OF INTENTION TO:		SUBSEQUENT REPORT OF:	
TEST WATER SHUT-OFF <input type="checkbox"/>	PULL OR ALTER CASING <input type="checkbox"/>	WATER SHUT-OFF <input type="checkbox"/>	REPAIRING WELL <input type="checkbox"/>
FRACTURE TREAT <input type="checkbox"/>	MULTIPLE COMPLETE <input type="checkbox"/>	FRACTURE TREATMENT <input type="checkbox"/>	ALTERING CASING <input type="checkbox"/>
SHOOT OR ACIDIZE <input checked="" type="checkbox"/>	ABANDON* <input type="checkbox"/>	SHOOTING OR ACIDIZING <input type="checkbox"/>	ABANDONMENT* <input type="checkbox"/>
REPAIR WELL <input type="checkbox"/>	CHANGE PLANS <input type="checkbox"/>	(Other) <input type="checkbox"/>	

(NOTE: Report results of multiple completion on Well Completion or Recompletion Report and Log form.)

17. DESCRIBE PROPOSED OR COMPLETED OPERATIONS (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work. If well is directionally drilled, give subsurface locations and measured and true vertical depths for all markers and zones pertinent to this work.)

1. POH w/prod equip.
2. CO to 4217' (PBTD).
3. Perf San Andres 4170' - 4214' (2 JSPE).
4. CO to PBTD.
5. Acidz perfs 4127' - 4214' w/1500 gals 15% HCl-NEA.
6. Install prod equip & ret well to prod.

RECEIVED
 AUG 12 11 15 AM '85
 CASE AREA

18. I hereby certify that the foregoing is true and correct

SIGNED A. J. FORE TITLE SUPERVISOR REG. & PERMITS DATE 8-10-85

(This space for Federal or State office use)

APPROVED BY _____ TITLE _____ DATE 8.16.85

CONDITIONS OF APPROVAL, IF ANY:

*See Instructions on Reverse Side