

NO. OF COPIES RECEIVED		
DISTRIBUTION		
SANTA FE		
FILE		
U.S.G.S.		
LAND OFFICE		
OPERATOR		

NEW MEXICO OIL CONSERVATION COMMISSION

Form C-103  
Supersedes Old  
C-102 and C-103  
Effective 1-1-65

5a. Indicate Type of Lease  
State  Fee   
5. State Oil & Gas Lease No.  
13989

SUNDRY NOTICES AND REPORTS ON WELLS

(DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A DIFFERENT RESERVOIR. USE "APPLICATION FOR PERMIT -" (FORM C-101) FOR SUCH PROPOSALS.)

1. OIL WELL <input checked="" type="checkbox"/> GAS WELL <input type="checkbox"/> OTHER <input type="checkbox"/>	7. Unit Agreement Name
2. Name of Operator Continental Oil Company	8. Farm or Lease Name State A-36 "A"
3. Address of Operator P. O., Box 460, Hobbs, New Mexico	9. Well No. 2
4. Location of Well UNIT LETTER <u>A</u> , <u>660</u> FEET FROM THE <u>North</u> LINE AND <u>660</u> FEET FROM THE <u>East</u> LINE, SECTION <u>36</u> TOWNSHIP <u>18 S</u> RANGE <u>36 E</u> NMPM.	10. Field and Pool, or Wildcat Undesignated
15. Elevation (Show whether DF, RT, GR, etc.) 3757 GL	12. County Lea

16. Check Appropriate Box To Indicate Nature of Notice, Report or Other Data

NOTICE OF INTENTION TO:	SUBSEQUENT REPORT OF:
PERFORM REMEDIAL WORK <input type="checkbox"/>	REMEDIAL WORK <input type="checkbox"/>
TEMPORARILY ABANDON <input type="checkbox"/>	COMMENCE DRILLING OPNS. <input type="checkbox"/>
PULL OR ALTER CASING <input type="checkbox"/>	CASING TEST AND CEMENT JOBS <input type="checkbox"/>
OTHER <input type="checkbox"/>	OTHER <u>Plugback &amp; Recomplete</u> <input checked="" type="checkbox"/>
PLUG AND ABANDON <input type="checkbox"/>	ALTERING CASING <input type="checkbox"/>
CHANGE PLANS <input type="checkbox"/>	PLUG AND ABANDONMENT <input type="checkbox"/>

17. Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work) SEE RULE 1103.

Subject well was plugged back and recompleted using the following procedure:

Before Workover - TD 7691, PB 7310, DF 12' AGL. DF Elev 3757. Csg. Pt 4 1/2" @ 7642. Perfs 7067-76, 7122-30, 7144-54 & 7260-70. Well temporarily abandoned since 6-7-63. Work Done: Ran GR-Collar log from 5500-7000. Set CIBP @ 6850 W/2 sx cmt on top. Perf thru tbg @ 6655, 6657, 6660, 6662, 6718, 6720, 6722, 6728, 6739, 6744, 6751 & 6763 W/1 JSPF. Acidized 6655-6763 W/1500 gals LSTNE using 12 ball sealers. Well Non-Productive. Tsd. To be converted to salt wtr disposal well at a later date. After workover- TD 7691, PB 6828. No change in DF Elev or csg pt. Well non-productive - Tsd. Workover started 4-20-65, Completed 4-24-65.

18. I hereby certify that the information above is true and complete to the best of my knowledge and belief.

SIGNED ROBERT GAULT III TITLE Staff Supervisor DATE 5-27-65

APPROVED BY \_\_\_\_\_ TITLE \_\_\_\_\_ DATE \_\_\_\_\_

CONDITIONS OF APPROVAL, IF ANY:  
ATMOCO 6 TM