

NEW MEXICO OIL CONSERVATION COMMISSION

NO. OF COPIES RECEIVED	
DISTRIBUTION	
SANTA FE	
FILE	
U.S.G.S.	
LAND OFFICE	
OPERATOR	

5a. Indicate Type of Lease
State Fee

5. State Oil & Gas Lease No.
B-1306

7. Unit Agreement Name
-

8. Farm or Lease Name
NM "R" St. NCT-1

9. Well No.
7

10. Field and Pool, or Wildcat
Vacuum Abo Reef

12. County
Lea

SUNDRY NOTICES AND REPORTS ON WELLS
(DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO RE-OPEN OR PLUG BACK TO A DIFFERENT RESERVOIR.
USE "APPLICATION FOR PERMIT - A" (FORM C-101, FOR SUCH PROPOSALS.)

OIL WELL GAS WELL OTHER

2. Name of Operator
TEXACO Inc.

3. Address of Operator
P.O. Box 728 Hobbs, NM 88240

4. Location of Well
UNIT LETTER **G**, **2310** FEET FROM THE **North** LINE AND **1650** FEET FROM
THE **East** LINE, SECTION **6** TOWNSHIP **18-S** RANGE **35-E** N.M.P.M.

15. Elevation (Show whether DF, RT, GR, etc.)
3973' (GR)

16. Check Appropriate Box To Indicate Nature of Notice, Report or Other Data
NOTICE OF INTENTION TO: SUBSEQUENT REPORT OF:

PERFORM REMEDIAL WORK <input type="checkbox"/>	PLUG AND ABANDON <input type="checkbox"/>	REMEDIAL WORK <input type="checkbox"/>	ALTERING CASING <input type="checkbox"/>
TEMPORARILY ABANDON <input type="checkbox"/>	CHANGE PLANS <input type="checkbox"/>	COMMENCE DRILLING OPNS. <input type="checkbox"/>	PLUG AND ABANDONMENT <input type="checkbox"/>
PULL OR ALTER CASING <input type="checkbox"/>	OTHER <input type="checkbox"/>	CASING TEST AND CEMENT JOBS <input type="checkbox"/>	OTHER Open Addl. Perfs in Abo Reef <input checked="" type="checkbox"/>

17. Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work) SEE RULE 1103.

- Rig Up. Pull rods and pump, Install BOP.
- Pull RBP @ 8367'. Perforate 2-7/8" OD Csg w/2-JSPF @ 8360', 63', 71' 74'.
- Spot 2750 gal 2% KCL Water across old & new perforations 8245' - 8510'. Set pkr @ 8225'.
- Acidize perforations 8245' - 8510; w/9000 gal 15% NE Acid in 6-Equal stages using 1000# Benzoic Acid Flakes between each stage. Flush w/115 Bbl 2% KCL water.
- SWAB
- Install pumping equipment, test, and return to production.

18. I hereby certify that the information above is true and complete to the best of my knowledge and belief.

SIGNED *John Runyar* TITLE **Asst. Dist. Supt.** DATE **4-15-77**

APPROVED BY *John Runyar* Geologist TITLE _____ DATE **4-19-77**

CONDITIONS OF APPROVAL, IF ANY: