

Submit 3 Copies
to Appropriate
District Office

State of New Mexico
Energy, Minerals and Natural Resources Department

Form C-183
Revised 1-1-89

DISTRICT I
P.O. Box 1980, Hobbs, NM 88240

OIL CONSERVATION DIVISION
P.O. Box 2088
Santa Fe, New Mexico 87504-2088

DISTRICT II
P.O. Drawer DD, Artesia, NM 88210

DISTRICT III
1000 Rio Brazos Rd., Aztec, NM 87410

WELL API NO. 3002521106
5. Indicate Type of Lease STATE <input checked="" type="checkbox"/> FEE <input type="checkbox"/>
6. State Oil & Gas Lease No. B-3936-1
7. Lease Name or Unit Agreement Name New Mexico "AA" State NCT-4
8. Well No. SWD #1
9. Pool name or Wildcat Vacuum (SWD Well)

SUNDRY NOTICES AND REPORTS ON WELLS
(DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A DIFFERENT RESERVOIR. USE "APPLICATION FOR PERMIT" (FORM C-101) FOR SUCH PROPOSALS.)

1. Type of Well: OIL WELL <input type="checkbox"/> GAS WELL <input type="checkbox"/> OTHER SWD
2. Name of Operator Texaco Producing Inc.
3. Address of Operator P.O. Box 730 Hobbs, New Mexico 88240
4. Well Location Unit Letter <u>B</u> : <u>500</u> Feet From The <u>North</u> Line and <u>1830</u> Feet From The <u>East</u> Line Section <u>10</u> Township <u>18S</u> Range <u>34E</u> NMPM Lea County
10. Elevation (Show whether DF, RKB, RT, GR, etc.) 4030' DF

11. Check Appropriate Box to Indicate Nature of Notice, Report, or Other Data

NOTICE OF INTENTION TO:		SUBSEQUENT REPORT OF:	
PERFORM REMEDIAL WORK <input type="checkbox"/>	PLUG AND ABANDON <input type="checkbox"/>	REMEDIAL WORK <input type="checkbox"/>	ALTERING CASING <input type="checkbox"/>
TEMPORARILY ABANDON <input type="checkbox"/>	CHANGE PLANS <input type="checkbox"/>	COMMENCE DRILLING OPNS. <input type="checkbox"/>	PLUG AND ABANDONMENT <input checked="" type="checkbox"/>
PULL OR ALTER CASING <input type="checkbox"/>		CASING TEST AND CEMENT JOB <input type="checkbox"/>	
OTHER: _____ <input type="checkbox"/>		OTHER: _____ <input type="checkbox"/>	

12. Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work) SEE RULE 1103. 10-3-90 thru 10-5-90

- MIRU PU, install BOP
- TIH w/bit on 2 7/8 w/s to PBTD @4990
- Spot 25 sx plug on CIBP 4990-4775
- Spot 25 sx plug f/ 3155-2940
- Run cmt bond log 2600 to surf - no cmt
- Spot 25 sx plug f/ 1890 - 1675
- Perf @ 400' circ 120 sx cmt to surface
- Cut off wellhead & Set marker.

I hereby certify that the information above is true and complete to the best of my knowledge and belief.

SIGNATURE Richard DeSoto TITLE Engineering Technician DATE 10-16-90

TYPE OR PRINT NAME Richard DeSoto TELEPHONE NO. 393-7191

(This space for State Use)

APPROVED BY [Signature] TITLE OIL & GAS INSPECTOR DATE MAR 05 1991

CONDITIONS OF APPROVAL, IF ANY: