

Submit 3 Copies To Appropriate District Office
 District I
 1625 N. French Dr., Hobbs, NM 88240
 District II
 811 South First, Artesia, NM 88210
 District III
 1000 Rio Brazos Rd., Aztec, NM 87410
 District IV
 1220 S. St. Francis Dr., Santa Fe, NM 87505

State of New Mexico
 Energy, Minerals and Natural Resources

Form C-103
 Revised March 25, 1999

OIL CONSERVATION DIVISION
 1220 South St. Francis Dr.
 Santa Fe, NM 87505

WELL API NO. 30-025-23399
5. Indicate Type of Lease STATE <input checked="" type="checkbox"/> FEE <input type="checkbox"/>
6. State Oil & Gas Lease No. E-7653
7. Lease Name or Unit Agreement Name: Central Vacuum Unit
8. Well No. 123
9. Pool name or Wildcat Vacuum Grayburg, San Andres
10. Elevation (Show whether DR, RKB, RT, GR, etc.)

SUNDRY NOTICES AND REPORTS ON WELLS
 (DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A DIFFERENT RESERVOIR. USE "APPLICATION FOR PERMIT" (FORM C-101) FOR SUCH PROPOSALS.)

1. Type of Well:
 Oil Well Gas Well Other

2. Name of Operator
 Texaco Exploration & Production, Inc.

3. Address of Operator
 P. O. Box 3109, Midland, TX 79702

4. Well Location
 Unit Letter B : 330 feet from the North line and 2310 feet from the East line
 Section 7 Township 18S Range 35E NMPM Lea County

10. Elevation (Show whether DR, RKB, RT, GR, etc.)

11. Check Appropriate Box to Indicate Nature of Notice, Report or Other Data

NOTICE OF INTENTION TO:		SUBSEQUENT REPORT OF:	
PERFORM REMEDIAL WORK <input type="checkbox"/>	PLUG AND ABANDON <input type="checkbox"/>	REMEDIAL WORK <input type="checkbox"/>	ALTERING CASING <input type="checkbox"/>
TEMPORARILY ABANDON <input type="checkbox"/>	CHANGE PLANS <input type="checkbox"/>	COMMENCE DRILLING OPNS. <input type="checkbox"/>	PLUG AND ABANDONMENT <input checked="" type="checkbox"/>
PULL OR ALTER CASING <input type="checkbox"/>	MULTIPLE COMPLETION <input type="checkbox"/>	CASING TEST AND CEMENT JOB <input type="checkbox"/>	
OTHER: <input type="checkbox"/>		OTHER: <input type="checkbox"/>	

12. Describe proposed or completed operations. (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work). SEE RULE 1103. For Multiple Completions: Attach wellbore diagram of proposed completion or recompilation.

1. Tag CIBP @ 4605 (Grayburg-San Andres) spot 25 Sx 4605'-4400' tag @ 4335'
2. Displace hole w/MLF 9.5# Brine w/25# gel P/BBL
3. Spot 40 Sx plug 3800'-3400' (Queen)
4. Spot 25 Sx plug 2800'-2600' (Yates, B-Salt)
5. Spot 40 Sx plug 1600'-1200' (T-Salt)
6. Perf 5 1/2" Csg @ 460' Circ cmt between 5 1/2" Csg 8 5/8" w/ 175 Sx Tag Cmt @ Surf (8 5/8" shoe)
7. Install dry hole marker. 8/10/01

I hereby certify that the information above is true and complete to the best of my knowledge and belief.

SIGNATURE *[Signature]* TITLE MANAGER DATE 8/10/01

Type or print name Jimmy BAGLEY Telephone No. 915 6834996

(This space for State use)

APPROVED BY *[Signature]* TITLE _____ DATE OCT 18 2001

Conditions of approval, if any: