

Submit to Appropriate
District Office
State Lease - 6 copies
Fee Lease - 5 copies

State of New Mexico
Energy, Minerals and Natural Resources Department

Form C-101
Revised 1-1-89

DISTRICT I
P.O. Box 1980, Hobbs, NM 88240

DISTRICT II
P.O. Drawer DD, Artesia, NM 88210

DISTRICT III
1000 Rio Brazos Rd., Aztec, NM 87410

OIL CONSERVATION DIVISION
P.O. Box 2088
Santa Fe, New Mexico 87504-2088

API NO. (assigned by OCD on New Wells) 30-025-23961
5. Indicate Type of Lease STATE ☒ FEE ☐
6. State Oil & Gas Lease No. B-1258-1

APPLICATION FOR PERMIT TO DRILL, DEEPEN, OR PLUG BACK

1a. Type of Work: DRILL ☐ RE-ENTER ☐ DEEPEN ☐ PLUG BACK ☒	7. Lease Name or Unit Agreement Name New Mexico "AE" State
b. Type of Well: OIL WELL ☒ GAS WELL ☐ OTHER ☐ SINGLE ZONE ☒ MULTIPLE ZONE ☐	8. Well No. 24
2. Name of Operator Texaco Exploration and Production Inc.	9. Foot name or Wildcat Vacuum Drinkard
3. Address of Operator P.O. Box 730 Hobbs, New Mexico 88240	

4. Well Location Unit Letter H : 1850 Feet From The North Line and 550 Feet From The East Line Section 11 Township 18-S Range 34-E NMPM Lea County
--

10. Proposed Depth 8215'	11. Formation Drinkard	12. Rotary or C.T. -	
13. Elevations (Show whether DF, RT, GR, etc.) 3994' GR	14. Kind & Status Plug. Bond -	15. Drilling Contractor -	16. Approx. Date Work will start 3-15-93

17. PROPOSED CASING AND CEMENT PROGRAM					
SIZE OF HOLE	SIZE OF CASING	WEIGHT PER FOOT	SETTING DEPTH	SACKS OF CEMENT	EST. TOP
11	8 5/8	24	1810	850	cmt circ
7 7/8	5 1/2	14	8900	860	4550'

1. MIRU. RUN GR TO 8250'. SET CIBP @ 8300' & CAP W/ 35' CLASS C CMT.
2. RUN CORRELATION LOG. PERF W/ 2 JSPF @ 8042'-8161'. (62 INT, 124 HLES)
3. SPT 250 GALS 20% NEFE FR 8042'-8265', SET PKR @ 7665', LOAD BS W/ KCL WTR.
4. A/ PERFS @ 8042'-8161' W/ 6000 GALS 20% NEFE @ 3-4 BPM. SI 1 HR, SWAB BACK LOAD.
5. PERF W/ 2 JSPF @ 7858'-8007'. (72 INT, 144 HLES)
6. TIH W/ PKR & RBP, SET RBP @ 8020, SPT 200 GALS 20% NEFE FR 7858'-8020', SET PKR @ 7520', LOAD BS W/ KCL WTR.
7. A/ PERFS @ 7858'-8007' W/ 8000 GALS 20% NEFE @ 3-4 BPM. SI 1 HR, SWAB BACK LOAD.
TOH W/ PKR & RBP. RETURN WELL TO PRODUCTION.

IN ABOVE SPACE DESCRIBE PROPOSED PROGRAM: IF PROPOSAL IS TO DEEPEN OR PLUG BACK, GIVE DATA ON PRESENT PRODUCTIVE ZONE AND PROPOSED NEW PRODUCTIVE ZONE. GIVE BLOWOUT PREVENTER PROGRAM, IF ANY.

I hereby certify that the information above is true and complete to the best of my knowledge and belief.

SIGNATURE Monte C. Duncan TITLE Engineer's Assistant DATE 3-9-93
TYPE OR PRINT NAME Monte C. Duncan TELEPHONE NO. 393-7191

(This space for State Use)

ORIGINAL SIGNED BY JERRY SEXTON

APPROVED BY DISTRICT I SUPERVISOR TITLE DATE

CONDITIONS OF APPROVAL, IF ANY: