

NO. OF COPIES DESIRED	
DISTRIBUTION	
SANTA FE	
FILE	
U.S.G.E.	
LAND OFFICE	
OPERATOR	

OIL CONSERVATION DIVISION  
P. O. BOX 2088  
SANTA FE, NEW MEXICO 87501

Form O-103  
Revised 10-1-77

API #30-025-26935

5a. Indicate Type of Lease  
State  Fee   
5. State Oil & Gas Lease No.

SUNDRY NOTICES AND REPORTS ON WELLS

DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO REEVALUATE PLUG BACK TO A DIFFERENT RESERVOIR.  
USE "APPLICATION FOR PERMIT TO DRILL OIL WELLS" FOR SUCH PROPOSALS.

6. Name of Operator  
SHELL WESTERN E&P INC.  
Address of Operator  
P. O. BOX 576, HOUSTON, TEXAS 77001 (WCK 4435)  
Location of Well  
UNIT LETTER K 1400 FEET FROM THE SOUTH LINE AND 1370 FEET FROM  
THE WEST LINE, SECTION 30 TOWNSHIP 18-S RANGE 38-E NMPM.  
15. Elevation (Show whether DF, RT, GR, etc.)  
3650.77' GR

7. Unit Agreement Name  
N. HOBBS (G/SA) UNIT  
8. Form or Lease Name  
SECTION 30  
9. Well No.  
232  
10. Field and Pool, or Window  
HOBBS (G/SA)  
12. County  
LEA

Check Appropriate Box To Indicate Nature of Notice, Report or Other Data  
NOTICE OF INTENTION TO: SUBSEQUENT REPORT OF:

PERFORM REMEDIAL WORK <input type="checkbox"/>	PLUG AND ABANDON <input type="checkbox"/>	REMEDIAL WORK <input type="checkbox"/>	ALTERIVE CASING <input type="checkbox"/>
TEMPORARILY ABANDON <input type="checkbox"/>	CHANGE PLANS <input type="checkbox"/>	COMMENCE DRILLING OPER. <input type="checkbox"/>	PLUG AND ABANDONMENT <input type="checkbox"/>
PULL OR ALTER CASING <input type="checkbox"/>	OTHER <input type="checkbox"/>	CASING TEST AND CEMENT JOB <input type="checkbox"/>	OTHER <u>PROFILE MODIFICATION</u> <input checked="" type="checkbox"/>

17. Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work) SEE RULE 1103.

- 11-14-86: Pulled inj equip. CO to 4357'. Logged csg from 4390' to 2390' w/VRT tool. Set CIBP @ 4205'.
- 11-17 to 11-18-86: Set CIBP @ 4110'. Sqzd San Andres perfs 4170' - 4194' w/200 sx CIs "C" cmt & .2% Halad-4 & 2% CaCl2 + 300 sx CIs "C" cmt & 2% CaCl2.
- 11-19-86: Tagged TOC @ 4100'. DO cmt (& CIBP @ 4110') to 4180'. Pres tstd sqzd perfs 4170' - 4178' to 500#, held OK. DO cmt to 4205'. Pres tstd sqzd perfs 4186' - 4194' to 500#, held OK.
- 11-20 to 11-21-86: Drld on CIBP @ 4205' - fell free to 4218'. DO CIBP & cmt to 4290'. Perf'd San Andres 4218' - 4310' (2 JSPF, 64 holes).
- 11-24-86: Acd perfs 4218' - 4310' w/3000 gals 15% HCl + 750# rock salt. Installed inj equip & pres tstd csg to 500# for 15 min. Returned well to inj.

I hereby certify the information above is true and complete to the best of my knowledge and belief.

J. Fore A. J. FORE TITLE SUPERVISOR REG. & PERMITTING DATE JANUARY 8, 1987  
ORIGINAL SIGNED BY JERRY SEXTON DISTRICT I SUPERVISOR  
DATE JAN 2 1987

RECEIVED  
JAN 14 1987  
OCD  
HOBBS OFFICE