

Submit Copy to Appropriate District Office

Energy, MINERALS and WATER

# CONSERVATION DIVISION

P.O. Box 2088

Santa Fe, New Mexico 87504-2088

DISTRICT I  
P.O. Box 1980, Hobbs, NM 88240

DISTRICT II  
P.O. Drawer DD, Artesia, NM 88210

DISTRICT III  
1000 Rio Brazos Rd., Aztec, NM 87410

WELL API NO.
5. Indicate Type of Lease STATE <input type="checkbox"/> FEE <input checked="" type="checkbox"/>
6. State Oil & Gas Lease No.
7. Lease Name or Unit Agreement Name N. HOBBS (G/SA) UNIT SECTION 32
8. Well No. 143
9. Pool name or Wildcat HOBBS (G/SA)

**SUNDRY NOTICES AND REPORTS ON WELLS**  
(DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A DIFFERENT RESERVOIR. USE "APPLICATION FOR PERMIT" (FORM G-101) FOR SUCH PROPOSALS.)

1. Type of Well:  
OIL WELL  GAS WELL  OTHER

2. Name of Operator  
SHELL WESTERN E & P INC. (4431 WCK)

3. Address of Operator  
P.O. BOX 576, Houston, TX 77001-0576

4. Well Location  
Unit Letter M : 1185 Feet From The South Line and 330.20 Feet From The West Line  
Section 32 Township 18-S Range 38-E NMPM LEA County

10. Elevation (Show whether DF, RKB, RT, GR, etc.)  
3630' GL

11. Check Appropriate Box to Indicate Nature of Notice, Report, or Other Data

<b>NOTICE OF INTENTION TO:</b>		<b>SUBSEQUENT REPORT OF:</b>	
PERFORM REMEDIAL WORK <input type="checkbox"/>	PLUG AND ABANDON <input type="checkbox"/>	REMEDIAL WORK <input type="checkbox"/>	ALTERING CASING <input type="checkbox"/>
TEMPORARILY ABANDON <input type="checkbox"/>	CHANGE PLANS <input type="checkbox"/>	COMMENCE DRILLING OPNS. <input type="checkbox"/>	PLUG AND ABANDONMENT <input type="checkbox"/>
PULL OR ALTER CASING <input type="checkbox"/>		CASING TEST AND CEMENT JOB <input type="checkbox"/>	
OTHER: _____ <input type="checkbox"/>		OTHER: <u>AT</u> <input checked="" type="checkbox"/>	

12. Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work) SEE RULE 1103.

8-22-88 thru 8-24-88:

POOH w/ prod equip. CO to 4220'. Selectively AT San Andres 4077' - 4181' w/ 1000 gals 15% NEFE HCl acid, using SPA.

RIH w/ prod equip. Well returned to production 8-24-88.

I hereby certify that the information above is true and complete to the best of my knowledge and belief.

SIGNATURE J. Smitherman for W.F.N. KELLDORF TITLE STAFF PRODUCTION ENGINEER DATE MAR 21 1989

TYPE OR PRINT NAME \_\_\_\_\_ TELEPHONE NO. \_\_\_\_\_

(This space for State Use)

APPROVED BY ORIGINAL SIGNED BY JERRY SEXTON TITLE DISTRICT I SUPERVISOR DATE MAR 30 1989

CONDITIONS OF APPROVAL, IF ANY: