

DISTRICT I

1625 N. French Drive, Hobbs, NM 88240

OIL CONSERVATION DIVISION

310 Old Santa Fe Trail, Room 206
Santa Fe, New Mexico 87503

WELL API NO. 30-025-34869
5. Indicate Type of Lease FED <input type="checkbox"/> STATE <input type="checkbox"/> FEE <input checked="" type="checkbox"/>
6. State Oil & Gas Lease No.

<p align="center">SUNDRY NOTICES AND REPORTS ON WELLS (DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A DIFFERENT RESERVOIR. USE "APPLICATION FOR PERMIT" (FORM C-101 FOR SUCH PROPOSALS.)</p>	
1. Type of Well: Oil Well <input checked="" type="checkbox"/> Gas Well <input type="checkbox"/> Other <input type="checkbox"/>	7. Lease Name or Unit Agreement Name NORTH HOBBS (G/SA) UNIT
2. Name of Operator OCCIDENTAL PERMIAN LIMITED PARTNERSHIP	SECTION 29
3. Address of Operator 1017 W STANOLIND RD.	8. Well No. 623
4. Well Location Unit Letter <u>K</u> : <u>1837</u> Feet From The <u>SOUTH</u> Line and <u>2482</u> Feet From The <u>WEST</u> Line Section <u>29</u> Township <u>18-S</u> Range <u>38-E</u> NMPM LEA County	9. Pool name or Wildcat HOBBS (G/SA)
10. Elevation (Show whether DF, RKB, RT GR, etc.) 3645' GL	

11. Check Appropriate Box to Indicate Nature of Notice, Report, or Other Data

NOTICE OF INTENTION TO:		SUBSEQUENT REPORT OF:	
PERFORM REMEDIAL WORK <input type="checkbox"/>	PLUG AND ABANDON <input type="checkbox"/>	REMEDIAL WORK <input type="checkbox"/>	ALTERING CASING <input type="checkbox"/>
TEMPORARILY ABANDON <input type="checkbox"/>	CHANGE PLANS <input type="checkbox"/>	COMMENCE DRILLING OPNS. <input type="checkbox"/>	PLUG & ABANDONMENT <input type="checkbox"/>
PULL OR ALTER CASING <input type="checkbox"/>		CASING TEST AND CEMENT JOB <input type="checkbox"/>	
OTHER: _____ <input type="checkbox"/>		OTHER: <u>NEW WELL COMPLETION</u> <input checked="" type="checkbox"/>	

12. Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work) SEE RULE 1103.

Rig up Pulling Unit 05/15/00.
Sqr San Andres perms 4100 - 4129.
PBTD = 4329'.
Reperforate San Andres Zone from 4156- 4258'. (2 JSPF)
Acidize w/3000 gal 20% HCL acid.
RIH w/production equipment. REDA ESP.
Rig Down and Clean Location.

Rig Up Date: 05/15/00
Rig Down Date: 05/23/00

I hereby certify that the information above is true and complete to the best of my knowledge and belief.

SIGNATURE Robert N. Gilbert TITLE LIFT SPECIALIST DATE 05/30/00
TYPE OR PRINT NAME R.N. GILBERT TELEPHONE NO. 505/397-8206

(This space for State Use)

APPROVED BY _____ TITLE _____ DATE _____