STATE OF NEW MEXICO ENERGY AND MINERALS DEPARTMENT

Ν

OIL CONSERVATION DIVISIO
P. O. BOX 2088
SANTA FE, NEW MEXICO 87501

		OX 2088			
DISTRIBUTION	SANTA FE, NEW	MEXICO 87501	Form C-103		
SANTA FE			Revised 10-1-78		
FILE					
U.S.G.S.			5a. Indicate Type of Lease		
LAND OFFICE			State X Fee		
API No. 30-025-02898			5. State Oil & Gas Lease No. B-1840		
SUNDR	Y NOTICES AND REPORTS ON V	VELLS			
	ROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK ATION FOR PERMIT - * (FORM C-101) FOR SUCH PRI				
11.			7. Unit Agreement Name		
OIL GAS WELL 🔀 WELL [OTHER		East Vacuum GB/SA Unit		
12. Name of Operator			8. Farm or Lease Name		
Phillips Petroleum Company			East Vacuum GB/SA Unit		
13 Address of Operator			9. Well No. Tr. 2739		
4001 Penbrook Street, Odessa, Texas 79762			004		
14. Location of Well			10. Field and Pool, or Wildcat		
	21	10001	Vacuum GR/SA		
UNIT LETTER L DOL	O' FEET FROM THE West	LINE AND 1980' FEET FROM			
THE SOUTH LINE, SECTION	27 TOWNSHIP 17-S	RANGE 35-E NMPM			
	15. Elevation (Show whether DF, I	RT, GR, etc.)	12. County		
	3948' RKB, 3938' GF	₹	Lea		
16. Check Appr	ropriate Box To Indicate Nature	e of Notice, Report or Ot	her Data		
NOTICE OF INTENTIO	•	•	ENT REPORT OF:		
_	51110.		_		
PERFORM REMEDIAL WORK	PLUG AND ABANDON	REMEDIAL WORK	ALTERING CASING		
TEMPORARILY ABANDON	_	COMMENCE DRILLING OPNS.	PLUG AND ABANDONMENT		
PULL OR ALTER CASING	CHANGE PLANS	CASING TEST AND CEMENT JOB]		
OTHER		OTHER			
	17 Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any propos work) SEE RULE 1103				
17 Describe Proposed or Completed Oper work) SEE RULE 1103	rations (Clearly state all pertinent deta	ils, and give pertinent dates, in	ncluding estimated date of starting any propos		
work) SEE RULE 1103 5-07-87: RU DDU, NU BOP, WIH w/2-3/8" tail	, COOH w/tbg. and submersible pipe & pkr. Spotted 1000 gals.	e equip. WIH w/bit end s Xylene, waited 2 hours,	craper. COOH w/bit and scraper. swbd back. Pmpd 2500 gals. 15% ast test: Fluid 10 BO, 46 BW, 35		
work) SEE RULE 1103 5-07-87: RU DDU, NU BOP WIH w/2-3/8" tail NEFe HCl w/2 dru MCFG.	, COOH w/tbg. and submersible pipe & pkr. Spotted 1000 gals.	e equip. WIH w/bit end s Xylene, waited 2 hours,	craper. COOH w/bit and scraper. swbd back. Pmpd 2500 gals. 15%		
work) SEE RULE 1103 5-07-87: RU DDU, NU BOP, WIH w/2-3/8" tail NEFe HCl w/2 dru MCFG. 5-08-87: Flowed 24 hrs., 92	, COOH w/tbg. and submersible pipe & pkr. Spotted 1000 gals. ms Tech-Wet 425. Unflange BC	e equip. WIH w/bit end s Xylene, waited 2 hours,	craper. COOH w/bit and scraper. swbd back. Pmpd 2500 gals. 15%		
work) SEE RULE 1103 5-07-87: RU DDU, NU BOP WIH w/2-3/8" tail NEFe HCl w/2 dru MCFG.	, COOH w/tbg. and submersible pipe & pkr. Spotted 1000 gals. ms Tech-Wet 425. Unflange BC 2 BO, 230 BW, 262 MCFG.	e equip. WIH w/bit end s Xylene, waited 2 hours,	craper. COOH w/bit and scraper. swbd back. Pmpd 2500 gals. 15%		
work) SEE RULE 1103 5-07-87: RU DDU, NU BOP WIH w/2-3/8" tail NEFe HCl w/2 dru MCFG. 5-08-87: Flowed 24 hrs., 92 5-10 thru 7-25-87: Flowed until stab	, COOH w/tbg. and submersible pipe & pkr. Spotted 1000 gals. ms Tech-Wet 425. Unflange BC 2 BO, 230 BW, 262 MCFG.	e equip. WIH w/bit end s Xylene, waited 2 hours, DP, hook up wellhead. L	craper. COOH w/bit and scraper. swbd back. Pmpd 2500 gals. 15% ast test: Fluid 10 BO, 46 BW, 35		
work) SEE RULE 1103 5-07-87: RU DDU, NU BOP WIH w/2-3/8" tail NEFe HCl w/2 dru MCFG. 5-08-87: Flowed 24 hrs., 92 5-10 thru 7-25-87: Flowed until stab	, COOH w/tbg. and submersible pipe & pkr. Spotted 1000 gals. Ims Tech-Wet 425. Unflange BC 2 BO, 230 BW, 262 MCFG.	e equip. WIH w/bit end s Xylene, waited 2 hours, DP, hook up wellhead. L	craper. COOH w/bit and scraper. swbd back. Pmpd 2500 gals. 15% ast test: Fluid 10 BO, 46 BW, 35		
5-07-87: RU DDU, NU BOP, WIH w/2-3/8" tail NEFe HCl w/2 dru MCFG. 5-08-87: Flowed 24 hrs., 92 5-10 thru 7-25-87: Flowed until stab 7-26-87: Flowed 24 hrs., 32	, COOH w/tbg. and submersible pipe & pkr. Spotted 1000 gals. Ims Tech-Wet 425. Unflange BC 2 BO, 230 BW, 262 MCFG. Dilized. 2 BO, 128 BW, 209 MCFG, GOR: and complete to the best of my knowledge and the second pipe.	e equip. WIH w/bit end s Xylene, waited 2 hours, OP, hook up wellhead. L : 6529, 200# TP. Job Con	craper. COOH w/bit and scraper. swbd back. Pmpd 2500 gals. 15% ast test: Fluid 10 BO, 46 BW, 35		
5-07-87: RU DDU, NU BOP, WIH w/2-3/8" tail NEFe HCl w/2 dru MCFG. 5-08-87: Flowed 24 hrs., 92 5-10 thru 7-25-87: Flowed until stab 7-26-87: Flowed 24 hrs., 32	, COOH w/tbg. and submersible pipe & pkr. Spotted 1000 gals. Ims Tech-Wet 425. Unflange BC 2 BO, 230 BW, 262 MCFG. Dilized. 2 BO, 128 BW, 209 MCFG, GOR: and complete to the best of my knowledge and the second pipe.	e equip. WIH w/bit end s Xylene, waited 2 hours, DP, hook up wellhead. L	craper. COOH w/bit and scraper. swbd back. Pmpd 2500 gals. 15% ast test: Fluid 10 BO, 46 BW, 35		
5-07-87: RU DDU, NU BOP WIH w/2-3/8" tail NEFe HCl w/2 dru MCFG. 5-08-87: Flowed 24 hrs., 92 5-10 thru 7-25-87: Flowed until stab 7-26-87: Flowed 24 hrs., 32	, COOH w/tbg. and submersible pipe & pkr. Spotted 1000 gals. Ims Tech-Wet 425. Unflange BC 2 BO, 230 BW, 262 MCFG. Silized. 2 BO, 128 BW, 209 MCFG, GOR: a and complete to the best of my knowledge and the complete to the	e equip. WIH w/bit end s Xylene, waited 2 hours, OP, hook up wellhead. L : 6529, 200# TP. Job Con	craper. COOH w/bit and scraper. swbd back. Pmpd 2500 gals. 15% ast test: Fluid 10 BO, 46 BW, 35		