

DISTRICT I
P.O. Box 1980, Hobbs, NM 88240

DISTRICT II
P.O. Drawer DD, Artesia, NM 88210

DISTRICT III
1000 Rio Brazos Rd., Aztec, NM 87410

OIL CONSERVATION DIVISION

P.O. Box 2088
Santa Fe, New Mexico 87504-2088

WELL API NO. 30-025-20862
5. Indicate Type of Lease STATE ☒ FEE ☐
6. State Oil & Gas Lease No.

SUNDRY NOTICES AND REPORTS ON WELLS
(DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A DIFFERENT RESERVOIR. USE 'APPLICATION FOR PERMIT' (FORM C-101) FOR SUCH PROPOSALS.)

1. Type of Well:
OIL WELL ☒ GAS WELL ☐ OTHER ☐

2. Name of Operator
Mobil Producing TX & NM Inc.* *Mobil Exploration & Producing
US Inc as agent for MPTM

3. Address of Operator
P.O. Box 633, Midland, TX 79702

4. Well Location

Unit Letter D : 510 Feet From The North Line and 535 Feet From The West Line

Section 31 Township 17-S Range 35-E NMPM Lea County

10. Elevation (Show whether DF, RKB, RT, GR, etc.)
KB 3999

7. Lease Name or Unit Agreement Name

State DD

Well No.

1

9. Pool name or Wildcat
Vacuum (Drinkard)

11. Check Appropriate Box to Indicate Nature of Notice, Report, or Other Data

NOTICE OF INTENTION TO:

PERFORM REMEDIAL WORK ☒ PLUG AND ABANDON ☐
TEMPORARILY ABANDON ☐ CHANGE PLANS ☐
PULL OR ALTER CASING ☐
OTHER: ☐

SUBSEQUENT REPORT OF:

REMEDIAL WORK ☒ ALTERING CASING ☐
COMMENCE DRILLING OPNS. ☐ PLUG AND ABANDONMENT ☐
CASING TEST AND CEMENT JOB ☐
OTHER: ☐

12. Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work) SEE RULE 1103.

12-07-93 MIRU Permian P/U #35. WIH w/CIBP @ 9210, SISDFN
12-08-93 MIRU Schlumberger, dump 10' cmt on CIBP. Perf w/2JSPF @ 7501-20, 7540-68, 7582-7600
7632-46, 7706-18, 7728-42 (222 holes). RD Schlumberger. SISDFN
12-09-93 PU Packer, Test 2-7/8 tbg, set packer @ 7843; test CIBP to 5000 PSI, held OK. Shot
perfs w/500 gal 15% HCl. Acdz w/25 RCB in6 BBL 3000 Gal 20% HCl + 250 Ball Sealers,
no action. RU Flowline to tank, flow back acid water, no build of press, SISDFN.
12-10,11-93 RU swab equipment, swag, wait 1 hour between runs. SISDFN & weekend
12-13-93 MIRU Schlumberger, acid & gel up; acdz; RU Gray wireline, log GR, temp logs, RD.
Run to flow back, flow well til stops.
12-14-93 Rel packer, reset @ 7412; swab. RU hot oiler; pump 70 BBL breaker @ 2300 PSI, RD.
SISDFN
12-15,16-93 Open well, swab, wait 1 hour between runs. SISDFN
12-17-93 RD swab equipment. Rel packer. ND BOP, NU WH. RU & RIH w/rods, pump
12-18-93 Loak tbg, check pump, OK 12-19-93 Will SI, pending engineering evaluation

I hereby certify that the information above is true and complete to the best of my knowledge and belief.

SIGNATURE Kaye Pollock TITLE Env. & Reg. Tech. DATE 01-05-94
TYPE OR PRINT NAME Kaye Pollock 915-
TELEPHONE NO. 688-2584

(This space for State Use)

ORIGINAL SIGNED BY JERRY SEXTON
DISTRICT I SUPERVISOR

APPROVED BY _____ TITLE _____ DATE JAN 07 1994

CONDITIONS OF APPROVAL, IF ANY: