STATE OF NEW MEXICO ENERGY AND MINERALS DEPARTMENT

TIOT AND WINVENACO DE	
we. or carice acceives	
DISTRIBUTION	
SANTA FE	
FILE	
U.1.0.1.	
LAND OFFICE	1
0000000	1

2. Name of Operator

Me. of COPICS RECEIVED	OIL CONSERVATIO
DISTRIBUTION	P. O. BOX 208
SANTA FE	SANTA FE, NEW ME
FILE	
U.S.O.S.	
LAND OFFICE	

ENERGY AND MINERAL	S DEPARTMENT	
BO. OF COMICO MCCO		
DISTRIBUTIO		Form C-103 Revised 10-1-78
SANTA FE	SANTA FE, NEW MEXICO 87501	Metrized to the
FILE		5a. Indicate Type of Lease
V.8.0.8.		State X Fee
LAND OFFICE		5. State Oil & Gus Lease No.
OPERATOR	API NO. 30-025-21080	B-2498
	API NO. 30-023-21000	VIIIIIIIIII
	SUNDRY NOTICES AND REPORTS ON WELLS	
(00 HOT UBE TH	S FORM FUR PROPOSALS TO DRILL OR TO DELPEN OR PLUG BECK PROPOSALS.)	7, Unit Agreement Name
	(**)	
OIL X	WELL OTHER-	8. Farm or Lease Name
. Name of Operator		_
Phillips Pe	roleum Company	Santa Fe
. Address of Operator		
Room 401, 4	001 Penbrook St., Odessa, TX 79762	105
Location of Well		10. Field and Pool, or Wildcat
	E 2322 FEET FROM THE NORTH LINE AND 660 FEET FROM	Vacuum Glorieta
UNIT LETTER	PEET FROM THE	
Uoat	LINE, SECTION 28 TOWNSHIP 17-S RANGE 35-E HMPPM	
THE	LINE, SECTION TOWNSHIP RANGE	
	15. Elevation (Show whether DF, RT, GR, etc.)	12. County
	3957' RKB, 3944' GL	Lea
16.	Check Appropriate Box To Indicate Nature of Notice, Report or Ot	ner Data
N	OTICE OF INTENTION TO: SUBSEQUEN	T REPORT OF:
		لنا
PERFORM REMEDIAL WO	PLUG AND ABANDON REMEDIAL WORK	ALTERING CASING
TEMPORARILY ABANDON	COMMENCE DRILLING OPHS.	PLUG AND ABANDONMENT
PULL OR ALTER CASING	CHANGE PLANS CASING TEST AND CEMENT JQB	
FOLC ON ACTION CONTRACTOR	OTHER	
ATUE T		
THE	1.2	and does of starting any proposed
17. Describe Proposed	or Completed Operations (Clearly state all pertinent details, and give pertinent dates, including	g estimated date of starting any proposed
work) SEE RULE	1603.	
Acid fractu	ed well as follows:	
	n 1 m 1 m	ant mirm at 61001
8-24-80	MI Tyler WS unit. Pulled rods and tbg. Ran tbg and pkr,	set pki at 0100.
	Last test 7-30-80, 24 hrs, 7 BO, no wtr, GOR 862.	
		1 /5050 1
8-25-80	Acid fracd perfs 6140-6159' w/5000 gals gelled brine foll	owed w/3250 gals
	15% NE HCl gelled acid, flshd w/2000 gals slick wtr.	
	,	
8-26-80	Ran and set $2-3/8$ " tbg at 6080'.	
0-20-00	Rail and See a System 1-8	•
	· · · · · · · · · · · · · · · · · · ·	on tacte for
0 27 90	$S_{O}+2"\times 1-1/4"\times 16'$ pmp at 6079'. MO Tyler WS unit. I	all Leata Ioi
8-27-80	Set 2" x $1-1/4$ " x 16' pmp at 6079'. MO Tyler WS unit. For a symbol of the symbol of	tall tests 101
8-27-80	Set 2" \times 1-1/4" \times 16' pmp at 6079'. MO Tyler WS unit. Evaluation.	dan tests for
	evaluation.	
8-27-80 9-20-80		
	evaluation.	

18. I hereby copts	fy that the information above is true and compl-	ete to the best of my knowledge and belief.		
/ · · · /	Just W. J. Mueller		DATE	9-23-80
SICHED				. 367
APPROVED BY	Rucyan	TITLE	DATE	19 9
	and the same of th			