

OIL CONSERVATION DIVISION
P. O. BOX 2088
SANTA FE, NEW MEXICO 87501

Form C-103
Revised 10-1-78

NO. OF COPIES RECEIVED	
DISTRIBUTION	
SANTA FE	
FILE	
U.S.G.S.	
LAND OFFICE	
OPERATOR	

1a. Indicate Type of Lease	
State <input checked="" type="checkbox"/>	Fee <input type="checkbox"/>
5. State Oil & Gas Lease No.	
LG-2417	

SUNDRY NOTICES AND REPORTS ON WELLS

(DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A DIFFERENT RESERVOIR. USE "APPLICATION FOR PERMIT - P" (FORM C-101) FOR SUCH PROPOSALS.)

1. <input checked="" type="checkbox"/> OIL WELL <input type="checkbox"/> GAS WELL <input type="checkbox"/> OTHER-		7. Unit Agreement Name
2. Name of Operator		8. Farm or Lease Name
FRED G. YATES, INC.		Reddy-Gulf State
3. Address of Operator		9. Well No.
Sunwest Centre, Suite 919, Roswell, N.M. 88201		1
4. Location of Well		10. Field and Pool, or Wildcat
UNIT LETTER <u>D</u> <u>660'</u> FEET FROM THE <u>North</u> LINE AND <u>660'</u> FEET FROM		
THE <u>West</u> LINE, SECTION <u>18</u> TOWNSHIP <u>19S</u> RANGE <u>35E</u> NMPM.		
15. Elevation (Show whether DF, RT, GR, etc.)		12. County
3936.25' G.L.		Lea

16. Check Appropriate Box To Indicate Nature of Notice, Report or Other Data
NOTICE OF INTENTION TO: SUBSEQUENT REPORT OF:

PERFORM REMEDIAL WORK <input type="checkbox"/>	PLUG AND ABANDON <input type="checkbox"/>	REMEDIAL WORK <input type="checkbox"/>	ALTERING CASING <input type="checkbox"/>
TEMPORARILY ABANDON <input type="checkbox"/>	CHANGE PLANS <input type="checkbox"/>	COMMENCE DRILLING OPNS. <input checked="" type="checkbox"/>	PLUG AND ABANDONMENT <input type="checkbox"/>
PULL OR ALTER CASING <input type="checkbox"/>	OTHER <input type="checkbox"/>	CASING TEST AND CEMENT JOB <input type="checkbox"/>	

17. Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work) SEE RULE 1103.

11-28-84: Moved in Dozer and scraped off road and location, dug cellar out with backhoe and cut off 13-3/8" and removed 4" regulation dry hole marker. Welder tied new 13-3/8" to cut 13-3/8" in cellar. Nipple up to drill. Moved in pulling unit and circulating and rotating equipment.

11-29-84: Rigged up pulling unit and hooked up circulating equipment. Picked up 7-7/8" bit and drill collars and 3-1/2" drill pipe and drilled cement and cleaned out hole to 314'.

11-30-84: Drilled out to 815'.

12-01-84: Drilled out to 846'.

18. I hereby certify that the information above is true and complete to the best of my knowledge and belief.

SIGNED Leah W. King TITLE Engineer DATE 12-3-84

APPROVED BY Edith W. King TITLE OIL & GAS INSPECTOR DATE DEC 4 1984

CONDITIONS OF APPROVAL, IF ANY: