·	
NO. OF COPIES RECEIVED	Form C-103 Supersedes Old
DISTRIBUTION	C-102 and C-103
SANTA FE NEW MEXICO OIL CONSERVATION COMMISSION	Effective 1-1-65
FILE	5a. Indicate Type of Lease
U.S.G.S.	State X Fee
LAND OFFICE	5. State Oil & Gas Lease No.
OPERATOR	NM E-8563 .
SUNDRY NOTICES AND REPORTS ON WELLS (DO NOT USE THIS FORM FOR PROPOSALS TO SHILL OR TO SEPPEN OR PLUG BACK TO A DIFFERENT RESERVOIR. USE "APPLICATION FOR PERMIT -" (FORM C-101) FOR SUCH PROPOSALS.)	7. Unit Agreement Name
OIL X GAS OTHER-	8. Farm or Lease Name
2. Name of Operator	Midway State
Consolidated Oil & Gas, Inc.	9. Well No.
1860 Lincoln St., Suite 1300, Denver, Co. 80295	3
4. Location of Well 330 south 2310	10. Fleid and Pool, or Wildcat Midway Abo
West 8 17S 37E THELINE, SECTION TOWNSHIP	
15. Elevation (Show whether DF, RT, GR, etc.) 3785 GL	12. County Lea
The man of Marine Perset of Other	her Data
NOTICE OF INTENTION TO.	, KELOKI OF:
PERFORM REMEDIAL WORK PLUG AND ABANDON REMEDIAL WORK TEMPORARILY ABANDON CASING TEST AND CEMENT JOB	T REPORT OF: ALTERING CASING PLUG AND ABANDONMENT [
PERFORM REMEDIAL WORK PLUG AND ABANDON COMMENCE DRILLING OPNS. PULL OR ALTER CASING CHANGE PLANS OTHER OTHER	ALTERING CASING [PLUG AND ABANDONMENT [
PERFORM REMEDIAL WORK PLUG AND ABANDON COMMENCE DRILLING OPNS. PULL OR ALTER CASING CHANGE PLANS OTHER OTHER	ALTERING CASING [PLUG AND ABANDONMENT [
PERFORM REMEDIAL WORK PLUG AND ABANDON TEMPORARILY ABANDON PULL OR ALTER CASING OTHER 17. Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, including work) SEE RULE 1703. The Well was plugged and abandoned effective 1-9-82. Plugthe well as follows:	ALTERING CASING PLUG AND ABANDONMENT [g estimated date of starting any propos s were placed i);
PERFORM REMEDIAL WORK PLUG AND ASANDON PULL OR ALTER CASING OTHER 17. Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, including work) SEE RULE 1703. The Well was plugged and abandoned effective 1-9-82. Plugthe Well as follows: 1. A CIBP was set in the 5-1/2" liner @ 8554'. 35' cmt was plugged and abandoned with mud.	ALTERING CASING [PLUC AND ABANDONMENT [gestimated date of starting any propos s were placed i); s dumped on top of
PERFORM REMEDIAL WORK PLUG AND ABANDON COMMENCE DRILLING OPNS. TEMPORARILY ABANDON CHANGE PLANS CASING TEST AND CEMENT JOB OTHER 17. Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, including work) SEE RULE 1703. The Well was plugged and abandoned effective 1-9-82. Plug the well as follows: 1. A CIBP was set in the 5-1/2" liner @ 8554'. 35' cmt was the plug and the hole was displaced with mud. 2. A 35 sx plug was placed in the 5-1/2" liner from 5710' 3. A 100' plug was placed across the liner top at 4281' f. 4. A 100' plug was placed in the 8-5/8" csg from 1700' to 5. A 100' plug was placed in the 8-5/8" csg from 325' to 6. The 8-5/8" csg was pulled from 210'. 7. A 10 sx plug was placed at the surface and a dry hole	ALTERING CASING PLUG AND ABANDONMENT [gestimated date of starting any proposes were placed in starting and starting any proposes were placed in starting and starting
PERFORM REMEDIAL WORK TEMPORARILY ABANDON PULL OR ALTER CASING OTHER 17. Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, including work) SEE RULE 1703. The well was plugged and abandoned effective 1-9-82. Plug the well as follows: 1. A CIBP was set in the 5-1/2" liner @ 8554'. 35' cmt wa the plug and the hole was displaced with mud. 2. A 35 sx plug was placed in the 5-1/2" liner from 5710' 3. A 100' plug was placed across the liner top at 4281' f 4. A 100' plug was placed in the 8-5/8" csg from 1700' to 5. A 100' plug was placed in the 8-5/8" csg from 325' to	ALTERING CASING PLUG AND ABANDONMENT [gestimated date of starting any proposes were placed in starting and starting any proposes were placed in starting and starting
PERFORM REMEDIAL WORK PLUG AND ABANDON COMMENCE DRILLING OPNS. TEMPORARILY ABANDON CHANGE PLANS CASING TEST AND CEMENT JOB OTHER 17. Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, including work) SEE RULE 1703. The Well was plugged and abandoned effective 1-9-82. Plug the well as follows: 1. A CIBP was set in the 5-1/2" liner @ 8554'. 35' cmt was the plug and the hole was displaced with mud. 2. A 35 sx plug was placed in the 5-1/2" liner from 5710' 3. A 100' plug was placed across the liner top at 4281' f. 4. A 100' plug was placed in the 8-5/8" csg from 1700' to 5. A 100' plug was placed in the 8-5/8" csg from 325' to 6. The 8-5/8" csg was pulled from 210'. 7. A 10 sx plug was placed at the surface and a dry hole	ALTERING CASING PLUG AND ABANDONMENT [gestimated date of starting any proposes were placed in starting and starting any proposes were placed in starting and starting

18. I hereby certify that the information above is true and complete to the best of my knowledge and belief.

SIGNED TITLE SO DIV Prod Mgr. DATE 2-18-82

SEP 9.0 1983