

UNITED STATES  
DEPARTMENT OF THE INTERIOR  
GEOLOGICAL SURVEY

SUBMIT IN TRIPLI  
(Other instructions  
verse side)

Form approved.  
Budget Bureau No. 42-R1424.

SUNDRY NOTICES AND REPORTS ON WELLS

(Do not use this form for proposals to drill or to deepen or plug back to a different reservoir.  
Use "APPLICATION FOR PERMIT—" for such proposals.)

1. OIL WELL  GAS WELL  OTHER  Dry

2. NAME OF OPERATOR  
Me-Tex Supply Company

3. ADDRESS OF OPERATOR  
P.O. Box 2070, Hobbs, New Mexico 88240

4. LOCATION OF WELL (Report location clearly and in accordance with any State requirements.\*  
See also space 17 below.)  
At surface  
2310 FSL & 1650 FWL of Section

14. PERMIT NO.

15. ELEVATIONS (Show whether DF, RT, OR, etc.)  
3704 GR 3714 KB

5. LEASE DESIGNATION AND SERIAL NO.  
NM-0141013

6. IF INDIAN, ALLOTTEE OR TRIBE NAME

7. UNIT AGREEMENT NAME  
Mescalero Ridge

8. FARM OR LEASE NAME  
Mescalero

9. WELL NO.  
2

10. FIELD AND POOL, OR WILDCAT  
Wildcat

11. SEC. T. R. S. OR BLM. AND SURVEY OR ARRA  
Sec 20, T-19-S, R-34-E

12. COUNTY OR PARISH 13. STATE  
Lea New Mex.

10. Check Appropriate Box To Indicate Nature of Notice, Report, or Other Data

NOTICE OF INTENTION TO:		SUBSEQUENT REPORT OF:	
TEST WATER SHUT-OFF <input type="checkbox"/>	PULL OR ALTER CASING <input type="checkbox"/>	WATER SHUT-OFF <input type="checkbox"/>	REPAIRING WELL <input type="checkbox"/>
FRACTURE TREAT <input type="checkbox"/>	MULTIPLE COMPLETE <input type="checkbox"/>	FRACTURE TREATMENT <input type="checkbox"/>	ALTERING CASING <input type="checkbox"/>
SHOOT OR ACIDIZE <input type="checkbox"/>	ABANDON* <input checked="" type="checkbox"/>	SHOOTING OR ACIDIZING <input type="checkbox"/>	ABANDONMENT* <input type="checkbox"/>
REPAIR WELL <input type="checkbox"/>	CHANGE PLANS <input type="checkbox"/>	(Other) <input type="checkbox"/>	(Other) <input type="checkbox"/>

(NOTE: Report results of multiple completion on Well Completion or Recompletion Report and Log form.)

17. DESCRIBE PROPOSED OR COMPLETED OPERATIONS (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work. If well is directionally drilled, give subsurface locations and measured and true vertical depths for all markers and zones pertinent to this work.)\*

Plan to P & A as follows:  
Cmt plugs:  
3992 - 3750 w/15 sx (in 4 1/2" pipe across perf. 3931-3941)  
Cut off 4 1/2" casing at 3100'  
3180-3070 w/25 sx (across top 4 1/2" casing at 3100')  
1770-1700 w/25 sx (in anhy at top of salt)  
305-210 w/25 sx (across bottom 8 5/8" at 263')  
20 - 0 w/5 sx (top 8 5/8" at surf)

Install marker w/required identification.

18. I hereby certify that the foregoing is true and correct

SIGNED D. L. Larey TITLE Geologist DATE 4-21-70

(This space for Federal or State office use)

APPROVED BY \_\_\_\_\_ TITLE \_\_\_\_\_

CONDITIONS OF APPROVAL, IF ANY:

**APPROVED**  
APR 22 1970  
R. BROWNE  
DISTRICT ENGINEER

\*See Instructions on Reverse Side

RECEIVED

APR 26 1970

COMMUNICATIONS DIVISION