

4. LEASE DESIGNATION AND SERIAL NO.

LC 070375

6. IF INDIAN, ALLOTTEE OR TRIBE NAME _____

SUNDRY NOTICES AND REPORTS ON WELLS

Use "APPLICATION FOR PERMIT" for such purposes.

1. OIL ☐ GAS ☐ WELL ☐ WELL ☐ OTHER ☐	7. UNIT AGREEMENT NAME Federal
2. NAME OF OPERATOR John H. Trigg	8. FARM OR LEASE NAME D-2
3. ADDRESS OF OPERATOR P. O. Box 520, Roswell, New Mexico 86401	9. WELL NO. 1
4. LOCATION OF WELL (Report location clearly and in accordance with any State requirements. See also Space 17 below.) At surface 2510' FOL & 1050' FWL, Sec. 20, T13N, R36E	10. FIELD AND POOL, OR WILDCAT Pearl East
10. PERMIT NO.	11. SEC., T., R., M., OR BLM., AND SURVEY OR AREA Sec. 20, T13N, R36E

Check Appropriate Box To Indicate Nature of Notice, Report, or Other Data

NOTICE OF INTENTION TO:

SUBSEQUENT REPORT OF:

TEST WATER SHUT-OFF	FULL OR ALTER CASING	WATER SHUT-OFF	REPAIRING WELL
FRACURE TREAT	MULTIPLE COMPLETE	FRACURE TREATMENT	ALTERING CASING
SHOOT OR ACIDIZE	ABANDON*	SHOOTING OR ACIDIZING	ABANDONMENT*
REPAIR WELL	CHANGE PLANS	COLLAPSE	

(Notes) Report results of multiple completion on Well

• **Notes:** Report results of multiple completion on Well Completion or Recompletion Report and log form.

17. DESCRIBE (sketch or completed drawings clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work. If well is directionally drilled, give subsurface locations and measured and true vertical depths for all markers and zones pertinent to this work.)

page 167. for Attention: not required.

Get Cast Iron Bridge Plug 12" dia., 1-1 1/4" Ft., 3-55, Casing 3 1/2" 280'.
 Pump 35' Cement Plug on bridge plug w/ 1" sp. collar. Fill hole w/Mud.
 Mixed @ 2" ex Gel per 100 barrels Water. Run Casing Jet Cutter to
 2200' and cut casing. Pull off 1" of casing off of the hole. Get 35 ex
 Cement Plug @ 1/2" dia Casing 3400'. Get 1" ex Cement Plug from 3400' to
 3500'. Pull up to 2000' and get 1" ex Cement Plug from 2000' to 2200'.
 Get Cast Iron Bridge Plug 12" dia., 1-1 1/4" Ft., 3-55, Casing 3 1/2" 280'.
 Pump 35' Cement Plug on bridge plug. Pull off 1" of casing and get 15 ex Cement Plug
 1 1/2" dia. Get off 3-3 3/8" dia. Casing. Pull on place and install vibrator
 pipe w/ 1" collar on top. If required. Level, clean and restore well
 time as required.

ILLEGIBLE

**NOTIFY USG IN TIME TO
WITNESS PLUMBING OPERATIONS**

APPROVED SUBJECT TO POSSIBLE FUTURE
REQUIREMENT THAT PAD AND/OR ROAD
BE RIPPED AND RELEVELLED

18. I hereby certify that the foregoing is true and correct

SIGNED

TITLE

DATE 3/19/74

(This space for Federal or State office use)

APPROVED BY

TITLE:

DATE _____

CONDITIONS OF APPROVAL, IF ANY:

APPROVED

AUG 20 1974

*See Instructions on Reverse Side

JIM SIMS
ACTING DISTRICT ENGINEER