

COPIES RECEIVED			
DISTRIBUTION			
OFFICE			

NEW MEXICO OIL CONSERVATION COMMISSION

3-NMOCC-HOBBS

1-FILE

Form C-103
Supersedes Old
C-102 and C-103
Effective 1-1-65

SUNDRY NOTICES AND REPORTS ON WELLS DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO AN ADJACENT RESERVOIR. USE "APPLICATION FOR PERMIT TO DRILL" (FORM C-101) FOR SUCH PROPOSALS.		5a. Indicate Type of Lease State ☒ Fee ☐ 5. State Oil & Gas Lease No.
☒ GAS WELL ☐ OTHER Operator GETTY OIL COMPANY Address of Operator P.O. BOX 249, HOBBS, NEW MEXICO		7. Unit Agreement No. 8. Farm or Lease No. STATE "J" 9. Well No. #2
1. Location of Well UNIT LETTER D 660 FEET FROM THE NORTH 660 FEET FROM WEST LINE, SECTION 17 TOWNSHIP 19-S RANGE 37-E NMPM.		10. Field and Pool or Wildcat MONUMENT
15. Elevation (Show whether DF, BT, CR, etc.)		12. County LEA

Check Appropriate Box To Indicate Nature of Notice, Report or Other Data			
NOTICE OF INTENTION TO:		SUBSEQUENT REPORT ON:	
PERFORM REMEDIAL WORK ☐	PLUG AND ABANDON ☒	REMEDIAL WORK ☐	ALTERED CASING ☐
TEMPORARILY ABANDON ☐	CHANGE PLANS ☐	COMMENCE DRILLING OPNS. ☐	PLUG AND ABANDONMENT ☐
PULL OR ALTER CASING ☐	OTHER ☐	CASING TEST AND CEMENT JOB ☐	OTHER ☐

7. Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, including estimated dates of completion of any proposed work) SEE RULE 1103.

1. Set CIBP @ 3800' and dump 35' cement on top.
2. Circulate hole with 9.5# brine mixed with 25 sks. per 100 bbl. salt gel.
3. Place 100' cement plug with top @ 1400'.
4. Place 10 sk. Cement plug @ surface.
5. Set P/A Marker and clean off location.

8. I hereby certify that the information above is true and complete to the best of my knowledge.

ORIGINAL SIGNED BY:		
SIGNED C.L. Wade:	C. L. Wade	TITLE AREA SUPERINTENDENT
Orig. Signed by John Runyan Geologist		DATE AUGUST 12, 1975
APPROVED BY		DATE
CONDITIONS OF APPROVAL, IF ANY:		

AO/bh