

**DISTRICT I**

P.O. Box 1980, Hobbs, NM 88241

**DISTRICT II**

P.O. Box Drawer DD, Artesia, NM 88210

**DISTRICT III**

1000 Rio Brazos Rd., Aztec, NM 87410

**OIL CONSERVATION DIVISION**

2040 Pacheco St.  
Santa Fe, NM 87505

WELL API NO. 30-025-05639	
5. Indicate Type of Lease STATE <input checked="" type="checkbox"/> FEE <input type="checkbox"/>	
6. State Oil / Gas Lease No. B-2656	
7. Lease Name or Unit Agreement Name North Monument G/SA Unit Blk. 5	
8. Well No. 12	
9. Pool Name or Wildcat Eunice Monument G/SA	
10. Elevation (Show whether DF, RKB, RT, GR, etc.)	

**SUNDY NOTICES AND REPORTS ON WELLS**  
(DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A DIFFERENT RESERVOIR. USE "APPLICATION FOR PERMIT" (FORM C-101) FOR SUCH PROPOSALS.)


1. Type of Well OIL WELL <input checked="" type="checkbox"/> GAS WELL <input type="checkbox"/> OTHER <input type="checkbox"/>
2. Name of Operator Amerada Hess Corporation
3. Address of Operator P.O. Box 840, Seminole, TX 79360
4. Well Location Unit Letter <u>L</u> : <u>1980</u> Feet From The <u>FSL</u> Line and <u>660</u> Feet From The <u>FWL</u> Line Section <u>19</u> Township <u>19S</u> Range <u>37E</u> NMPM <u>Lea</u> COUNTY

11. Check Appropriate Box to Indicate Nature of Notice, Report, or Other Data

NOTICE OF INTENTION TO:	SUBSEQUENT REPORT OF:
PERFORM REMEDIAL WORK <input checked="" type="checkbox"/>	REMEDIAL WORK <input type="checkbox"/>
TEMPORARILY ABANDON <input type="checkbox"/>	ALTERING CASING <input type="checkbox"/>
PULL OR ALTER CASING <input type="checkbox"/>	COMMENCE DRILLING OPERATIONS <input type="checkbox"/>
OTHER: <input type="checkbox"/>	PLUG AND ABANDONMENT <input type="checkbox"/>
	CASING TEST AND CEMENT JOB <input type="checkbox"/>
	OTHER: <input type="checkbox"/>

12. Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work) SEE RULE 1103.

Plan to MIRU pulling unit & TOH w/rods & pump. Remove wellhead, install BOP & TOH w/tbg. TIH w/bit & drill out plug to TD at 3967'. Spot cement plug in Open Hole to 3880'. Swab well. Re-run prod. eqpt. & continue prod. well.



I hereby certify that the information above is true and complete to the best of my knowledge and belief.

SIGNATURE <u>Roy L. Wheeler, Jr.</u>	TITLE <u>Bus. Svc. Spec. II</u>	DATE <u>04/29/2002</u>
TYPE OR PRINT NAME <u>Roy L. Wheeler, Jr.</u>	TELEPHONE NO. <u>915-758-6778</u>	

(This space for State Use)

APPROVED BY <u>PAUL F. KAUTZ</u>	TITLE <u>PETROLEUM ENGINEER</u>	DATE <u>APR 30 2002</u>
CONDITIONS OF APPROVAL, IF ANY:		