

Submit 3 Copies
to Appropriate
District Office

State of New Mexico
Energy, Minerals and Natural Resources Department

Form C-103
Revised 1-1-89

DISTRICT I
P.O. Box 1980, Hobbs NM 88241-1980

DISTRICT II
P.O. Drawer DD, Artesia, NM 88210

DISTRICT III
1000 Rio Brazos Rd., Aztec, NM 87410

OIL CONSERVATION DIVISION

P.O. Box 2088
Santa Fe, New Mexico 87504-2088

WELL API NO.
30-025-05713

5. Indicate Type of Lease
STATE ☒ FEE ☐

6. State Oil & Gas Lease No.
B-246-1

7. Lease Name or Unit Agreement Name
NORTH MONUMENT G/SA UNIT
BLK. 12

8. Well No.
5

9. Pool name or Wildcat
EUNICE MONUMENT G/SA

SUNDRY NOTICES AND REPORTS ON WELLS (DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A DIFFERENT RESERVOIR. USE "APPLICATION FOR PERMIT" (FORM C-101) FOR SUCH PROPOSALS.)	
1. Type of Well: OIL WELL <input type="checkbox"/> GAS WELL <input type="checkbox"/> OTHER INJECTION WELL	
2. Name of Operator Amerada Hess Corporation	
3. Address of Operator P.O. DRAWER D, MONUMENT, NM 88265	
4. Well Location Unit Letter <u>E</u> : <u>1980</u> Feet From The <u>NORTH</u> Line and <u>660</u> Feet From The <u>WEST</u> Line Section <u>28</u> Township <u>19S</u> Range <u>37E</u> NMPM LEA County	
10. Elevation (Show whether DF, RKB, RT, GR, etc.)	

11. Check Appropriate Box to Indicate Nature of Notice, Report, or Other Data

NOTICE OF INTENTION TO:

PERFORM REMEDIAL WORK ☐ PLUG AND ABANDON ☐
TEMPORARILY ABANDON ☐ CHANGE PLANS ☐
PULL OR ALTER CASING ☐
OTHER: ☐

SUBSEQUENT REPORT OF:

REMEDIAL WORK ☐ ALTERING CASING ☐
COMMENCE DRILLING OPNS. ☐ PLUG AND ABANDONMENT ☐
CASING TEST AND CEMENT JOB ☐
OTHER: CONVERT TO INJECTION WELL. ☒

12. Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work) SEE RULE 1103.

NMGSAU #.205 (12-18-96 THRU 12-30-96)

TYLER WELL SVC. & STAR TOOL MIRU. TOH W/PROD. EQUIPMENT. ND WH, RELEASED TAC BUT UNABLE TO REMOVE WFAP AROUND & PKG'G RUBBER FR. TBG. HEAD. UNSCREWED & RMV'D. 5-1/2" 8RD HINDERLITER TBG. SPOOL. SROVE OUT PKG'G. RUBBER & RE-INSTALLED TBG. HEAD. INSTALLED ADAPTER FLANGE & NU BOP. TOH W/TBG., TAC & SN. CHG'D. BOP RAMS TO 2-7/8". UNLOADED & RACKED WORKSTRING FR. #1805. TIH W/BIT, D.C.'S, SN & PU OFF RACKS W/121 JTS. TBG. TAGGED @ 3,911' (16' FILL). PU POWER SWIVEL & INSTALLED STRIPPER. PUMPED 130 BBLS. WATER TO LOAD & BROKE CIRC. DRLD. OUT FILL FR. 3,911'-3,926'. FELL OUT & TAGGED @ 3,930'. CIRC. CLEAN. TOH W/122 JTS. TBG., SN, D.C.'S & BIT. TIH W/MODEL "G" RBP, SN & 121 JTS. TBG. SET & GOT OFF RBP @ 3,751'. LOADED 5-1/2" CSG. W/85 BBLS. & CIRC. WELLBORE.
(CONTINUED)

I hereby certify that the information above is true and complete to the best of my knowledge and belief.

SIGNATURE Terry L. Harvey TITLE SR. STAFF ASSISTANT DATE 12/31/96

TYPE OR PRINT NAME TERRY L. HARVEY TELEPHONE NO. 505-393-2144

(This space for State Use)

APPROVED BY _____ TITLE _____ DATE _____

CONDITIONS OF APPROVAL, IF ANY:

JAN 09 1997

JCBA

dp