Service Control of Con	NO. OF COPIES RECEIVED		Form C-103
NEW MEXICO OIL CONSERVATION COMMISSION St. Indicate Type of Linear Property Of the Constant Property of Linear Property Of the Constant Propert	DISTRIBUTION		
Solution of Companies Solution Solutio	SANTA FE	NEW MEXICO OIL CONSERVATION COMMISSION	
SUNDRY NOTICES AND REPORTS ON WELLS OB NOT DEFENDED TO THE CONTROL OF THE PROPERTY OF THE CONTROL OF THE CONTR	FILE	The second secon	FULLOCATAGE 1-1-00
SUNDRY NOTICES AND REPORTS ON WELLS OR NOT DET THE PERMANENT PROPERTY OF THE SECOND NOTICES AND REPORTS ON WELLS OR NOT DET THE PERMANENT PROPERTY OF THE SECOND NOTICES AND REPORTS ON WELLS OR NOT DET THE PERMANENT PROPERTY OF THE SECOND NOTICE OF THE SECOND	U.S.G.S.		5a. Indicate Type of Lease
SUNDRY NOTICES AND REPORTS ON WELLS TO NOT DETERMINE AND REPORTS ON WELLS TO COMMENT OF COMMENT OF THE STREET AND REPORTS ON WELLS TO COMMENT OF THE STREET AND REPORTS ON WELLS TO COMMENT OF THE STREET AND REPORTS ON WELLS THE STREET OF THE STREET AND REPORTS ON WELLS THE STREET OF THE STREET OF THE STREET OF THE STREET ASSOCIATION OF THE STREET OF THE STREE	LAND OFFICE		
SUNDRY NOTICES AND REPORTS ON WELLS Description of the first of the following of the first of	OPERATOR		
ALTERNA CARRELLA MORE CANNEL PROPOSADO CARRETT RESIDENCE CANNEL PLANS THE FEBRUAL PLANS THE FEBR	· · · · · · · · · · · · · · · · · · ·	1	o, state on a das Lease No.
ALTERNA CARRELLA MORE CANNEL PROPOSADO CARRETT RESIDENCE CANNEL PLANS THE FEBRUAL PLANS THE FEBR	SUNDO	NOTICES AND DEDODES ON HIELD O	- himminn
ALTERNA CARRELLA MORE CANNEL PROPOSADO CARRETT RESIDENCE CANNEL PLANS THE FEBRUAL PLANS THE FEBR	(DO NOT USE THIS FORM FOR PRO	POSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A DIFFERENT RESERVOIR.	
Notes of Control Bidgs. Fidland, Texas 79701 316 Central Bidgs. Fidland, Texas 79701 10. Field and pool, or Wildows 11. Location of West 11. Location of West 12. Location of West 13. Licentine of West 13. Licentine of West 14. Location of West 15. Licentine of West 16. Licentine of West 17. Licentine of West 18. Licentine of West 19. Market 37E	1.	TOR FOR FERMIT - (FORM C-101) FOR SUCH PROPOSALS.)	
Althorse of Operator John H. Hendrix John H. Hendrix 316 Central Side., Midland, Texas 79701 1. Contine 1990 The East Int. Section 32 Townself 195 Name 1990 The East Int. Section 32 Townself 195 Name 37B Notice of Notice		OTHER.	7. Unit Agreement Name
John H. Hendrix 316 Central Bidg., Midland, Texas 79701 316 Central Bidg., Midland, Texas 79701 317 John H. Line and Pool, or Wildow John Letter I. 1650 South Line and 990 rest read House of Control of Pool, or Wildow The East Line, Section 32 roomers 198 same 37B read Check Appropriate Box To Indicate Nature of Notice, Report or Other Data NOTICE OF INTENTION TO: PRESCAM REMOVAL MORE CHANGE PLANE COMMENCE OR BILLING OWNE. ALTERING CASHING COMMENCE OR BILLING OWNE. COMMENCE OF THE	2. Name of Operator	OTHER.	
316 Central Bldg., Midland, Texas 79701 10. Field and Pool, or Wildow 110. Field and Pool 110. F	John H. Handrie		
316 Central Bidg., Midland, Texas 79701 Licostops of well Licostops	3. Address of Operator		
UNIT LETTER I . 1650 PERFORM THE SOUTH LINE AND 990 PERFORM CONTROL OF WILLOW AND ADDRESS IN THE East LINE, SECTION 32 YOUNGERS 198 SAAGE 37E NAME. 13. 1650 PERFORM THE SOUTH SOUT		97 * 17 1 M3	
The East Line, section 32 Township 198 Name 37E Name 10. Field and Peal, or Wildow 1990 The East Line, section 32 Township 198 Name 37E Name 1990 The East Line, section 32 Township 198 Name 37E Name 1990 The East Line, section 32 Township 198 Name 37E Name 1990 The East Notice of Intention To: Check Appropriate Box To Indicate Nature of Notice, Report or Other Data Notice of Intention To: Subsequent Report of: Subsequent Repor	4. Location of Well		<u> </u>
The East the section 32 Township 198 Range 37E MAPPA 13. Elevation (Show whether DF, RT, GR, etc.) 12. County 15. Elevation (Show whether DF, RT, GR, etc.) 16. Check Appropriate Box To Indicate Nature of Notice, Report or Other Data NOTICE OF INTENTION TO: PENTORM REMEDIAL WORK TEMPORABILLY Abandon PULL AND ABANDON PULL OF AND ABANDON PULL OF AND ABANDON OTHER 1. Describe Proposed of Completed Operations (Clearly store all persinent details, and give pertinent dates, including estimated date of storing any proposed water loss cement retainer at 3750° and squeezed old perforations w/300 sxs low water loss cement. Perforated Grayburg formation w/14 holes @ 3653, 3665, 3674, 3684, 3692, 3699, 3706, 3710, 3714, 3722, 3726, 3731, 3735 & 3741. 2. Acidized with 8200 gallons 15;5 N.E. acid and fractured with 40,000 gals. gelled water and 30,000% 20-40 sand. Treated @ 3500% with AIR of 20 BPM. 3. Tested November 18, 1971 flowing 350 MCFGPD, 3 barrels oil and 6 barrels water through a 40/64* choke. FTP 30%. 10 Describe Proposed of Completed Operations of the best of my knowledge and bellef. 12 Country 15 Country 16 Country 16 Country 16 Country 16 Country 17 Country 17 Country 17 Country 18 Country 19 Country 18 Country 19 Country 18 Country 19 Country 18 Country 19			
The East the section 32 Township 198 Range 37E MAPPA 13. Elevation (Show whether DF, RT, GR, etc.) 12. County 15. Elevation (Show whether DF, RT, GR, etc.) 16. Check Appropriate Box To Indicate Nature of Notice, Report or Other Data NOTICE OF INTENTION TO: PENTORM REMEDIAL WORK TEMPORABILLY Abandon PULL AND ABANDON PULL OF AND ABANDON PULL OF AND ABANDON OTHER 1. Describe Proposed of Completed Operations (Clearly store all persinent details, and give pertinent dates, including estimated date of storing any proposed water loss cement retainer at 3750° and squeezed old perforations w/300 sxs low water loss cement. Perforated Grayburg formation w/14 holes @ 3653, 3665, 3674, 3684, 3692, 3699, 3706, 3710, 3714, 3722, 3726, 3731, 3735 & 3741. 2. Acidized with 8200 gallons 15;5 N.E. acid and fractured with 40,000 gals. gelled water and 30,000% 20-40 sand. Treated @ 3500% with AIR of 20 BPM. 3. Tested November 18, 1971 flowing 350 MCFGPD, 3 barrels oil and 6 barrels water through a 40/64* choke. FTP 30%. 10 Describe Proposed of Completed Operations of the best of my knowledge and bellef. 12 Country 15 Country 16 Country 16 Country 16 Country 16 Country 17 Country 17 Country 17 Country 18 Country 19 Country 18 Country 19 Country 18 Country 19 Country 18 Country 19	UNIT LETTER	250 FEET FROM THE South LINE AND 990 FEET	FROM Monument (Grv-S.A.)
Check Appropriate Box To Indicate Nature of Notice, Report or Other Data NOTICE OF INTENTION TO: PRINT AND ASAMOUN PRILL OR ALTER CASING COMMENCE DELLING OPEN. COMMENCE			
Check Appropriate Box To Indicate Nature of Notice, Report or Other Data NOTICE OF INTENTION TO: PRINT AND ASAMOUN PRILL OR ALTER CASING COMMENCE DELLING OPEN. COMMENCE	THE East LINE, SECTION	00 - 32 TOWNSHIP 198 RANGE 37E	
Check Appropriate Box To Indicate Nature of Notice, Report or Other Data SUBSEQUENT REPORT OF: PERFORM REMEDIAL WORK PLUG AND ABANDON PLUG AND ABANDON PLUG AND ABANDON PLUG AND ABANDON CHANGE PLANS CHANGE			
Check Appropriate Box To Indicate Nature of Notice, Report or Other Data NOTICE OF INTENTION TO: PERFORM MEMERIAL WORK TEMPORABLY ABANDON PULL OR ALTER CASING OTHER 7. Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed water loss cement retainer at 3750° and squeezed old perforations w/300 sxs low water loss cement. Perforated Grayburg formation w/14 holes @ 3653, 3665, 3674, 3692, 3692, 3699, 3706, 3710, 3714, 3722, 3726, 3731, 3735 & 3741. 2. Acidized with 8200 gallons 15; N.E. acid and fractured with 40,000 gals. gelled water and 30,000# 20-40 sand. Treated @ 3500# with AIR of 20 BPM. 15 minute SIP @ 2100#. 3. Tested November 18, 1971 flowing 350 MCFGPD, 3 barrels oil and 6 barrels water through a 40/64* choke. FTP 30#.		15. Elevation (Show whether DF, RT, GR, etc.)	12. County
Check Appropriate Box To Indicate Nature of Notice, Report or Other Data NOTICE OF INTENTION TO: PERFORM REMEDIAL WORK PERFORM REMEDIAL WORK TEMPORABILLY ADARDON PULL OR ALTERING CASING THE OTHER TO THE OTHER TO THE OTHER TO THE OTHER OF THE OTHER		\\\\\\ 3573 DF	Lea
NOTICE OF INTENTION TO: SUBSEQUENT REPORT OF: PERFORM HEMEDIAL WORK PLUG AND ASARDON CHANGE PLANS COMMENCE BRILLING ORDS. CHANGE PLANS OTHER ALTERING CASING PLUG AND ABANDONMENT PLUG AND ABANDONMENT CASING TEST AND CEMENT JOB OTHER OTHER OTHER OTHER OTHER OTHER OTHER ALTERING CASING PLUG AND ABANDONMENT ALTERING CASING OTHER	Check A	Appropriate Box To Indicate Nature of Notice Report of	Other Date
PERFORM SEMEDIAL WORK TEMPORABILY ABARDON PULL OR ALTER CASING OTHER 7. Describe Proposed or Completed Operations (Clearly state all persiness details, and give pertinent dates, including estimated date of starting any proposed work) SEE RULE 1103. Workover operations started October 14, 1971 1. Set cement retainer at 3750° and squeezed old perforations w/300 sxs low water loss cement. Perforated Grayburg formation w/14 holes @ 3653, 3665, 3674, 3684, 3692, 3699, 3706, 3710, 3714, 3722, 3726, 3731, 3735 & 3741. 2. Acidized with 8200 gallons 15; N.E. acid and fractured with 40,000 gals. gelled water and 30,000# 20-40 sand. Treated @ 3500# with AIR of 20 BPM. 1.5 minute SIP @ 2100#. 3. Tested November 18, 1971 flowing 350 MCFGPD, 3 barrels oil and 6 barrels water through a 40/64* choke. FTP 30#.	NOTICE OF IN	17 CN TION	
TEMPORABILY ABANDON PULL OR ALTER CASING OTHER 7. Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work) see Rule 1108. Workover operations started October 14, 1971 1. Set coment retainer at 3750° and squeezed old perforations w/300 sxs low water loss cement. Perforated Grayburg formation w/14 holes @ 3653, 3665, 3674, 3692, 3699, 3706, 3710, 3714, 3722, 3726, 3731, 3735 & 3741. 2. Acidized with 8200 gallons 15; N.E. acid and fractured with 40,000 gals. gelled water and 30,000# 20-40 sand. Treated @ 3500# with AIR of 20 BPM. 15 minute SIP @ 2100#. 3. Tested November 18, 1971 flowing 350 MCFGPD, 3 barrels oil and 6 barrels water through a 40/64" choke. FTP 30#.		3083200	ENT REPORT OF:
TEMPORARILY ABANDON PULL OR ALTER CASING OTHER CHANGE PLANS PLUE AND ABANDONMENT PLUE AND ABANDONMEN	PERFORM REMEDIAL WORK	PLUG AND ABANDON DEMEDIAL WORK]
OTHER OT	TEMPORARILY ABANDON		ALTERING CASING
7. Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed works SER RULE 1103. Workover operations started October 14, 1971 1. Set cement retainer at 3750° and squeezed old perforations w/300 sxs low water loss cement. Perforated Grayburg formation w/14 holes @ 3653, 3665, 3674, 3684, 3692, 3699, 3706, 3710, 3714, 3722, 3726, 3731, 3735 & 3741. 2. Acidized with 8200 gallons 15½ N.E. acid and fractured with 40,000 gals. gelled water and 30,000# 20-40 sand. Treated @ 3500# with AIR of 20 BPM. 15 minute SIP @ 2100#. 3. Tested November 18, 1971 flowing 350 MCFGPD, 3 barrels oil and 6 barrels water through a 40/64* choke. FTP 30#.			PLUG AND ABANDONMENT
7. Describe Proposed of Completed Operations (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work) see Rule 1103. Workover operations started October 14, 1971 1. Set cement retainer at 3750° and squeezed old perforations w/300 sxs low water loss cement. Perforated Grayburg formation w/14 holes @ 3653, 3665, 3674, 3684, 3692, 3699, 3706, 3710, 3714, 3722, 3726, 3731, 3735 & 3741. 2. Acidized with 8200 gallons 15, N.E. acid and fractured with 40,000 gals. gelled water and 30,000# 20-40 sand. Treated @ 3500# with AIR of 20 BPM. 1.5 minute SIP @ 2100#. 3. Tested November 18, 1971 flowing 350 MCFGPD, 3 barrels oil and 6 barrels water through a 40/64 choke. FTP 30#.		THE TEST AND CEIMENT SOR	
7. Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work) see RULE 1703. Workover operations started October 14, 1971 1. Set cement retainer at 3750° and squeezed old perforations w/300 sxs low water loss cement. Perforated Grayburg formation w/14 holes @ 3653, 3665, 3674, 3684, 3692, 3699, 3706, 3710, 3714, 3722, 3726, 3731, 3735 & 3741. 2. Acidized with 8200 gallons 15% N.E. acid and fractured with 40,000 gals. gelled water and 30,000# 20-40 sand. Treated @ 3500# with AIR of 20 BPM. 15 minute SIP @ 2100#. 3. Tested November 18, 1971 flowing 350 MCFGPD, 3 barrels oil and 6 barrels water through a 40/64 choke. FTP 30#. Silver of the best of my knowledge and belief. One. Signed by Joe D. Ramey NOV 22197	OTHER	OTHER	
Workover operations started October 14, 1971 1. Set cement retainer at 3750° and squeezed old perforations w/300 sxs low water loss cement. Perforated Grayburg formation w/14 holes @ 3653, 3665, 3674, 3684, 3692, 3699, 3706, 3710, 3714, 3722, 3726, 3731, 3735 & 3741. 2. Acidized with 8200 gallons 15; N.E. acid and fractured with 40,000 gals. gelled water and 30,000# 20-40 sand. Treated @ 3500# with AIR of 20 BPM. 15 minute SIP @ 2100#. 3. Tested November 18, 1971 flowing 350 MCFGPD, 3 barrels oil and 6 barrels water through a 40/64* choke. FTP 30#.			
Orig. Signed by Joe D. Ramey TITLE OWNER-Operator DATE NOV. 19, 1971 NOV 2 2 197	 Set cement retai water loss cemen 3674, 3684, 3692 Acidized with 82 gelled water and 15 minute SIP @ Tested November 	ner at 3750 and squeezed old perfora t. Perforated Grayburg formation w/14 , 3699, 3706, 3710, 3714, 3722, 3726, 300 gallons 15% N.E. acid and fracture 30,000# 20-40 sand. Treated @ 3500# 2100#. 18. 1971 flowing 350 MCFGPD. 3 barrel	holes @ 3653, 3665, 3731, 3735 & 3741. ed with 40,000 gals. with AIR of 20 BPM.
A series of the	IGNED John J. J.	Out f TITLE OWNER-Operator	
PROVED BY Diet I C.			MUN ER 131

ONDITIONS OF APPROVAL, IF ANY:

, , ,