



(SUBMIT IN TRIPLICATE)

UNITED STATES

TERIOR

Budget Bureau 42 R358.3
Approval expires 12-31-55.

Land Office Las Cruces

Lease No. 055715 (a)

Unit

SUNDRY NOTICES AND REPORTS ON WELLS

NOTICE OF INTENTION TO DRILL	SUBSEQUENT REPORT OF WATER SHUT-OFF
NOTICE OF INTENTION TO CHANGE PLANS	SUBSEQUENT REPORT OF SHOOTING OR ACIDIZING
NOTICE OF INTENTION TO TEST WATER SHUT-OFF	SUBSEQUENT REPORT OF ALTERING CASING
NOTICE OF INTENTION TO RE-DRILL OR REPAIR WELL	SUBSEQUENT REPORT OF RE-DRILLING OR REPAIR
NOTICE OF INTENTION TO SHOOT OR ACIDIZE	SUBSEQUENT REPORT OF ABANDONMENT
NOTICE OF INTENTION TO PULL OR ALTER CASING	SUPPLEMENTARY WELL HISTORY
NOTICE OF INTENTION TO ABANDON WELL	

(INDICATE ABOVE BY CHECK MARK NATURE OF REPORT, NOTICE, OR OTHER DATA)

N. B. Bordages

September 8, 1955

Well No. 2 is located 1650 ft. from N line and 1650 ft. from E line of sec. 33

NW/4 of Sec. 33
($\frac{1}{4}$ Sec. and Sec. No.)

19-S
(Twp.)

37-E
(Range)

NMPM
(Meridian)

Monument
(Field)

Lea
(County or Subdivision)

New Mexico
(State or Territory)

The elevation of the derrick floor above sea level is 3581 ft.

DETAILS OF WORK

(State names of and expected depths to objective sands; show sizes, weights, and lengths of proposed casings; indicate mudding jobs, cementing points, and all other important proposed work)

A 75 sack cement plug was placed in the bottom of the well and the well and the casing filled with fresh water treated with sodium bichromate (for corrosion protection). A swedge and valve were placed on the casing at the surface. A 4" dia steel marker was placed on the location. The cellar was filled and the location cleaned for inspection.

I understand that this plan of work must receive approval in writing by the Geological Survey before operations may be commenced.

Company Great Western Producers, Inc.

Address Box 1659

Midland, Texas

R. W. A. L. I.