

DISTRICT I  
P.O. Box 1980, Hobbs, NM 88240

DISTRICT II  
P.O. Drawer DD, Artesia, NM 88210

DISTRICT III  
1000 Rio Brazos Rd., Aztec, NM 87410

OIL CONSERVATION DIVISION  
P.O. Box 2088  
Santa Fe, New Mexico 87504-2088

WELL API NO. 30-025-05908
5. Indicate Type of Lease STATE <input type="checkbox"/> FEE <input checked="" type="checkbox"/>
6. State Oil & Gas Lease No.
7. Lease Name or Unit Agreement Name NORTH MONUMENT G/SA UNIT BLK. 21
8. Well No. 3
9. Pool name or Wildcat EUNICE MONUMENT G/SA

SUNDRY NOTICES AND REPORTS ON WELLS  
(DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A  
DIFFERENT RESERVOIR. USE "APPLICATION FOR PERMIT"  
(FORM C-101) FOR SUCH PROPOSALS.)

1. Type of Well: OIL WELL <input checked="" type="checkbox"/> GAS WELL <input type="checkbox"/> OTHER <input type="checkbox"/>	2. Name of Operator AMERADA HESS CORPORATION
3. Address of Operator DRAWER D, MONUMENT, NM 88265	4. Well Location Unit Letter C : 660 Feet From The NORTH Line and 1980 Feet From The WEST Line Section 5 Township 20S Range 37E NMPM LEA County
10. Elevation (Show whether DF, RKB, RT, GR, etc.)	

11. Check Appropriate Box to Indicate Nature of Notice, Report, or Other Data	
NOTICE OF INTENTION TO:	SUBSEQUENT REPORT OF:
PERFORM REMEDIAL WORK <input type="checkbox"/>	REMEDIAL WORK <input type="checkbox"/>
TEMPORARILY ABANDON <input type="checkbox"/>	ALTERING CASING <input type="checkbox"/>
PULL OR ALTER CASING <input type="checkbox"/>	COMMENCE DRILLING OPNS. <input type="checkbox"/>
OTHER: <input type="checkbox"/>	PLUG AND ABANDONMENT <input type="checkbox"/>
	CASING TEST AND CEMENT JOB <input type="checkbox"/>
	OTHER: TESTED CSG. & ACIDIZED <input checked="" type="checkbox"/>

12. Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work) SEE RULE 1103.

4-20-93 THRU 4-26-93

MIRU X-PERT WELL SERVICE PULLING UNIT & PULLED RODS & PUMP. INSTALLED BOP & PULLED TBG. RAN A 6-1/8" BIT & TAGGED BOTTOM AT 3861' FOR 33' OF FILL. TOH W/TUBING & BIT. RAN A 7" X 2-7/8" BAKER LOC-SET RBP AND SET THE PLUG AT 3751'. STAR TOOL CIRC. THE 7" CSG. CLEAN W/170 BBLs. FRESH WATER & PRESS. UP ON CSG. TO 600 PSI FOR 38 MIN. HELD OK. LATCHED ONTO, RELEASED RBP & TOH. RAN A 6-1/8" BIT. TAGGED UP ON FILL AT 3861', BROKE CIRC. W/140 BBLs. FRESH WATER & DRILLED OUT FILL FR. 3861' TO TD AT 3894'. TOH W/BIT. SCHLUMBERGER LOGGED THE OH FR. 3894' TO 3730' & CSG. FR. 3730' TO 2894' W/A CNL & GAMMA RAY. RAN A 7" X 2-3/8" BAKER FULLBORE PKR. & SET AT 3734'. STAR TOOL LOADED 7" CSG. W/120 BBLs. FRESH WATER & PRESS. UP TO 500 PSI. LOADED TBG. W/23 BBLs. FRESH WATER & TESTED TO 2500 PSI. HELD OK. SERFCO LOADED 7" CSG. & PRESS. TO 500 PSI & ACIDIZED OH FR. 3780'-3894' W/5000 GAL. OF

(CONT)

I hereby certify that the information above is true and complete to the best of my knowledge and belief.

SIGNATURE R. L. Wheeler, Jr. TITLE SUPV. ADMIN. SER. DATE 5-14-93  
TYPE OR PRINT NAME ROY L. WHEELER, JR. TELEPHONE NO. 393-2144

(This space for State Use)  
ORIGINAL SIGNED BY JERRY SEXTON  
DISTRICT I SUPERVISOR

APPROVED BY \_\_\_\_\_ TITLE \_\_\_\_\_ DATE MAY 21 1993

CONDITIONS OF APPROVAL, IF ANY:

RECEIVED

MAY 20 1933

OLD MOUNTS AT