		*			ż.				
NO. OF COPIES	RECEIVED	٦				Form C-103			
DISTRIBU		-		0.0.		Supersedes Ol			
SANTA FE	3.101	- NEW MEX	וכס חוו בחאי	SERVATION, COMMIS	SSION	C-102 and C-1 Effective 1-1-6			
FILE		Orig&2cc: 000	Hobb∎			21.001.70 11 (,,,		
			ional off:			5a. Indicate Type	of Lease		
U.S.G.S.		cc: fil				State	Fee X		
LAND OFFIC	E	-	.0			5, State Oil & Ga	s Lease No.		
OPERATOR									
	CLIND	DV NOTICES AND I	DEDODIE ON	WELLC		mmm			
SUNDRY NOTICES AND REPORTS ON WELLS (DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEFENEN OR PLUG BACK TO A DIFFERENT RESERVOIR. USE "APPLICATION FOR PERMIT —" (FORM C-101) FOR SUCH PROPOSALS.)									
1.			· ·			7. Unit Agreemen	t Name		
OIL X	GAS WELL	OTHER-	Einstell C.1	Committee Marget					
2. Name of Oper				Richfield Company		8. Farm or Lease			
	Sinclair Oi	1 & Gas Company	r inffective Mar	ch 4, 1969			J. Barber		
3, Address of Operator						9. Well No.			
P. O. Box 1920, Hobbs, New Mexico 88240						17			
4. Location of Well						10. Field and Pool, or Wildcat			
UNIT LETTER I 2310 FEET FROM THE South LINE AND 495 FEET FROM						Monument Blinebry			
	·								
La Ea	st He sect	10N TOV	WNSHIP 20S	RANGE	37E NMPM.				
186	LINE, SEC.	104 104							
THITT		15. Elevation	on (Show whether	DF, RT, GR, etc.)		12. County			
						Lea			
16.	Check	Appropriate Box 7	To Indicate 1	Nature of Notice.	Report or Oth	ner Data			
		INTENTION TO:		1	_	REPORT OF:			
	1101102 01								
PERFORM REMED	ITAL WORK	PLUG A	ND ABANDON	REMEDIAL WORK	X	ALTER	ING CASING		
	Ħ			COMMENCE DRILLING	OPNS.		AND ABANDONMENT		
TEMPORARILY A	75	CHANGI	E PLANS	CASING TEST AND CE	77				
PULL OR ALTER	CASING	CHANGE	- PCANS	OTHER					
OTHER				J					
				<u> </u>					
	oposed or Completed (Operations (Clearly state	all pertinent de	tails, and give pertiner	nt dates, including	estimated date of	starting any proposed		
		O sacks Incor !	Vest cemen	t eliment wit 1	11. 6# into 1	Rlinehmr ner	of c		
2-12-01		. Press. 2100#,					4 □ •		
2 11, 67	Resourced B	II 655. LICCH,	EELI OOT	w/150 nacks Tr	crasilor with	w/25# floor	ool in lat		
2-14-07	2-14-67 Resqueezed Blinebry perfs. 5541-82' w/150 sacks Incor cemen 100 sacks Max. Press. 4500#. Reversed out 65 sacks. WOC 2				TOOL CAUSTIC	base 1108 cal In 186			
2 15 67							11 dol		
Z-13-0/		et. @ 5501 and			essure test	su peris. 55	41-82'		
0.35 /5		30 mins. Test	• • •						
	Jet perforated 7"OD casing @ 5608' w/4 -3/8" holes. Squeezed Blinebry perfs. 5576-5640' w/150 sacks Class C cement 14.5# Max. Press.								
2-20-67					Lass C cemer	nt 14.5# Max	c. Press.		
		sed out 5 sacks			_				
	Pressure tested perfs. 5576-5640' 1000# for 30 mins. Tested O.K.								
2-22-67 Jet perforate Blinebry 5542-48-52-55-57' w/10-3/8" holes. Acidized perfs.							's. w/1000		
		tages Max. Pres	ss. 2100#,	Min. 1500# @	1.2 BPM IS	[P 18^O#, 5"	' SIP		
	1400#.								
3-29-67	Acidized Blinebry perfs. 5542-57' w/2000 gals. 15% N.E. acid 2 gals.C-12 plus								
	4 gals. J4 inhibitors, flushed w/35 Bbl. leare oil w/3 gale. BIA & 4 Gals. N-44								
	Max. Press.	2175#, Min. 150	00#@1.8	BPM ISIP 1700#	#, 10" SIP 5	500#.			
4-4-67									
plus 81 BFW. GOR 787:1. Gravity 39°.									
18. I hereby certify that the information above is true and complete to the best of my knowledge and belief.									
10. I hereby cer	V	source to the wind comp	,						
2	n/N.	At the		knaineen		,	5 47		
SIGNED	1/1/1/20	XUXCX	TITLE	Engineer		. DATE 4-	-5-67		
		\							
		ł							

CONDITIONS OF APPROVAL, IF ANY