STATE OF NEW MEXICO NERGY AND MINERALS DEPARTMENT OIL CONSERVATION DIVISION HO. OF COPICS RECEIVED Form C-103 P. O. BOX 2088 DISTRIBUTION Revised 10-1-73 SANTA FE SANTA FE, NEW MEXICO 87501 FILE 5a. Indicate Type of Lease U.S.G.3. Fen State LAND OFFICE 5. State Oil & Gas Lease No. DPERATOR SUNDRY NOTICES AND REPORTS ON WELLS (DO NOT USE THIS FORM FOR PROPOSALS TO I FILL ON TO DEEPEN OR PLUG BACK TO A DIFF USE "APPLICATION FOR PERMIT -" FORM C-101) FOR SUCH PROPOSALS.) 7. Unit Agreement Name OIL X 8. Farm or Lease Name Nume of Operator South Hobbs (GSA) Unit Amoco Production Company 9. Well No. Address of Operator 15 P. O. Box 68, Hobbs, NM 88240 10. Field and Pool, or Wildcat . Location of Well Hobbs GSA 660 660 North UNIT LETTER East 15. Elevation (Show whether DF, RT, GR, etc.) 12. County Lea Check Appropriate Box To Indicate Nature of Notice, Report or Other Data SUBSEQUENT REPORT OF: NOTICE OF INTENTION TO: PLUG AND ABANDON CASING TEST AND CEMENT JOB CHANGE PLANS Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work) SEE RULE 1103. Propose to increase production by the following method: Pull rods, pump, and tubing. Run retrievable bridge plug and set at 4020'. Perforate 3982'-3990' with 4 JSPF. Run packer and set at 3900'. Pump 1000 gallons of ASOL acid tagged with Radioactive Iodine. Pull tubing and packer. Install pumping equipment. 1-GPM 0+4-NMOCD, H 1-Hou 1-Susp

id. I hereby certify that the information above is true and complete to the best of my knowledge and belief. 4-10-81 Admin. Analyst

CONDITIONS OF APPROVAL, IF ANY: