## State of New Mexico Energy, Minerals and Natural Resources Department

Form C-103 Revised 1-1-89

	Energy, Minerals and Natu		Rev	ised 1-1-89
FILE IN TRIPLICATE	OIL CONSERVA	TION DIVISION	WELL API NO.	
DISTRICT	2040 Pacheco St. Santa Fe, NM 87505		30-025-076	539
P.O. Box 1980, Hobbs, NM 88240	Santa re, r	(N 67505	5. Indicate Type of Lease	7
DISTRICT II 811 S. 1st Street, Artesia, NM 88210			FED STATE X	FEE
DISTRICT III			6. State Oil & Gas Lease No.	
1000 Pio Brazos Rd. Aztec, NM 87410				
SUNDRY NOTIC	CES AND REPORTS ON WEL	LS	7. Lease Name or Unit Agreement	Name
(DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A DIFFERENT RESERVOIR. USE "APPLICATION FOR PERMIT"				
DIFFFRENT RESERV	OIR. USE "APPLICATION FOR TEXT 101 FOR SUCH PROPOSALS.)		SOUTH HOBBS (G/SA) UNI	Т
1. Type of Well:	Gas Well Other INJ	ECTOR (T&A'd)		
Oil Well  2. Name of Operator	Gas well Other Itys	Ecroit (1441-5)	8. Well No. 113	
OCCIDENTAL PERMIAN LTD.			9. Pool name or Wildcat	HOBBS (G/SA)
3. Address of Operator 1017 W. Stanolind Rd., HOBBS, N	M 88240 505/393	7-8200		
4. Well Location			77.4 C/F	_ine
Unit Letter G: 1650	Feet From The NORTH	Line and 1650 Fe	et From The EAST	Zine
	Township 19S	Range 381	S NMPM	LEA County
Section 6	10. Elevation (Show whether DF, RK	(B, RT GR, etc.)		
	3613' GL Appropriate Box to Indicate Na	ture of Notice, Report, or	Other Data	
11. Check NOTICE OF INTE	Appropriate Box to indicate Nation TO:	SUB	OLGOLITI II.	
	PLUG AND ABANDON X	REMEDIAL WORK	ALTERING C	
PERFORM REMEDIAL WORK	CHANGE PLANS	COMMENCE DRILLING OF	PNS. PLUG & ABA	ANDONMENT
TEMPORARILY ABANDON	CHANGE I LANG	CASING TEST AND CEME		
PULL OR ALTER CASING		OTHER:		
OTHER:			a estimated date of starting any propo	osed work)
OTHER:  12. Describe Proposed or Completed Operation	ns (Clearly state all pertinent details, an	nd give pertinent dates, including	g estimated acres by the	
SEE RULE 1103.  Notify the NMOCD 24 hr before job.				
Notify the NMOCD 24 III before job.	(575 )	41102 4" CIDD @2705' I	Rot of salt @2800'.	
RUPU. Spot cmt from PBTD @3795'	to 2675'. 4" liner from 3042' to 4	1112. 4 CIBF (@3775. 1	Sol of Salar	
Chat mud get from 2675' to 600'. 109	01 3.3 CSg (@1240 (CDD)			
Spot cmt from 1725' to 1475'. Top of Perforate sqz hole @450'.	sait @1000.	/6		
Circ cmt to surface.		1	The same	
	C2213 TA	6		
Snot cmt from 450' to surface. Botton	n of 8-5/8" csg @321 .— \ \	•		
Cut off wellhead and install dry libre in	THE COLLEGE ON MIST	tre notified $24^{-1}$ .	7 000 2000 V	
RDPU. Clean Location.	- ANNOR BRIME TO LIFE	BEGINNING OF T		
	PLUGGING OPERATION	S FOR THE C-103		
	TO BE APPROVED.			
I hereby certify that the information above is	true and complete to the best of my kno	wledge and belief.		
I hereby certify that the information above is	2111 +	TITLE SR. ENGR.	TECH DATE	10142002
SIGNATURE Xoful	Filling	THEE SK. ENGL.	TELEPHONE NO.	505/397-8206
TYPE OR PRINT NAME ROBERT C				
(This space for State Use)ORIGINAL SI GARY W. W		TITI E	DATI	OCT 142
	PRESENTATIVE ILICTARE NA	TITLE		<del></del>
CONDITIONS OF APPROVAL IF ANY:	COMMENSATION OF THE PARTY NAMED WAS			
		·		