

DISTRICT I
P.O. Box 1980, Hobbs, NM 88240

DISTRICT II
P.O. Drawer DD, Artesia, NM 88210

DISTRICT III
1000 Rio Brazos Rd., Aztec, NM 87410

NEW MEXICO CONSERVATION DIVISION
P.O. Box 2088
Santa Fe, New Mexico 87504-2088

WELL API NO.
5. Indicate Type of Lease STATE <input type="checkbox"/> FEE <input checked="" type="checkbox"/>
6. State Oil & Gas Lease No.
7. Lease Name or Unit Agreement Name Cooper "A"
8. Well No. 1
9. Pool name or Wildcat Eunice Monument (G/SA)

SUNDRY NOTICES AND REPORTS ON WELLS
(DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A DIFFERENT RESERVOIR. USE "APPLICATION FOR PERMIT" (FORM C-101) FOR SUCH PROPOSALS.)

1. Type of Well: OIL WELL <input checked="" type="checkbox"/> GAS WELL <input type="checkbox"/> OTHER <input type="checkbox"/>
2. Name of Operator SHELL WESTERN E & P INC. (4431 WCK)
3. Address of Operator P.O. BOX 576, Houston, TX 77001-0576
4. Well Location Unit Letter <u>B</u> : <u>330</u> Feet From The <u>North</u> Line and <u>2310</u> Feet From The <u>East</u> Line Section <u>4</u> Township <u>20-S</u> Range <u>37-E</u> NMPM <u>Lea</u> County

10. Elevation (Show whether DF, RKB, RT, GR, etc.)
3563' DF

11. Check Appropriate Box to Indicate Nature of Notice, Report, or Other Data	
NOTICE OF INTENTION TO: PERFORM REMEDIAL WORK <input type="checkbox"/> PLUG AND ABANDON <input type="checkbox"/> TEMPORARILY ABANDON <input type="checkbox"/> CHANGE PLANS <input type="checkbox"/> PULL OR ALTER CASING <input type="checkbox"/> OTHER: <input type="checkbox"/>	SUBSEQUENT REPORT OF: REMEDIAL WORK <input type="checkbox"/> ALTERING CASING <input type="checkbox"/> COMMENCE DRILLING OPNS. <input type="checkbox"/> PLUG AND ABANDONMENT <input type="checkbox"/> CASING TEST AND CEMENT JOB <input type="checkbox"/> OTHER: Repair Brine flow, poss. casing leak <input checked="" type="checkbox"/>

12. Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work) SEE RULE 1103.

2-10-89 thru 2-28-89:

CO to 3530'. Ran CBL/CCL/GR from 3530' - 2570'. Shot 4-way shot @2510'. Set pkr @ 2377' and spot 250 gals 15% HCl acid into perfs. Set CICR @ 2377' and pmp 75 sxs class "C" cmt + 2% CaCl. Pres test to 300 psi - held O.K. Ran CBL/CCl from 4270' (PBTD) to surface. Perf w/ 4-way shot @ 1247'. Set CICR @ 1147' and pmp 260 sxs class "C" cmt. Pres test to 500 psi - held O.K. Circ hole w/ fresh water treated w/ Exxon 7720. Left well shut-in.

see Amended report

I hereby certify that the information above is true and complete to the best of my knowledge and belief.

SIGNATURE J. Smithman for W.F.N. KELLDORF TITLE STAFF PRODUCTION ENGINEER DATE APR 17 1989

TYPE OR PRINT NAME

TELEPHONE NO.

(This space for State Use)

**ORIGINAL SIGNED BY JERRY SEXTON
DISTRICT I SUPERVISOR**

APR 24 1989

APPROVED BY

TITLE

DATE

CONDITIONS OF APPROVAL, IF ANY:

RECEIVED

APR 21 1980

OCD
HOBBS OFFICE

DISTRICT I
P.O. Box 1980, Hobbs, NM 88240

DISTRICT II
P.O. Drawer DD, Artesia, NM 88210

DISTRICT III
1000 Rio Brazos Rd., Aztec, NM 87410

OIL CONSERVATION DIVISION

P.O. Box 2088
Santa Fe, New Mexico 87504-2088

WELL API NO.
5. Indicate Type of Lease STATE <input type="checkbox"/> FEE <input checked="" type="checkbox"/>
6. State Oil & Gas Lease No.
7. Lease Name or Unit Agreement Name COOPER "A"
8. Well No. 1
9. Pool name or Wildcat EUNICE MONUMENT (G-SA)

SUNDRY NOTICES AND REPORTS ON WELLS
(DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A
DIFFERENT RESERVOIR. USE "APPLICATION FOR PERMIT"
(FORM C-101) FOR SUCH PROPOSALS.)

1. Type of Well: OIL WELL <input checked="" type="checkbox"/> GAS WELL <input type="checkbox"/> OTHER	2. Name of Operator SHELL WESTERN E & P INC. (4431 WCK)
3. Address of Operator P.O. BOX 576, Houston, TX 77001-0576	4. Well Location Unit Letter B : 330 Feet From The NORTH Line and 2310 Feet From The EAST Line Section 4 Township 20-S Range 37-E NMPM LEA County
10. Elevation (Show whether DF, RKB, RT, GR, etc.) 3563' DF	

11. Check Appropriate Box to Indicate Nature of Notice, Report, or Other Data

NOTICE OF INTENTION TO:

PERFORM REMEDIAL WORK ☐ PLUG AND ABANDON ☐
TEMPORARILY ABANDON ☐ CHANGE PLANS ☐
PULL OR ALTER CASING ☐
OTHER: Repair Brine flow, poss. casing leak ☒

SUBSEQUENT REPORT OF:

REMEDIAL WORK ☐ ALTERING CASING ☐
COMMENCE DRILLING OPNS. ☐ PLUG AND ABANDONMENT ☐
CASING TEST AND CEMENT JOB ☐
OTHER: ☐

12. Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work) SEE RULE 1103.

- 1) CO to 3530' (PBTD).
- 2) Pres test 7" casing to 300 psi.
- 3) Run CBL/CCL/GR from PBTD to TOC.
- 4) Shoot 4-way shot +/- 50' above TOC as indicated by log evaluation.
- 5) TIH w/ pkr and set 100' above 4-way shot.
- 6) Set cmt retainer 100' above 4-way, pres test to 300 psi and pmp cmt (circ to surf).
- 7) Pres test to 300 psi.
- 8) Leave well shut-in.

I hereby certify that the information above is true and complete to the best of my knowledge and belief.

SIGNATURE W.F.N. KellDore TITLE STAFF PRODUCTION ENGINEER DATE 3/15/89
TYPE OR PRINT NAME TELEPHONE NO.

(This space for State Use)

ORIGINAL SIGNED BY JERRY SEXTON

MAR 21 1989

APPROVED BY DISTRICT I SUPERVISOR TITLE

DATE

CONDITIONS OF APPROVAL, IF ANY: