

NO. OF COPIES RECEIVED		
DISTRIBUTION		
SANTA FE		
FILE		
U.S.G.S.		
LAND OFFICE		
OPERATOR		

NEW MEXICO OIL CONSERVATION COMMISSION

Form C-103
Supersedes Old
C-102 and C-103
Effective 1-1-65

5a. Indicate Type of Lease	
State <input type="checkbox"/>	Fee <input checked="" type="checkbox"/>
5. State Oil & Gas Lease No.	

SUNDRY NOTICES AND REPORTS ON WELLS

(DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A DIFFERENT RESERVOIR. USE "APPLICATION FOR PERMIT - A" (FORM C-101) FOR SUCH PROPOSALS.)

1. OIL WELL <input checked="" type="checkbox"/> GAS WELL <input type="checkbox"/> OTHER <input type="checkbox"/>		7. Unit Agreement Name
2. Name of Operator Sun Oil Company		8. Farm or Lease Name W. B. Maveety
3. Address of Operator P. O. Box 1861, Midland, Texas 79701		9. Well No. 3
4. Location of Well UNIT LETTER <u>H</u> <u>660</u> FEET FROM THE <u>East</u> LINE AND <u>660</u> FEET FROM THE <u>North</u> LINE, SECTION <u>35</u> TOWNSHIP <u>19S</u> RANGE <u>36E</u> NN1PM.		10. Field and Pool, or Wildcat Monument G-SA
15. Elevation (Show whether DF, RT, GR, etc.) GR 3608		12. County Lea

Check Appropriate Box To Indicate Nature of Notice, Report or Other Data
NOTICE OF INTENTION TO: SUBSEQUENT REPORT OF:

PERFORM REMEDIAL WORK <input type="checkbox"/>	PLUG AND ABANDON <input type="checkbox"/>	REMEDIAL WORK <input type="checkbox"/>	ALTERING CASING <input type="checkbox"/>
TEMPORARILY ABANDON <input type="checkbox"/>	CHANGE PLANS <input type="checkbox"/>	COMMENCE DRILLING OPNS. <input type="checkbox"/>	PLUG AND ABANDONMENT <input type="checkbox"/>
PULL OR ALTER CASING <input type="checkbox"/>	OTHER <input type="checkbox"/>	CASING TEST AND CEMENT JOBS <input type="checkbox"/>	OTHER <u>Install artificial lift equipment</u> <input checked="" type="checkbox"/>

17. Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work) SEE RULE 1103.

10/28/70 - Pull tubing and packer; clean out with sand pump.
10/29/70 - Run tubing, set packer @ 3579; treat w/400 gal. XF63 acid.
10/30-31/11-1/70 - Swab
11/2/70 - Shut in; wait on pumping unit.
12/2/70 - Set pumping unit, start well pumping.

Note - Open hole completion 3774-3945.

18. I hereby certify that the information above is true and complete to the best of my knowledge and belief.

SIGNED <u>R. W. Hughes</u>	TITLE <u>Proration Clerk</u>	DATE <u>12/7/70</u>
APPROVED BY <u>[Signature]</u>	TITLE <u>SUPERVISOR DISTRICT</u>	DATE <u>DEC 2 1970</u>
CONDITIONS OF APPROVAL, IF ANY:		

RECEIVED

DEC 8 1970

OIL CONSERVATION COMM.
HOSES, N. H.