

SUNDRY NOTICES AND REPORTS ON WELLS

(Do not use this form for proposals to drill or to deepen or plug back to a different reservoir. Use "APPLICATION FOR PERMIT-" for such proposals.)

1. OIL ☐ GAS ☐  
WELL ☐ WELL ☒ OTHER

2. NAME OF OPERATOR  
Read & Stevens, Inc.

3. ADDRESS OF OPERATOR  
P.O. Box 1518, Roswell, NM 88201

4. LOCATION OF WELL (Report location clearly and in accordance with State requirements. \* See also space 17 below.)

At surface  
660' FNL & 990' FFL

14. PERMIT NO.

-

15. ELEVATIONS (Show whether DF, RT, GR, etc.)  
3642' GL

5. LEASE DESIGNATION AND SERIAL NO.  
NM-06570

6. IF INDIAN, ALLOTTEE OR TRIBE NAME  
-

7. UNIT AGREEMENT NAME  
-

8. FARM OR LEASE NAME  
Laurie "D" Federal

9. WELL NO.

1

10. FIELD AND POOL, OR WILDCAT  
Lea Penn

11. SEC, T, R, M, OR BLK & SURVEY OR AREA  
Sec. 15-T20S-R34E

12. COUNTY OR PARISH  
Lea

13. STATE  
NM

16. Check Appropriate Box To Indicate Nature of Notice, Report, Other Data  
NOTICE OF INTENTION TO:

TEST WATER SHUT-OFF  
FRACTURE TREAT  
SHOOT OR ACIDIZE  
REPAIR WELL  
(Other)

<input type="checkbox"/>
<input type="checkbox"/>
<input type="checkbox"/>
<input type="checkbox"/>

PULL OR ALTER CASING  
MULTIPLE COMPLETE  
ABANDON \*  
CHANGE PLANS

<input type="checkbox"/>
<input type="checkbox"/>
<input type="checkbox"/>
<input type="checkbox"/>

WATER SHUT-OFF  
FRACTURE TREATMENT  
SHOOTING OR ACIDIZING  
(Other) Acidize, swab

<input type="checkbox"/>
<input type="checkbox"/>
<input type="checkbox"/>

REPAIRING WELL  
ALTERING CASING  
ABANDONMENT \*

<input type="checkbox"/>
<input type="checkbox"/>
<input checked="" type="checkbox"/>

(NOTE: Report results of multiple completion on well  
Completion or Recompletion Report and Log form.)

17. DESCRIBE PROPOSED OR COMPLETED OPERATIONS (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work. If well is directionally drilled give subsurface locations and measured and true vertical depths for all markers and zones pertinent to this work.) \*

2-12-86 SITP 2100psi, hkd up to chk, flr to pt, flwd 7:30am-11:00am, 330psi-100psi, 20/64"chk, 225 MCF, unld 13 BW, 4 BNO, swbd Noon-5:30pm, rec'd ttl 8 BO, 24 BLW, 40 BFW, GG, approx 200 MCF, swbd 6 1/2 hrs, flwd 4 hrs. SION. SI 13 1/2 hrs, TP @ 6:00am 2-12-86 2000psi.

2-13-86 SI 13 1/2 hrs, TP 2000psi, blw dwn 2 1/2 hrs, swb 4 1/2 hrs, rec'd ttl 20 BO, 20 BW, 60 BW ovrd. RI & acdz perfs: 9470'-9476', 6'; 9490'-9508', 18'; 9604'-9612', 8'. Acdz w/3,000gals 15% NFFE acid w/53 ballsealers, avg press 5185psi, max press 5600psi, avg rate 4.6 BPM, gd ball action, gd brks, ISIP 2000psi, 5min 1600 psi, 10min 1150psi, 15min 850psi, ttl "d 116 BRLS, press bld dwn, swab 3 1/2 hrs, 47 BLW, 69 BLWTR.

2-14-86 SITP 1450psi, SI 13 1/2 hrs, flwd 7:00am-11:30am, 4 1/2 hrs, 10-20#, rec'd 41 BO, 44 BLW, swb 6 hrs, rec'd 15 BO, 31 BLW, ttl 56 BO, 69 BLW, +6 BFW, FL @ 6400', swbg from 8400', bringing 2000' varied GCO&W (fmy), flwd 15-20mins after each swb run, dry gas, 100#, fell off, will blw dwn, swb, run bombs for 72hr build-up. @ 7:30am 2-14-86 SI 13 1/2 hrs, TP 1500psi, flwg to tnks, unldg, gained 50psi.

I hereby certify that the foregoing is true and correct

SIGNED B. J. Stevens

TITLE Drilling & Production Manager

DATE February 17, 1986

(This space for Federal or State office use)

APPROVED BY

TITLE

DATE

CONDITIONS OF APPROVAL, IF ANY:

ACCEPTED FOR RECORD

Gwo

FEB 19 1986

CARLSBAD, NEW MEXICO