

DISTRICT I
P.O. Box 1980, Hobbs, NM 88240

DISTRICT II
P.O. Drawer DD, Artesia, NM 88210

DISTRICT III
1000 Rio Brazos Rd., Aztec, NM 87410

OIL CONSERVATION DIVISION
P.O. Box 2088
Santa Fe, New Mexico 87504-2088

WELL API NO. <u>30-125-30730</u>
5. Indicate Type of Lease STATE ☐ FEE ☒
6. State Oil & Gas Lease No.

SUNDRY NOTICES AND REPORTS ON WELLS (DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A DIFFERENT RESERVOIR. USE "APPLICATION FOR PERMIT" (FORM C-101) FOR SUCH PROPOSALS.)	
1. Type of Well: OIL WELL ☒ GAS WELL ☐ OTHER ☐	7. Lease Name or Unit Agreement Name <u>DANIELLE</u>
2. Name of Operator <u>LBO NEW MEXICO INC.</u>	8. Well No. <u>1</u>
3. Address of Operator <u>4101 BIRCH ST SUITE 130 NEWPORT BEACH, CALIF 92640</u>	9. Pool name or Wildcat <u>DRINKARD 1 ABO</u>
4. Well Location Unit Letter <u>C</u> : <u>1980</u> Feet From The <u>WEST</u> Line and <u>650</u> Feet From The <u>NORTH</u> Line Section <u>26</u> Township <u>18S</u> Range <u>38E</u> NMPM <u>CCN</u> County <u></u>	
10. Elevation (Show whether DF, RKB, RT, GR, etc.)	

11. Check Appropriate Box to Indicate Nature of Notice, Report, or Other Data	
NOTICE OF INTENTION TO:	SUBSEQUENT REPORT OF:
PERFORM REMEDIAL WORK ☐	REMEDIAL WORK ☐
TEMPORARILY ABANDON ☐	ALTERING CASING ☐
PULL OR ALTER CASING ☐	COMMENCE DRILLING OPNS. ☒
OTHER: ☐	PLUG AND ABANDONMENT ☐
	CASING TEST AND CEMENT JOB ☐
	OTHER: ☐

12. Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work) SEE RULE 1103.

SET 1548' 8 5/8" 2 1/2" ESP. PERFORATED 4500' CLASS 2" (B.T. TITAN) PERFORATED 1550'.

WELL 18 HAS.

SET 1730' 5 1/2" 1 7/8" ESP. WITH DV TOOL 4660' (CONCRETE) PERFORATED 12500'.

STAGE 1 3500' CLASS 2" PERFORATED 1500' W. 1 1/2" HAS. PERFORATED 12500'.

CLASS 2" PERFORATED 11000'. WELL 48 HAS. PERFORATED 12500' (RIGGED UP).

B.T. TITAN FOR 6000' 48 HAS. K-LINK ACID WITH 15% HCL FOR 1602-7215).

SWAPPED BACK 2000' BBS FOR SECTION WATER WITH 48 HAS.

RESEQUENCED DV. TOOL WITH 5500' CLASS 2" PERFORATED 12500'.

DRILLED OUT DV. TOOL SWAPPED 5000' STAGE 1 ACID 18 HAS.

RIGGED UP B.T. TITAN FOR ACID JOB TREATED WITH 15% HCL 1602-7215.

30,000 GAL 20% HCL 15% HCL AND 3000 GAL 15% HCL.

I hereby certify that the information above is true and complete to the best of my knowledge and belief.

SIGNATURE Donald A. Turner TITLE Geologist DATE 12-27-89

TYPE OR PRINT NAME DONALD A. TURNER TELEPHONE NO.

(This space for State Use)

ORIGINAL SIGNED BY JERRY SEXTON

APPROVED BY DISTRICT I SUPERVISOR TITLE DATE

CONDITIONS OF APPROVAL, IF ANY:

DEC 27 1989

RECEIVED

DEC 26 1989

OCD
HOBBS OFFICE