

Submit 3 Copies To Appropriate District  
Office  
District I  
1625 N. French Dr., Hobbs, NM 87240  
District II  
811 South First, Artesia, NM 87210  
District III  
1000 Rio Brazos Rd., Aztec, NM 87410  
District IV  
2040 South Pacheco, Santa Fe, NM 87505

State of New Mexico  
Energy, Minerals and Natural Resources

OIL CONSERVATION DIVISION  
2040 South Pacheco  
Santa Fe, NM 87505

Form C-103  
Revised March 25, 1999

WELL API NO. 30-025-30864
5. Indicate Type of Lease STATE <input checked="" type="checkbox"/> FEE <input type="checkbox"/>
6. State Oil & Gas Lease No. E-1587
7. Lease Name or Unit Agreement Name: West Pearl Queen Unit
8. Well No. 194
9. Pool name or Wildcat Pearl Queen
10. Elevation (Show whether DR, RKB, RT, GR, etc.)

**SUNDRY NOTICES AND REPORTS ON WELLS**  
(DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A DIFFERENT RESERVOIR. USE "APPLICATION FOR PERMIT" (FORM C-101) FOR SUCH PROPOSALS.)

1. Type of Well:  
Oil Well ☒ Gas Well ☐ Other ☐

2. Name of Operator  
Xeric Oil & Gas Corporation

3. Address of Operator  
PO Box 352 Midland, Texas 79702

4. Well Location  
Unit Letter P : 100 feet from the S line and 92 feet from the E line  
Section 29 Township 19S Range 35E NMPM Lea County

11. Check Appropriate Box to Indicate Nature of Notice, Report or Other Data

NOTICE OF INTENTION TO:		SUBSEQUENT REPORT OF:	
PERFORM REMEDIAL WORK <input type="checkbox"/>	PLUG AND ABANDON <input type="checkbox"/>	REMEDIAL WORK <input type="checkbox"/>	ALTERING CASING <input type="checkbox"/>
TEMPORARILY ABANDON <input type="checkbox"/>	CHANGE PLANS <input type="checkbox"/>	COMMENCE DRILLING OPNS. <input type="checkbox"/>	PLUG AND ABANDONMENT <input checked="" type="checkbox"/>
PULL OR ALTER CASING <input type="checkbox"/>	MULTIPLE COMPLETION <input type="checkbox"/>	CASING TEST AND CEMENT JOB <input type="checkbox"/>	
OTHER: <input type="checkbox"/>		OTHER: <input type="checkbox"/>	

12. Describe proposed or completed operations. (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work). SEE RULE 1103. For Multiple Completions: Attach wellbore diagram of proposed completion or recompilation.

1. MIRU Pulling Unit
2. RIH w/tbg & tag cement retainer @ 4735'
3. Circulate hole w/65 BBLs mud
4. Set plug #1 @ 1700' w/25 sx class "c" + CaCL
5. Set plug #2 @ 400' w/25 sx class "c" + CaCL
6. Tagged top of plug #2 @ 163'
7. Set surface plug @ 60' w/ 10 sx class "c" + CaCL
8. Installed dry hole marker and RDMO

Approved as to plugging of the Well Bore.  
Liability under bond is retained until  
surface restoration is completed.

I hereby certify that the information above is true and complete to the best of my knowledge and belief.

SIGNATURE Kyle Lewis TITLE Treasurer DATE 1/19/01

Type or print name Kyle Lewis

Telephone No 915-683-3650

(This space for State use)

JAN 30 2003

APPROVED BY Kyle Lewis TITLE Treasurer DATE 1/19/01

Conditions of approval, if any:

FIELD REPRESENTATIVE II/STAFF MANAGER

GWW

IC