

OIL CONSERVATION DIVISION
P. O. BOX 2088
SANTA FE, NEW MEXICO 87501

Form C-103
Revised 10-1-78

| | |
|------------------------|--|
| NO. OF COPIES RECEIVED | |
| DISTRIBUTION | |
| SANTA FE | |
| FILE | |
| U.S.G.S. | |
| LAND OFFICE | |
| OPERATOR | |

5a. Indicate Type of Lease
State Fee

5. State Oil & Gas Lease No.

SUNDRY NOTICES AND REPORTS ON WELLS
(DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A DIFFERENT RESERVOIR. USE "APPLICATION FOR PERMIT -" (FORM C-101) FOR SUCH PROPOSALS.)

| | |
|-------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------|----------------------------------------------------|
| 1. OIL WELL <input checked="" type="checkbox"/> GAS WELL <input type="checkbox"/> OTHER- | 7. Unit Agreement Name |
| 2. Name of Operator ARCO Oil and Gas Company Division of Atlantic Richfield Company | 8. Farm or Lease Name J. R. Cone AB |
| 3. Address of Operator P. O. Box 1710, Hobbs, New Mexico 88240 | 9. Well No. 1 |
| 4. Location of Well UNIT LETTER <u>M</u> <u>660</u> FEET FROM THE <u>South</u> LINE AND <u>660</u> FEET FROM THE <u>West</u> LINE, SECTION <u>26</u> TOWNSHIP <u>21S</u> RANGE <u>37E</u> NMPM. | 10. Field and Pool, or WHdcat Drinkard/Blinebry |
| 15. Elevation (Show whether DF, RT, GR, etc.) 3385' GL | 12. County Lea |

16. Check Appropriate Box To Indicate Nature of Notice, Report or Other Data
NOTICE OF INTENTION TO: SUBSEQUENT REPORT OF:

| | | | |
|------------------------------------------------|------------------------------------------------------------------------------------------------|-----------------------------------------------------|-----------------------------------------------|
| PERFORM REMEDIAL WORK <input type="checkbox"/> | PLUG AND ABANDON <input type="checkbox"/> | REMEDIAL WORK <input type="checkbox"/> | ALTERING CASING <input type="checkbox"/> |
| TEMPORARILY ABANDON <input type="checkbox"/> | CHANGE PLANS <input type="checkbox"/> | COMMENCE DRILLING OPWS. <input type="checkbox"/> | PLUG AND ABANDONMENT <input type="checkbox"/> |
| PULL OR ALTER CASING <input type="checkbox"/> | OTHER <u>Temp Abandon Drkd - Return to single Blinebry</u> <input checked="" type="checkbox"/> | CASING TEST AND CEMENT JOB <input type="checkbox"/> | OTHER <input type="checkbox"/> |

17. Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work) SEE RULE 1103.

- RU, kill well, install BOP, POH w/Bly tbg string. Rel anchor seal assembly from pkr & POH w/Drinkard tbg string.
- RIH w/CIBP & set @ 6280', spot 35' cmt on top of BP. Temporarily abandon Drinkard.
- RIH w/2" ACME 8 tbg w/SN, PN & bull plug, hang tbg @ 5900'. Swab well in, return to production as single Blinebry oil well.


18. I hereby certify that the information above is true and complete to the best of my knowledge and belief.

SIGNED Robert E. Balthus TITLE Drlg. Engr. DATE 4/23/84

ORIGINAL SIGNED BY JERRY SEXTON
DISTRICT I SUPERVISOR

DATE APR 24 1984

APPROVED BY _____ TITLE _____ DATE _____
CONDITIONS OF APPROVAL, IF ANY:



ARCO Oil & Gas Company
 Division of Atlantic Richfield Company
Blow Out Preventer Program

Lease Name J, R, Cone AB

Well No. 1

Location 660' FSL & 660' FWL
Sec 26-21S-37E, Lea County

BOP to be tested when installed on well and will be maintained in good working condition during drilling. All wellhead fittings to be of sufficient pressure to operate in a safe manner.