

Submit 3 Copies  
to Appropriate  
District Office

State of New Mexico  
Energy, Minerals and Natural Resources Department  
**OIL CONSERVATION DIVISION**  
P.O. Box 2088  
Santa Fe, New Mexico 87504-2088

Form C-103  
Revised 1-1-89

DISTRICT I  
P.O. Box 1980, Hobbs, NM 88240  
DISTRICT II  
P.O. Drawer Dd, Artesia, NM 88210  
DISTRICT III  
1000 Rio Brazos Rd., Aztec, Nm 87410

API NO. (assigned by OCD on New Wells) <b>30-025-06836</b>	
5. Indicate Type of Lease STATE <input type="checkbox"/> FEE <input checked="" type="checkbox"/>	
6. State Oil & Gas Lease No. N/A	
7. Lease Name or Unit Agreement Name J.N. CARSON NCT-C	
8. Well No. 9	
9. Pool name or Wildcat BLINEBRY	
10. Elevation(Show whether DF, RKB, RT, GR, etc.) 3424 GE	

**SUNDRY NOTICES AND REPORTS ON WELLS**  
(DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A DIFFERENT RESERVOIR. USE "APPLICATION FOR PERMIT" (FORM C-101) FOR SUCH PROPOSALS.)

1. Type of Well: OIL WELL <input checked="" type="checkbox"/> GAS WELL <input type="checkbox"/> OTHER <input type="checkbox"/>	
2. Name of Operator CHEVRON U.S.A. INC.	
3. Address of Operator P.O. BOX 1150 MIDLAND, TX 79702 ATTN: P.R. MATTHEWS	
4. Well Location Unit Letter <u>I</u> : <u>2086</u> Feet From The <u>SOUTH</u> Line and <u>766</u> Feet From The <u>EAST</u> Line Section <u>28</u> Township <u>21S</u> Range <u>37E</u> NMPM <u>LEA</u> County	
10. Elevation(Show whether DF, RKB, RT, GR, etc.) 3424 GE	

11 Check Appropriate Box to Indicate Nature of Notice, Report, or Other Data

<b>NOTICE OF INTENTION TO:</b>		<b>SUBSEQUENT REPORT OF:</b>	
PERFORM REMEDIAL WORK <input type="checkbox"/>	PLUG AND ABANDON <input type="checkbox"/>	REMEDIATION WORK <input type="checkbox"/>	ALTER CASING <input type="checkbox"/>
TEMPORARILY ABANDON <input type="checkbox"/>	CHANGE PLANS <input type="checkbox"/>	COMMENCE DRILLING OPNS. <input type="checkbox"/>	PLUG AND ABAN. <input type="checkbox"/>
PULL OR ALTER CASING <input type="checkbox"/>		CASING TEST AND CMT JOB <input type="checkbox"/>	
OTHER: <input type="checkbox"/>		OTHER: <u>SQZ. PADDOCK PERFS &amp; ADD PAY</u> <input checked="" type="checkbox"/>	

12. Describe Proposed or Completed Operations(Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work) SEE RULE 1103.

CLEAN OUT TO TD. SQUEEZE PADDOCK PERFS AT 5111-5270. W/125 SXS. OF CMT.  
TIH AND SET CICR AT 3597, SQZ. OFF PENROSE PERFS 3642-3768. W/100 SXS. OF CMT.  
DRILL OUT CICR AND CMT. TO 5274. DRILL OUT CIBP AT 5321. C/O TO 6345.  
LOG HOLE: GR-CCL. PERF 5457-5797. ACDZ PERFS, SWB BACK.  
FRAC PERFS WITH 90,000 GALS. OF X-L GEL, AND 205,000 LBS. OF 12/20 SAND.  
CLEAN OUT WELL. TIH WITH PACKER AND SET AT 5913.  
TEST ANN. RETURN TO PRODUCTION ON 03-13-92.

I hereby certify that the information above is true and complete to the best of my knowledge and belief.  
SIGNATURE P.R. Matthews TITLE TECH. ASSISTANT DATE: 03-23-92  
TYPE OR PRINT NAME P.R. MATTHEWS TELEPHONE NO. (915)687-7812

APPROVED BY \_\_\_\_\_ TITLE \_\_\_\_\_ DATE MAR 27  
CONDITIONS OF APPROVAL, IF ANY: