

Submit 3 Copies To Appropriate District Office
 District I
 1625 N. French Dr., Hobbs, NM 87240
 District II
 811 South First, Artesia, NM 87210
 District III
 1000 Rio Brazos Rd., Aztec, NM 87410
 District IV
 2040 South Pacheco, Santa Fe, NM 87505

State of New Mexico
 Energy, Minerals and Natural Resources

Form C-103
 Revised March 25, 1999

OIL CONSERVATION DIVISION
 2040 South Pacheco
 Santa Fe, NM 87505

WELL API NO. 30-025-06963
5. Indicate Type of Lease STATE <input type="checkbox"/> FEE <input checked="" type="checkbox"/>
6. State Oil & Gas Lease No.
7. Lease Name or Unit Agreement Name: CENTRAL DRINKARD UNIT
8. Well No. 147
9. Pool name or Wildcat DRINKARD

SUNDRY NOTICES AND REPORTS ON WELLS
 (DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A DIFFERENT RESERVOIR. USE "APPLICATION FOR PERMIT" (FORM C-101) FOR SUCH PROPOSALS.)

1. Type of Well: Oil Well Gas Well Other WIK

2. Name of Operator
Chevron U.S.A. Inc.

3. Address of Operator
P.O. Box 1150 Midland, TX 79702

4. Well Location
 Unit Letter K : 1980 feet from the SOUTH line and 1980 feet from the WEST line
 Section 33 Township 21S Range 37E NMPM County LEA

10. Elevation (Show whether DR, RKB, RT, GR, etc.)

11. Check Appropriate Box to Indicate Nature of Notice, Report, or Other Data

NOTICE OF INTENTION TO: PERFORM REMEDIAL WORK <input type="checkbox"/> PLUG AND ABANDON <input type="checkbox"/> TEMPORARILY ABANDON <input type="checkbox"/> CHANGE PLANS <input type="checkbox"/> PULL OR ALTER CASING <input type="checkbox"/> MULTIPLE COMPLETION <input type="checkbox"/> OTHER: <input type="checkbox"/>	SUBSEQUENT REPORT OF: REMEDIAL WORK <input type="checkbox"/> ALTERING CASING <input type="checkbox"/> COMMENCE DRILLING OPNS. <input type="checkbox"/> PLUG AND ABANDONMENT <input checked="" type="checkbox"/> CASING TEST AND CEMENT JOB <input type="checkbox"/> OTHER: <input type="checkbox"/>
---	--

12. Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work). SEE RULE 1103. For Multiple Completions: Attach wellbore diagram of proposed completion or recompilation.

POH W/TBG. SET CIBP @ 6414'; TAGGED. CIRC W/P&A MOD. SPOTTED 15 SX CMT @ 6413'.
 SPOTTED 25 SX CMT @ 4500'. SPOTTED 30 SX CMT @ 2800'; TAGGED @ 2600'. PERFD 1401';
 ATTEMPTED TO CIRC - PRESS UP, NO BLEED OFF. SPOTTED 25 SX CMT @ 2600'. SPOTTED 25
 SX CMT @ 1451' (PER E.L. GONZALES). PERFD 233'. CIRC DN 5-1/2" CSG & UP 8-5/8" CSG.
 CIRC CMT TO SURF IN 8-5/8". SET MARKER, CLEANED LOCATION.

P&A'D 10/22/01

RECEIVED
 Hobbs
 OGD

I hereby certify that the information above is true and complete to the best of my knowledge and belief.

SIGNATURE J. K. Ripley TITLE REGULATORY O.A. DATE 11/6/01

Type or print name J. K. RIPLEY Telephone No. (915)687-7148

(This space for State use)
 APPROVED BY Johnny Robinson TITLE COMPLIANCE SUPERVISOR DATE _____

Conditions of approval, if any:
GWW

S
 C
 S