

NO. OF COPIES RECEIVED		
DISTRIBUTION		
SANTA FE		
FILE		
U.S.G.S.		
LAND OFFICE		
OPERATOR		

NEW MEXICO OIL CONSERVATION COMMISSION

Form C-103
Supersedes Old
C-102 and C-103
Effective 1-1-65

5a. Indicate Type of Lease
State ☒ Fee ☐

5. State Oil & Gas Lease No.

B-143

SUNDRY NOTICES AND REPORTS ON WELLS

(DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A DIFFERENT RESERVOIR.
USE "APPLICATION FOR PERMIT -" (FORM C-101) FOR SUCH PROPOSALS.)

1. <input checked="" type="checkbox"/> OIL WELL <input type="checkbox"/> GAS WELL <input type="checkbox"/> OTHER-	7. Unit Agreement Name
2. Name of Operator	Jalmat Yates Sand Unit
3. Address of Operator	8. Farm or Lease Name
The British-American Oil Producing Company	Jalmat Yates Sand Unit
Box 474, Midland, Texas	9. Well No.
4. Location of Well	29-32
UNIT LETTER G , 1280 FEET FROM THE North LINE AND 1982' FEET FROM	10. Field and Pool, or Wildcat
THE East LINE, SECTION 1 TOWNSHIP 22-N RANGE 35-E NMPM.	Jalmat
15. Elevation (Show whether DF, RT, GR, etc.)	12. County
3691' RL	LOA

Check Appropriate Box To Indicate Nature of Notice, Report or Other Data

NOTICE OF INTENTION TO:

SUBSEQUENT REPORT OF:

PERFORM REMEDIAL WORK <input checked="" type="checkbox"/>	PLUG AND ABANDON <input type="checkbox"/>	REMEDIAL WORK <input type="checkbox"/>	ALTERING CASING <input type="checkbox"/>
TEMPORARILY ABANDON <input type="checkbox"/>	CHANGE PLANS <input type="checkbox"/>	COMMENCE DRILLING OPNS. <input type="checkbox"/>	PLUG AND ABANDONMENT <input type="checkbox"/>
WELL OR ALTER CASING <input type="checkbox"/>	OTHER <input type="checkbox"/>	CASING TEST AND CEMENT JOB <input type="checkbox"/>	

16. Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work) SEE RULE 1103.

1. Pull rods and tubing. Clean out to PSTD at 3873'.
2. Fracture treat perforations 3743 - 3770', 3790 - 3806', 3824 - 3847', and 3860 - 3878' with 50,000 gallons gelled injection water and 100,000 lbs 20-40 mesh frac sand. Treatment to be divided into four equal stages by using moth balls as temporary blocking agent.
3. Run sand pump to PSTD.
4. Run tubing, pump and rods.

I, hereby certify that the information above is true and complete to the best of my knowledge and belief.

SIGNED *O O Floyd* TITLE District Clerk DATE May 27, 1965

APPROVED BY _____ TITLE _____ DATE _____

CONDITIONS OF APPROVAL, IF ANY: