

Submit 3 Copies
to Appropriate
District Office

State of New Mexico
Energy, Minerals and Natural Resources Department

Form C-103
Revised 1-1-89

DISTRICT I
P.O. Box 1980, Hobbs, NM 88240

OIL CONSERVATION DIVISION
P.O. Box 2088
Santa Fe, New Mexico 87504-2088

DISTRICT II
P.O. Drawer DD, Artesia, NM 88210

DISTRICT III
1000 Rio Brazos Rd., Aztec, NM 87410

WELL API NO.
30-025-22851

5. Indicate Type of Lease
STATE FEE

6. State Oil & Gas Lease No.

SUNDRY NOTICES AND REPORTS ON WELLS
(DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A
DIFFERENT RESERVOIR. USE "APPLICATION FOR PERMIT"
(FORM C-101) FOR SUCH PROPOSALS.)

7. Lease Name or Unit Agreement Name

1. Type of Well:
OIL WELL GAS WELL OTHER

Royalty Holding

2. Name of Operator
American Exploration Company

8. Well No.
1

3. Address of Operator
1331 Lamar, Suite 900 Houston, Texas 77010

9. Pool name or Wildcat
Drinkard & Blinebry

4. Well Location
Unit Letter B : 1980 Feet From The East Line and 660 Feet From The North Line
Section 25 Township 21S Range 37E NMPM Lea County

10. Elevation (Show whether DF, RKB, RT, GR, etc.)
3406.8 GR

11. Check Appropriate Box to Indicate Nature of Notice, Report, or Other Data

NOTICE OF INTENTION TO:		SUBSEQUENT REPORT OF:	
PERFORM REMEDIAL WORK <input type="checkbox"/>	PLUG AND ABANDON <input checked="" type="checkbox"/>	REMEDIAL WORK <input type="checkbox"/>	ALTERING CASING <input type="checkbox"/>
TEMPORARILY ABANDON <input type="checkbox"/>	CHANGE PLANS <input type="checkbox"/>	COMMENCE DRILLING OPNS. <input type="checkbox"/>	PLUG AND ABANDONMENT <input type="checkbox"/>
PULL OR ALTER CASING <input type="checkbox"/>		CASING TEST AND CEMENT JOB <input type="checkbox"/>	
OTHER: <input type="checkbox"/>		OTHER: <input type="checkbox"/>	

12. Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work) SEE RULE 1103.

Current Configuration:

Proposed Plugging Procedure:

9 5/8" @ 910' Cmt'd to surface
7" @ 7500' Cmt'd w/785 sx
Drinkard/Abo Perfs 6532-7437'
CIBP @ 6470' + 35' cmt.
Blinebry Perfs 5829 - 5945'

1. Set CIBP @ 5775' & dump ~~30~~ cmt.
2. Load hole with mud.
3. Cut off 7" csg @ 960 and pull.
4. Spot: 50 sx cmt. 860 - 960'
5. Spot: 3 sx cmt. 3 - 15'.
6. Install well marker.

THE COMMISSION MUST BE NOTIFIED 24
HOURS PRIOR TO THE BEGINNING OF
PLUGGING OPERATIONS FOR THE C-103
TO BE APPROVED.

I hereby certify that the information above is true and complete to the best of my knowledge and belief.

SIGNATURE Melinda Mayse TITLE Regulatory Coordinator DATE 10/8/96
(713)
TYPE OR PRINT NAME Melinda Mayse TELEPHONE NO. 756-6338

(This space for State Use)

APPROVED BY _____ TITLE _____ DATE OCT 15 1996
CONDITIONS OF APPROVAL, IF ANY: