

NEW MEXICO OIL CONSERVATION COMMISSION
Santa Fe, New Mexico

MISCELLANEOUS NOTICES

Submit this notice in TRIPLICATE to the District Office, Oil Conservation Commission, before the work specified is to begin. A copy will be returned to the sender on which will be given the approval, with any modifications considered advisable, or the rejection by the Commission or agent, of the plan submitted. The plan as approved should be followed, and work should not begin until approval is obtained. See additional instructions in the Rules and Regulations of the Commission.

Indicate Nature of Notice by Checking Below

NOTICE OF INTENTION TO CHANGE PLANS		NOTICE OF INTENTION TO TEMPORARILY ABANDON WELL		NOTICE OF INTENTION TO DRILL DEEPER	
NOTICE OF INTENTION TO PLUG WELL		NOTICE OF INTENTION TO PLUG BACK	<input checked="" type="checkbox"/>	NOTICE OF INTENTION TO SET LINER	
NOTICE OF INTENTION TO SQUEEZE		NOTICE OF INTENTION TO ACIDIZE		NOTICE OF INTENTION TO SHOOT (Nitro)	
NOTICE OF INTENTION TO GUN PERFORATE		NOTICE OF INTENTION (OTHER) Fracture treat	<input checked="" type="checkbox"/>	NOTICE OF INTENTION (OTHER)	

OIL CONSERVATION COMMISSION
SANTA FE, NEW MEXICO

Hobbs, New Mexico
(Place)

May 28, 1956
(Date)

Gentlemen:

Following is a Notice of Intention to do certain work as described below at the.....

Gulf Oil Corporation **W. A. Ramsay "A"** Well No. **10** in **H** (Unit)
(Company or Operator)
NE $\frac{1}{4}$ **SW** $\frac{1}{4}$ of Sec. **35**, T. **21-S**, R. **36-E**, NMPM., **Arrowhead** Pool
(40-acre Subdivision)
Lea County.

FULL DETAILS OF PROPOSED PLAN OF WORK
(FOLLOW INSTRUCTIONS IN THE RULES AND REGULATIONS)

In order to increase production it is proposed to plug back and fracture treat as follows:

1. Pull tubing, rods and pump.
2. Run steel line measurement. Clean out with sand pump if necessary.
3. Plug back with Hydromite to 3865'
4. Run 2-7/8" tubing with Lynes self-anchoring packer set at approximately 3785'. Treat formation below packer with 10,000 gallons gelled lease oil with 1# sand per gallon. Swab and test.
5. Pull tubing and packer. Rerun tubing, rods and pump and return well to production.

Approved..... **MAY 31 1956**, 19.....
Except as follows:

Approved
OIL CONSERVATION COMMISSION
By..... *[Signature]* ..
Title..... **Engineer District 1** ..

Gulf Oil Corporation
Company or Operator
By..... *[Signature]* ..
Position..... **Area Supt. of Prod.** ..
Send Communications regarding well to:
Name..... **Gulf Oil Corporation** ..
Address..... **Box 2167, Hobbs, New Mexico** ..