

Submit 3 Copies
to Appropriate
District Office

1

State of New Mexico
Energy, Minerals and Natural Resources Department
OIL CONSERVATION DIVISION

P.O. Box 2088
Santa Fe, New Mexico 87504-2088

Form C-103
Revised 1-1-89

DISTRICT I

P.O. Box 1980, Hobbs, NM 88240

DISTRICT II

P.O. Drawer Dd, Artesia, NM 88210

DISTRICT III

1000 Rio Brazos Rd., Aztec, Nm 87410

API NO. (assigned by OCD on New Wells)

30-025-04920

5. Indicate Type of Lease
STATE ☒ FEE ☐

6. State Oil & Gas Lease No.

N/A

7. Lease Name or Unit Agreement Name

ARROWHEAD GRAYBURG UNIT

8. Well No.

134

9. Pool name or Wildcat

ARROWHEAD/GB

SUNDRY NOTICES AND REPORTS ON WELLS
(DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK
DIFFERENT RESERVOIR. USE "APPLICATION FOR PERMIT"
(FORM C-101) FOR SUCH PROPOSALS.)

1. Type of Well:

OIL WELL ☐ GAS WELL ☐ OTHER INJECTOR

2. Name of Operator

CHEVRON U.S.A. INC.

3. Address of Operator

(915) 687-7436

P.O. BOX 1150 MIDLAND, TX 79702 ATTN: NITA RICE

4. Well Location

Unit Letter I : 1980 Feet From The SOUTH Line and 660 Feet From The EAST Line
Section 35 Township 21S Range 36E NMPM LEA County

10. Elevation (Show whether DF, RKB, RT, GR, etc.)

3563'GR

11

Check Appropriate Box to Indicate Nature of Notice, Report, or Other Data

NOTICE OF INTENTION TO:

PERFORM REMEDIAL WORK ☐ PLUG AND ABANDON ☐
TEMPORARILY ABANDON ☐ CHANGE PLANS ☐
PULL OR ALTER CASING ☐
OTHER: ☐

SUBSEQUENT REPORT OF:

REMEDIAL WORK ☐ ALTER CASING ☐
COMMENCE DRILLING OPNS. ☐ PLUG AND ABAN. ☐
CASING TEST AND CMT JOB ☒
OTHER: DEEPEN 70', ACDZ, & PERF ☒

& CONVERT TO WTR INJ

12. Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, including
estimated date of starting any proposed work) SEE RULE 1103.

WORK PERFORMED 2-8 THRU 2-26-93

MIRU, POH & LD RODS & PMP. ND WH. NU BOP. POH & LD PROD TBG. CSG LEAK 262-870'
RIH W/BIT & DEEPEN WELL 70' W/AIR TO 3930'. CIRC CLEAN. RUN LOGS, GR 3934 - SURF
RUN DSN LOG 3934-3750', SDL 3934-3769', CALIPER 3934-3749. RIH & UNDER REAM CSG
3779-3933'. CIRC CLEAN. SET RBP @ 1000', CIRC DN 5-1/2 CSG & UP 9-5/8 CSG. ND
BOP, C/O WH, NU BOP. RUN 4-1/2 LINER, SET @ 3927'. PMP 200 SX CMT, TAIL W/100 SX CMT.
CIRC BETWEEN 4-1/2 & 5-1/2, 25% RTNS, CMT DID NOT CIRC. . FLOAT COLLAR HELD.
ND WH, MAKE CUT OFF, NU WH. TST TO 2000#. NU BOP. RUN TEMP LOG, DRL CMT 3598-3925'.
CIRC CLEAN. PERF 3920-3885, 2 JHPF, TTL 38 HOLES. ACDZ W/8 BBLS, PERF 3741-3877'
2 JHPF, TOTAL 92 HOLES. ACDZ W/17 BBLS 15% NEFE HCL .SWAB BACK LOAD.
SET PKR @ 3680', ND BOP. NU WH. TST CSG TO 560#, PLACE WELL ON INJECTION

I hereby certify that the information above is true and complete to the best of my knowledge and belief.

SIGNATURE

Nita Rice

TITLE

TECHNICAL ASSITANT

DATE:

3/3/93

TYPE OR PRINT NAME

NITA RICE

TELEPHONE NO. (915)687-7436

APPROVED BY

Orig. Signed by
Paul Kantz
Geologist

TITLE

DATE

1993 03 10

CONDITIONS OF APPROVAL

8

