

NO. OF COPIES RECEIVED	
DISTRIBUTION	
SANTA FE	
FILE	
U.S.G.S.	
LAND OFFICE	
OPERATOR	

NEW MEXICO OIL CONSERVATION COMMISSION

Form C-103  
Supersedes Old  
C-102 and C-103  
Effective 1-1-65

<b>SUNDRY NOTICES AND REPORTS ON WELLS</b> <small>(DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A DIFFERENT RESERVOIR. USE "APPLICATION FOR PERMIT -" (FORM C-101) FOR SUCH PROPOSALS.)</small>		5a. Indicate Type of Lease State <input type="checkbox"/> Fee <input checked="" type="checkbox"/>
		5. State Oil & Gas Lease No.
1. OIL WELL <input type="checkbox"/> GAS WELL <input checked="" type="checkbox"/> OTHER <input type="checkbox"/>	7. Unit Agreement Name	
2. Name of Operator <b>Sohio Petroleum Company</b>	8. Farm or Lease Name <b>Mae F. Currie</b>	
3. Address of Operator <b>P. O. Box 3000, Midland, TX 79701</b>	9. Well No. <b>1</b>	
4. Location of Well UNIT LETTER <b>I</b> <b>1980</b> FEET FROM THE <b>South</b> LINE AND <b>660</b> FEET FROM THE <b>East</b> LINE, SECTION <b>7</b> TOWNSHIP <b>21 S</b> RANGE <b>37 E</b> NMPM.	10. Field and Pool, or Wildcat <b>Eumont Queen (Gas)</b>	
15. Elevation (Show whether DF, RT, GR, etc.)		12. County <b>Lea</b>

16. Check Appropriate Box To Indicate Nature of Notice, Report or Other Data

NOTICE OF INTENTION TO:		SUBSEQUENT REPORT OF:	
PERFORM REMEDIAL WORK <input type="checkbox"/>	PLUG AND ABANDON <input type="checkbox"/>	REMEDIAL WORK <input type="checkbox"/>	ALTERING CASING <input type="checkbox"/>
TEMPORARILY ABANDON <input type="checkbox"/>	CHANGE PLANS <input type="checkbox"/>	COMMENCE DRILLING OPNS. <input type="checkbox"/>	PLUG AND ABANDONMENT <input checked="" type="checkbox"/>
PULL OR ALTER CASING <input type="checkbox"/>	OTHER <input type="checkbox"/>	CASING TEST AND CEMENT JOB <input type="checkbox"/>	
		OTHER _____ <input type="checkbox"/>	

17. Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work) SEE RULE 1103.

Loaded hole w/9 1/2" mud, set BP @ 3550' w/35' of cement on top. Shot off casing @ 1536' and pulled 37 jts. of 7" 20# casing. Spotted 100' cement plug 50' in and 50' out of 7" casing. Spotted cement plug at 1225' to 1395' and 10 sacks at surface. 8 5/8" surface pipe cut off 3' below ground level with permanent marker installed. Location leveled and cleaned up.

Plug and abandonment operations started 7-8-75 and completed 7-10-75.

Casing left in hole:

7" - 2154' from 1536' to 3690'  
8 5/8" - 1272' from 3' to 1275'

18. I hereby certify that the information above is true and complete to the best of my knowledge and belief.

SIGNED *J. Swanson* TITLE District Superintendent DATE July 23, 1975

APPROVED BY *John W. Runyan* TITLE Assistant DATE FEB 4 1976

CONDITIONS OF APPROVAL, IF ANY: