## TICO OIL CONSERVATION COMMIS

Santa Fe, New Mexico

(Form C-104) Revised 7/1/57

## REQUEST FOR (OIL) -

This form shall be submitted by the operator before an initial allowable will be assigned to any completed Oil or Gas well.

Recompletion

	die "c	ZK WIII	o. Qui iiiu	be reported on 15.025 psia at 60			New Mexico	Apr	pril 19, 1962	
E AR	HER	EBY R	EQUESTI	ng an allo	KANGE E	Boyalth	LL KNOWN A	S:		
	l	_		rporation, (						
3	Compai	ıy or Op Sec.	erator)	T. 218	(Lease)	M NMF	M	Linebry		Poo
Umit	Letter	,		_	OK	-92_49		D.: 4334 6		L_17_62
Les				County. Date Elevation	3844° B	DB	. Total Depth	6684	PBTD	66751
Please indicate location:				Top Oil/Gas Pa	5 <u>5</u>	ET to	Name of Prod.	6684 PBTD 6675 Form.		
D	C B		Å	PRODUCING INTE					-	
				Perforations 5814'-5950' various intervals w/4 JSPF						
E	F	G	н	Open Hole			Depth Casing Shoe	6684	Depth Tubing	57921
		*		OIL WELL TEST						
L	K	J	I			bbls.oi	1,bbl	s water in	hrs.	Choke min. Size
İ							t (after recover			
M	N	0	P	load oil used	90	hhls.oi).	O bbls wa	ter in 24	hrs.	Choke 5/
į										
980	PER	Lines	L	GAS WELL TEST			imp /n D	£1 3	Chala C	4
. <del></del>	<del>,</del>		enting Reco	•			MCF/Day; Hours			.1 ze
Size		Feet	Sax				ure, etc.):			lowed
				7			9:			
3-3/	84	248	225				W 40 .			
9-5/	8" 3	860	1500				unts of material			ater, oil, and
		744	(00	sand): 1500 Casing 180	Tubing	none Dat	20,000 oil e first new	4-11-6		
7	,	684	600	Press.	Press:	oil	run to tanks			
2	9	792		Oil Transporte		none	pe Line Co.		<del>,</del>	
	Desa 1	w/ax	isting I	Gas Transport	[r		والمراقبة والمساورة والمساورة والمساولة والمساولة والمساولة والمساولة والمساولة والمساولة والمساولة			
marks				1		7 . 7	• • • • • • • • • • • • • • • • • • •		••••••	******************
·····		••••	•••••			./				•••••••
	• • • • • • • • • • • • • • • • • • • •									•••••
				ormation given a		e and com	American Pe	treleum	Corporati	ion
prove	d			******	, 19		Original Sign	**********	***************************************	
	OIL C	ONSE	RVATION	COMMISSIO	N	Ву:	v. e.	**************************************		
						•	<u> </u>	(Signature		
·	20				**********	Title	Area Super Send Commu		, <del></del>	ll to:
							SANG L AMIMI	mications N	THUILD WE	

Address... Box 66 - Hobbs, New Mexico