

OIL CONSERVATION DIVISION
P. O. BOX 2088
SANTA FE, NEW MEXICO 87501

NO. OF COPIES RECEIVED	
DISTRIBUTION	
SANTA FE	
FILE	
U.F.G.S.	
LAND OFFICE	
OPERATOR	

5a. Indicate Type of Lease
State For

5. State Oil & Gas Lease No.
E-5890

SUMMARY NOTICES AND REPORTS ON WELLS
(DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A DIFFERENT RESERVOIR. USE "APPLICATION FOR PERMIT" (FORM C-101) FOR SUCH PROPOSALS.)

1. OIL WELL GAS WELL OTHER

2. Name of Operator
Wilson Oil Company

3. Address of Operator
P. O. Box 1297 - Santa Fe, New Mexico 87501

4. Location of Well
UNIT LETTER **K** **1847** FEET FROM THE **West** LINE AND **1980** FEET FROM THE **South** LINE, SECTION **19** TOWNSHIP **21-S** RANGE **35-E** N.M.P.M.

7. Unit Agreement Name

8. Farm or Lease Name
Leonard State

9. Well No.
1

10. Field and Pool, or Wildcat
Wilson Bone Springs

11. Elevation (Show whether DF, RT, GR, etc.)
3645 GR

12. County
Lea

Check Appropriate Box To Indicate Nature of Notice, Report or Other Data

NOTICE OF INTENTION TO:		SUBSEQUENT REPORT OF:	
PERFORM REMEDIAL WORK <input type="checkbox"/>	PLUG AND ABANDON <input checked="" type="checkbox"/>	REMEDIAL WORK <input type="checkbox"/>	ALTERING CASING <input type="checkbox"/>
TEMPORARILY ABANDON <input type="checkbox"/>	CHANGE PLANS <input type="checkbox"/>	COMMENCE DRILLING OPNS. <input type="checkbox"/>	PLUG AND ABANDONMENT <input type="checkbox"/>
PULL OR ALTER CASING <input type="checkbox"/>	OTHER <input type="checkbox"/>	CASING TEST AND CEMENT JOB <input type="checkbox"/>	OTHER <input type="checkbox"/>

17. Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work; SEE RULE 1103.

1. Set 35' cement plug on B. P. @ 12,600'.
2. Set B. P. & 35' cement plug @ 9300'.
3. Set 100' cement plug @ 7000'.
4. Set 100' cement plug @ 7" cut-off.
5. Set 100' cement plug @ 5525'- 5625'.
6. Set 100' cement plug @ base of salt.
7. Set 100' cement plug @ top of salt.
8. Take stretch on 9 5/8" casing, if not cemented to surface. Perforate or cut below 13 3/8" shoe and cement.
9. Set 10' cement surface plug and dry hole marker.

THE COMMISSION MUST BE NOTIFIED 24 HOURS BEFORE THE BEGINNING OF DRILLING OPERATIONS FOR THE C-103 TO BE APPROVED.

18. I hereby certify that the information above is true and complete to the best of my knowledge and belief.

SIGNED *Robert D. Service* TITLE *Robert Well Service* DATE *5-12-81*

APPROVED BY *Arny Sexton* TITLE _____ DATE _____

CONDITIONS OF APPROVAL, IF ANY: