


Wildcat

SCOUT REPORT NEW MEXICO OIL CONSERVATION COMMISSION



Company *P. L. Hargrave*
 Farm Name *State* Well No. _____
 Sec. _____ Twp. _____ Range _____ County _____
 Feet from Line: N. _____ S. _____ E. _____ W. _____
 Elevation *3369* Method _____
 Contractor _____
 Spudded *12-5-42* Completed *5-23-47*

AMOUNT CASING & CEMENTING RECORD

Size	Feet	Inches	Sax Cement
<i>13 3/8</i>	<i>190</i>		<i>Set</i>
<i>12 1/2</i>	<i>305</i>		<i>Set</i>
<i>9"</i>	<i>2308</i>		<i>Set</i>

TUBING RECORD

PACKER

ACID RECORD Gals.	TA	TG
		TX
	TCA	TGI
	BX	TYo
	TY	TABo
	TSR	TPenn
Top Pay	TQ	TOrd

SHOOTING RECORD

No. of Quarts	From	To
<i>S/ W 4447-55</i>	<i>S/</i>	<i>S/</i>
<i>S/</i>	<i>S/</i>	<i>S/</i>
<i>S/</i>	<i>S/</i>	<i>S/</i>

Date		Date	
<i>12-18</i>	<i>FD 17 3/8</i>	<i>2-26</i>	<i>FD 2315 X</i>
<i>1-8</i>	<i>FD Repairs</i>	<i>3-5</i>	<i>FD 2315 X</i>
<i>1-15</i>	<i>FD 240 RB Prep to under</i>	<i>3-12</i>	<i>FD</i>
	<i>ream.</i>	<i>4-1</i>	<i>FD 2335 X</i>
<i>1-22</i>	<i>FD 460 RB</i>	<i>4-9</i>	<i>FD 2335 X</i>
<i>1-29</i>	<i>FD 810 RB</i>	<i>4-16</i>	<i>FD 3055 X</i>
<i>2-5</i>	<i>FD 1240 RB</i>	<i>4-23</i>	<i>FD 3750</i>
<i>2-12</i>	<i>FD 1475 RB</i>	<i>4-30</i>	<i>FD 3915 X</i>
		<i>5-7</i>	<i>FD 4137 X</i>
		<i>5-12</i>	<i>FD 4322 X</i>

529 ID 44552 Hal full - 140