Office	State of New Mexico	Form C-103
District Eergy	, Minerals and Natural Resourc	
1625 N. French Dr., Hobbs, NM 88240		WELL API NO.
District II 811 South First, Artesia, NM 88210 OIL CONSERVATION DIVISION		30-025-09082
District III 1220 South St. Francis Dr.		5. Indicate Type of Lease
1000 Rio Brazos Rd., Aztec, NM 87410		STATE 🗆 FEE 📈
<u>District IV</u> 1220 S. St. Francis Dr., Santa Fe, NM	Santa Fe, INIVI 8/303	6. State Oil & Gas Lease No.
87505		
SUNDRY NOTICES AND RE	EPORTS ON WELLS	7. Lease Name or Unit Agreement Name:
(DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A		A Lease Name of Ont Agreement Name.
DIFFERENT RESERVOIR. USE "APPLICATION FOR PE	RMIT" (FORM C-101) FOR SUCH	SOUTH EUNICE UNIT
PROPOSALS.) 1. Type of Well:		SOOTH EGINEE GIVIT
	DUECTION	
Oil Well Gas Well Other 2. Name of Operator	INJECTION	
BRECK OPERATING CORP.		8. Well No.
		45
3. Address of Operator		9. Pool name or Wildcat
P.O. BOX 911, BRECKENRIDGE, TEXAS 76424 4. Well Location		EUNICE 7 RIVERS QUEEN, SO
4. Well Location		
Hair Laws W 1000		
Unit Letter K: 1980 f	eet from the <u>SOUTH</u> line a	and 1980 feet from the WEST line
Section 28 Towns	hi- 220 P. 26P	N (B) (
	hip 22S Range 36E	NMPM LEA County
10. Elevati	on (Show whether DR, RKB, RT, C	iR, etc.)
11 01 1 4	N	
11. Check Appropriate I	Box to Indicate Nature of No	
NOTICE OF INTENTION		SUBSEQUENT REPORT OF:
PERFORM REMEDIAL WORK PLUG AND A	ABANDON 🖾 REMEDIAL	WORK ☐ ALTERING CASING ☐
<u>_</u>		
TEMPORARILY ABANDON	ANS COMMENC	E DRILLING OPNS. PLUG AND
		ABANDONMENT L
DIII OD 41 TED 04 014 0	— la.a	
PULL OR ALTER CASING MULTIPLE	CASING TE	ST AND
PULL OR ALTER CASING MULTIPLE COMPLETIC		ST AND
COMPLETIC	ON CEMENT JO	ST AND
OTHER:	ON CEMENT JO OTHER:	ST AND DB
OTHER: 12. Describe proposed or completed operations.	ON CEMENT JO OTHER: (Clearly state all pertinent details,	ST AND DB and give pertinent dates, including estimated date
OTHER: 12. Describe proposed or completed operations. of starting any proposed work). SEE RULE 1	ON CEMENT JO OTHER: (Clearly state all pertinent details,	ST AND DB
OTHER: 12. Describe proposed or completed operations.	ON CEMENT JO OTHER: (Clearly state all pertinent details,	ST AND DB and give pertinent dates, including estimated date
OTHER: 12. Describe proposed or completed operations. of starting any proposed work). SEE RULE 1	ON CEMENT JO OTHER: (Clearly state all pertinent details,	ST AND DB and give pertinent dates, including estimated date
OTHER: 12. Describe proposed or completed operations. of starting any proposed work). SEE RULE 1 or recompilation.	CEMENT JO OTHER: (Clearly state all pertinent details, 1103. For Multiple Completions:	and give pertinent dates, including estimated date Attach wellbore diagram of proposed completion
OTHER: 12. Describe proposed or completed operations. of starting any proposed work). SEE RULE 1 or recompilation. CURRENT WELL CONDITIONS:	ON CEMENT JO OTHER: (Clearly state all pertinent details, 1103. For Multiple Completions: PROPOSED	and give pertinent dates, including estimated date Attach wellbore diagram of proposed completion
OTHER: 12. Describe proposed or completed operations. of starting any proposed work). SEE RULE 1 or recompilation. CURRENT WELL CONDITIONS: 1. 8-5/8" @ 298' cemented w/250 sxs cement circ	CEMENT JO OTHER: (Clearly state all pertinent details, 1103. For Multiple Completions: PROPOSED 1. Spot 35' of the completion of the c	and give pertinent dates, including estimated date Attach wellbore diagram of proposed completion
OTHER: 12. Describe proposed or completed operations. of starting any proposed work). SEE RULE 1 or recompilation. CURRENT WELL CONDITIONS: 1. 8-5/8" @ 298' cemented w/250 sxs cement circ 2. 5-1/2" @ 3816' cemented w/450 sxs cement circ	CEMENT JO OTHER: (Clearly state all pertinent details, 1103. For Multiple Completions: PROPOSED 1. Spot 35' c 2. Circulate I	and give pertinent dates, including estimated date Attach wellbore diagram of proposed completion
OTHER: 12. Describe proposed or completed operations. of starting any proposed work). SEE RULE 1 or recompilation. CURRENT WELL CONDITIONS: 1. 8-5/8" @ 298' cemented w/250 sxs cement circ 2. 5-1/2" @ 3816' cemented w/450 sxs cement circ 3. 3-1/2" fiberglass liner 3335'-3644' cemented w/450 sxs	CEMENT JO OTHER: (Clearly state all pertinent details, 1103. For Multiple Completions: PROPOSED 1. Spot 35' c 2. Circulate 1 7100 sxs 3. Spot 25 sx	and give pertinent dates, including estimated date Attach wellbore diagram of proposed completion
OTHER: 12. Describe proposed or completed operations. of starting any proposed work). SEE RULE 1 or recompilation. CURRENT WELL CONDITIONS: 1. 8-5/8" @ 298' cemented w/250 sxs cement circ 2. 5-1/2" @ 3816' cemented w/450 sxs cement circ 3. 3-1/2" fiberglass liner 3335'-3644' cemented w/4. Perfs 3652'-3790'	CEMENT JO OTHER: (Clearly state all pertinent details, 1103. For Multiple Completions: PROPOSED 1. Spot 35' c 2. Circulate I 7100 sxs 3. Spot 25 sx 4. Spot 35 sx	and give pertinent dates, including estimated date Attach wellbore diagram of proposed completion
OTHER: 12. Describe proposed or completed operations. of starting any proposed work). SEE RULE 1 or recompilation. CURRENT WELL CONDITIONS: 1. 8-5/8" @ 298' cemented w/250 sxs cement circ 2. 5-1/2" @ 3816' cemented w/450 sxs cement circ 3. 3-1/2" fiberglass liner 3335'-3644' cemented w/450 sxs	CEMENT JO CEMENT JO OTHER: (Clearly state all pertinent details, 1103. For Multiple Completions: PROPOSED 1. Spot 35' c 2. Circulate I 7100 sxs 3. Spot 25 sx 4. Spot 35 sx 5. Install dry	and give pertinent dates, including estimated date Attach wellbore diagram of proposed completion
OTHER: 12. Describe proposed or completed operations. of starting any proposed work). SEE RULE 1 or recompilation. CURRENT WELL CONDITIONS: 1. 8-5/8" @ 298' cemented w/250 sxs cement circ 2. 5-1/2" @ 3816' cemented w/450 sxs cement circ 3. 3-1/2" fiberglass liner 3335'-3644' cemented w/4. Perfs 3652'-3790' 5. RBP @ 3325'	CEMENT JO OTHER: (Clearly state all pertinent details, 1103. For Multiple Completions: PROPOSED 1. Spot 35' c 2. Circulate I 7100 sxs 3. Spot 25 sx 4. Spot 35 sx 5. Install dry	and give pertinent dates, including estimated date Attach wellbore diagram of proposed completion
OTHER: 12. Describe proposed or completed operations. of starting any proposed work). SEE RULE 1 or recompilation. CURRENT WELL CONDITIONS: 1. 8-5/8" @ 298' cemented w/250 sxs cement circ 2. 5-1/2" @ 3816' cemented w/450 sxs cement circ 3. 3-1/2" fiberglass liner 3335'-3644' cemented w/4. Perfs 3652'-3790' 5. RBP @ 3325' THE COMMISSION MUST BE	CEMENT JO CEMENT JO OTHER: (Clearly state all pertinent details, 1103. For Multiple Completions: PROPOSED 1. Spot 35 oc. 2. Circulate I 7100 sxs 3. Spot 25 sx 4. Spot 35 sx 5. Install dry 6. Clean Loc	and give pertinent dates, including estimated date Attach wellbore diagram of proposed completion
OTHER: 12. Describe proposed or completed operations. of starting any proposed work). SEE RULE 1 or recompilation. CURRENT WELL CONDITIONS: 1. 8-5/8" @ 298' cemented w/250 sxs cement circ 2. 5-1/2" @ 3816' cemented w/450 sxs cement circ 3. 3-1/2" fiberglass liner 3335'-3644' cemented w/4. Perfs 3652'-3790' 5. RBP @ 3325' THE COMMISSION MUST BE HOURS PRIOR TO THE BEC	CEMENT JO CEMENT JO OTHER: (Clearly state all pertinent details, 1103. For Multiple Completions: PROPOSED 1. Spot 35' c 2. Circulate I 7100 sxs 3. Spot 25 sx 4. Spot 35 sx 5. Install dry 6. Clean Loce SINNING OF	and give pertinent dates, including estimated date Attach wellbore diagram of proposed completion
OTHER: 12. Describe proposed or completed operations. of starting any proposed work). SEE RULE 1 or recompilation. CURRENT WELL CONDITIONS: 1. 8-5/8" @ 298' cemented w/250 sxs cement circ 2. 5-1/2" @ 3816' cemented w/450 sxs cement circ 3. 3-1/2" fiberglass liner 3335'-3644' cemented w/4. Perfs 3652'-3790' 5. RBP @ 3325' THE COMMISSION MUST BE	CEMENT JO CEMENT JO OTHER: (Clearly state all pertinent details, 1103. For Multiple Completions: PROPOSED 1. Spot 35' c 2. Circulate I 7100 sxs 3. Spot 25 sx 4. Spot 35 sx 5. Install dry 6. Clean Loce SINNING OF	and give pertinent dates, including estimated date Attach wellbore diagram of proposed completion
OTHER: 12. Describe proposed or completed operations. of starting any proposed work). SEE RULE 1 or recompilation. CURRENT WELL CONDITIONS: 1. 8-5/8" @ 298' cemented w/250 sxs cement circ 2. 5-1/2" @ 3816' cemented w/450 sxs cement circ 3. 3-1/2" fiberglass liner 3335'-3644' cemented w/4. Perfs 3652'-3790' 5. RBP @ 3325' THE COMMISSION MUST BE HOURS PRIOR TO THE BEC PLUGGING OPERATIONS FO TO BE APPROVED.	CEMENT JO OTHER: (Clearly state all pertinent details, 1103. For Multiple Completions: PROPOSED 1. Spot 35' c 2. Circulate I 3. Spot 25 sx 4. Spot 35 sx 5. Install dry 6. Clean Loc OR THE C-103	and give pertinent dates, including estimated date Attach wellbore diagram of proposed completion PLUGGING PROCEDURE: ement on RBP @ 332.5 / hole w/mud a plug 1450'-1700' a plug 350'- Surface — TAS hole marker eation
OTHER: 12. Describe proposed or completed operations. of starting any proposed work). SEE RULE 1 or recompilation. CURRENT WELL CONDITIONS: 1. 8-5/8" @ 298' cemented w/250 sxs cement circ 2. 5-1/2" @ 3816' cemented w/450 sxs cement circ 3. 3-1/2" fiberglass liner 3335'-3644' cemented w/4. Perfs 3652'-3790' 5. RBP @ 3325' THE COMMISSION MUST BE HOURS PRIOR TO THE BECOMPLIED OPERATIONS FOR TO THE BECOMPLIED OF THE BECOM	CEMENT JO OTHER: (Clearly state all pertinent details, 1103. For Multiple Completions: PROPOSED 1. Spot 35' c 2. Circulate I 3. Spot 25 sx 4. Spot 35 sx 5. Install dry 6. Clean Loc OR THE C-103	and give pertinent dates, including estimated date Attach wellbore diagram of proposed completion PLUGGING PROCEDURE: The ment on RBP @ 3325' Thole w/mud To plug 1450'-1700' To plug 350'- Surface TAS Thole marker Thole marker Thought the marker Thought the marker of
OTHER: 12. Describe proposed or completed operations. of starting any proposed work). SEE RULE 1 or recompilation. CURRENT WELL CONDITIONS: 1. 8-5/8" @ 298' cemented w/250 sxs cement circ 2. 5-1/2" @ 3816' cemented w/450 sxs cement circ 3. 3-1/2" fiberglass liner 3335'-3644' cemented w/4. Perfs 3652'-3790' 5. RBP @ 3325' THE COMMISSION MUST BE HOURS PRIOR TO THE BEC PLUGGING OPERATIONS FO TO BE APPROVED.	CEMENT JO OTHER: (Clearly state all pertinent details, 1103. For Multiple Completions: PROPOSED 1. Spot 35' c 2. Circulate I 3. Spot 25 sx 4. Spot 35 sx 5. Install dry 6. Clean Loc OR THE C-103	and give pertinent dates, including estimated date Attach wellbore diagram of proposed completion PLUGGING PROCEDURE: ement on RBP @ 332.5 / hole w/mud a plug 1450'-1700' a plug 350'- Surface — TAS hole marker eation
OTHER: 12. Describe proposed or completed operations. of starting any proposed work). SEE RULE 1 or recompilation. CURRENT WELL CONDITIONS: 1. 8-5/8" @ 298' cemented w/250 sxs cement circ 2. 5-1/2" @ 3816' cemented w/450 sxs cement circ 3. 3-1/2" fiberglass liner 3335'-3644' cemented w/4. Perfs 3652'-3790' 5. RBP @ 3325' THE COMMISSION MUST BE HOURS PRIOR TO THE BEC PLUGGING OPERATIONS FO TO BE APPROVED.	CEMENT JO OTHER: (Clearly state all pertinent details, 1103. For Multiple Completions: PROPOSED 1. Spot 35' c 2. Circulate I 7100 sxs 3. Spot 25 sx 4. Spot 35 sx 5. Install dry 6. Clean Loc OR THE C-103	and give pertinent dates, including estimated date Attach wellbore diagram of proposed completion PLUGGING PROCEDURE: The ment on RBP @ 3325 / Thole w/mud To plug 1450'-1700' To plug 350'- Surface TAB Thole marker Thomas and belief.
OTHER: 12. Describe proposed or completed operations. of starting any proposed work). SEE RULE 1 or recompilation. CURRENT WELL CONDITIONS: 1. 8-5/8" @ 298' cemented w/250 sxs cement circ 2. 5-1/2" @ 3816' cemented w/450 sxs cement circ 3. 3-1/2" fiberglass liner 3335'-3644' cemented w/4. Perfs 3652'-3790' 5. RBP @ 3325' THE COMMISSION MUST BE HOURS PRIOR TO THE BEC PLUGGING OPERATIONS FO TO BE APPROVED. I hereby certify that the information above is true a SIGNATURE	CEMENT JO OTHER: (Clearly state all pertinent details, 1103. For Multiple Completions: PROPOSED 1. Spot 35' c 2. Circulate I 7100 sxs 3. Spot 25 sx 4. Spot 35 sx 5. Install dry 6. Clean Loc OR THE C-103	and give pertinent dates, including estimated date Attach wellbore diagram of proposed completion PLUGGING PROCEDURE: The ment on RBP @ 3325' Thole w/mud To plug 1450'-1700' To plug 350'- Surface TAB Thole marker Thou the marker Thou th
OTHER: 12. Describe proposed or completed operations. of starting any proposed work). SEE RULE 1 or recompilation. CURRENT WELL CONDITIONS: 1. 8-5/8" @ 298' cemented w/250 sxs cement circ 2. 5-1/2" @ 3816' cemented w/450 sxs cement circ 3. 3-1/2" fiberglass liner 3335'-3644' cemented w/4. Perfs 3652'-3790' 5. RBP @ 3325' THE COMMISSION MUST BE HOURS PRIOR TO THE BEC PLUGGING OPERATIONS FO TO BE APPROVED.	CEMENT JO OTHER: (Clearly state all pertinent details, 103. For Multiple Completions: PROPOSED 1. Spot 35' c 2. Circulate I 3. Spot 25 sx 4. Spot 35 sx 5. Install dry 6. Clean Loce PRINING OF PRINE C-103 And complete to the best of my known of the complete state of the	and give pertinent dates, including estimated date Attach wellbore diagram of proposed completion PLUGGING PROCEDURE: The ment on RBP @ 3325 / Thole w/mud To plug 1450'-1700' To plug 350'- Surface TAB Thole marker Thomas and belief.
OTHER: 12. Describe proposed or completed operations. of starting any proposed work). SEE RULE 1 or recompilation. CURRENT WELL CONDITIONS: 1. 8-5/8" @ 298' cemented w/250 sxs cement circ 2. 5-1/2" @ 3816' cemented w/450 sxs cement circ 3. 3-1/2" fiberglass liner 3335'-3644' cemented w/4. Perfs 3652'-3790' 5. RBP @ 3325' THE COMMISSION MUST BE HOURS PRIOR TO THE BEC PLUGGING OPERATIONS FO TO BE APPROVED. I hereby certify that the information above is true a SIGNATURE	CEMENT JO OTHER: (Clearly state all pertinent details, 103. For Multiple Completions: PROPOSED 1. Spot 35' c 2. Circulate I 3. Spot 25 sx 4. Spot 35 sx 5. Install dry 6. Clean Loce PRINING OF PRINE C-103 And complete to the best of my known of the complete state of the	and give pertinent dates, including estimated date Attach wellbore diagram of proposed completion PLUGGING PROCEDURE: ement on RBP @ 3325' hole w/mud a plug 1450'-1700' a plug 350'- Surface TAS hole marker ation pwledge and belief. ING TECHNICIAN DATE April 4, 2002
OTHER: 12. Describe proposed or completed operations. of starting any proposed work). SEE RULE is or recompilation. CURRENT WELL CONDITIONS: 1. 8-5/8" @ 298' cemented w/250 sxs cement circ 2. 5-1/2" @ 3816' cemented w/450 sxs cement circ 3. 3-1/2" fiberglass liner 3335'-3644' cemented w/4. Perfs 3652'-3790' 5. RBP @ 3325' THE COMMISSION MUST BE HOURS PRIOR TO THE BEC PLUGGING OPERATIONS FO TO BE APPROVED. I hereby certify that the information above is true a SIGNATURE Type or print name ERNIE UNDERWOOD	CEMENT JO OTHER: (Clearly state all pertinent details, 103. For Multiple Completions: PROPOSED 1. Spot 35' c 2. Circulate J 3. Spot 25 sx 4. Spot 35 sx 5. Install dry 6. Clean Loc FOR THE C-103 And complete to the best of my known of the Complete State of Title ENGINEER	and give pertinent dates, including estimated date Attach wellbore diagram of proposed completion PLUGGING PROCEDURE: The sement on RBP @ 332.5 / Thole w/mud To plug 1450'-1700' To plug 350'- Surface TAS Thole marker Thou wellbore diagram of proposed completion The sement on RBP @ 332.5 / Thou wellbore diagram of proposed completion Thou well be a second of the wellbore diagram of proposed completion Thou well be a second of the wellbore diagram of proposed completion Thou well be a second of the wellbore diagram of proposed completion Thou well be a second of the wellbore diagram of proposed completion Thou well be a second of the well be a second of the wellbore diagram of the wellbo
OTHER: 12. Describe proposed or completed operations. of starting any proposed work). SEE RULE is or recompilation. CURRENT WELL CONDITIONS: 1. 8-5/8" @ 298' cemented w/250 sxs cement circ 2. 5-1/2" @ 3816' cemented w/450 sxs cement circ 3. 3-1/2" fiberglass liner 3335'-3644' cemented w/4. Perfs 3652'-3790' 5. RBP @ 3325' THE COMMISSION MUST BE HOURS PRIOR TO THE BEC PLUGGING OPERATIONS FO TO BE APPROVED. I hereby certify that the information above is true a SIGNATURE Type or print name ERNIE UNDERWOOD	CEMENT JO OTHER: (Clearly state all pertinent details, 1103. For Multiple Completions: PROPOSED 1. Spot 35' c 2. Circulate I 7100 sxs 3. Spot 25 sx 4. Spot 35 sx 5. Install dry 6. Clean Loc FOR THE C-103 COMPLETE ENGINEER	and give pertinent dates, including estimated date Attach wellbore diagram of proposed completion PLUGGING PROCEDURE: The sement on RBP @ 332.5 / Thole w/mud To plug 1450'-1700' To plug 350'- Surface TAS Thole marker Thou wellbore diagram of proposed completion The sement on RBP @ 332.5 / Thou wellbore diagram of proposed completion Thou well be a second of the wellbore diagram of proposed completion Thou well be a second of the wellbore diagram of proposed completion Thou well be a second of the wellbore diagram of proposed completion Thou well be a second of the wellbore diagram of proposed completion Thou well be a second of the well be a second of the wellbore diagram of the wellbo
OTHER: 12. Describe proposed or completed operations. of starting any proposed work). SEE RULE 1 or recompilation. CURRENT WELL CONDITIONS: 1. 8-5/8" @ 298' cemented w/250 sxs cement circ 2. 5-1/2" @ 3816' cemented w/450 sxs cement circ 3. 3-1/2" fiberglass liner 3335'-3644' cemented w/4. Perfs 3652'-3790' 5. RBP @ 3325' THE COMMISSION MUST BE HOURS PRIOR TO THE BEC PLUGGING OPERATIONS FO TO BE APPROVED. I hereby certify that the information above is true a SIGNATURE Type or print name ERNIE UNDERWOOD (This space for State use)	CEMENT JO OTHER: (Clearly state all pertinent details, 103. For Multiple Completions: PROPOSED 1. Spot 35' c 2. Circulate J 3. Spot 25 sx 4. Spot 35 sx 5. Install dry 6. Clean Loc FOR THE C-103 And complete to the best of my known of the Complete State of Title ENGINEER	and give pertinent dates, including estimated date Attach wellbore diagram of proposed completion PLUGGING PROCEDURE: The ement on RBP @ 3325 / Thole w/mud To plug 1450'-1700' To plug 350'- Surface TAS Thole marker Thole marker Thorefore The proposed completion

J C

T.D. • 3817

CONOCO, INC.
South Eunice Unit #45
1980' FSL & 1980' FWL
Sec. 28, T-22S, R-36E
Lea County, NM

3816' - 5 1/2", 15.5#, Cosing. Cemented w/450 sxs. Circulated.