

UNITED STATES
DEPARTMENT OF THE INTERIOR
BUREAU OF LAND MANAGEMENT

SUBMIT IN TRIPLICATE
(Other instructions on reverse side)

Form approved.
Budget Bureau No. 1004-0135
Expires August 31, 1985

SUNDRY NOTICES AND REPORTS ON WELLS

(Do not use this form for proposals to drill or to deepen or plug back to a different reservoir. Use "APPLICATION FOR PERMIT—" for such proposals.)

1. OIL WELL <input checked="" type="checkbox"/> GAS WELL <input type="checkbox"/> OTHER <input type="checkbox"/>		5. LEASE DESIGNATION AND SERIAL NO. LC-030133B
2. NAME OF OPERATOR Conoco Inc.		6. IF INDIAN, ALLOTTEE OR TRIBE NAME
3. ADDRESS OF OPERATOR P.O. Box 460 - Hobbs, New Mexico 88240		7. UNIT AGREEMENT NAME South Eunice Unit
4. LOCATION OF WELL (Report location clearly and in accordance with any State requirements.* See also space 17 below.) At surface 1980' FSL & 1980' FRL - Unit Letter J		8. FARM OR LEASE NAME South Eunice Unit
14. PERMIT NO. 30-025-09123	15. ELEVATIONS (Show whether DF, RT, GR, etc.)	9. WELL NO. 59
		10. FIELD AND POOL, OR WILDCAT Eunice 7 RVRs Queen S
		11. SEC., T., R., M., OR BLK. AND SURVEY OR AREA 33-22S-36E
		12. COUNTY OR PARISH Lea
		13. STATE NM

16. Check Appropriate Box To Indicate Nature of Notice, Report, or Other Data

NOTICE OF INTENTION TO:		SUBSEQUENT REPORT OF:	
TEST WATER SHUT-OFF <input type="checkbox"/>	PULL OR ALTER CASING <input type="checkbox"/>	WATER SHUT-OFF <input type="checkbox"/>	REPAIRING WELL <input type="checkbox"/>
FRACTURE TREAT <input type="checkbox"/>	MULTIPLE COMPLETE <input type="checkbox"/>	FRACTURE TREATMENT <input type="checkbox"/>	ALTERING CASING <input type="checkbox"/>
SHOOT OR ACIDIZE <input type="checkbox"/>	ABANDON* <input type="checkbox"/>	SHOOTING OR ACIDIZING <input type="checkbox"/>	ABANDONMENT* <input type="checkbox"/>
REPAIR WELL <input type="checkbox"/>	CHANGE PLANS <input type="checkbox"/>	(Other) <input type="checkbox"/>	

(Other) **Clean Out & Acidize**

(NOTE: Report results of multiple completion on Well Completion or Recompletion Report and Log form.)

17. DESCRIBE PROPOSED OR COMPLETED OPERATIONS. Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work. If well is directionally drilled, give subsurface locations and measured and true vertical depths for all markers and zones pertinent to this work.*

- 1) MIRR. POOH w/ rods & pump. Tag for fill with Hg & tally out of hole.
- 2) Clean out to 3790' & POOH. Run CS9 scraper to 3790'.
- 3) Set treating pkr at 3550'. Acidize w/ 90 bbls 15% HCL-FE acid w/ 63 gals Checker-Sol or equivalent inhibited for 24 hrs at 100°F, plus 500 # graded rock salt mixed in 4 bbls gelled 9# brine. Flush w/ 80 bbls 9# brine. Swab well. Release pkr at 3550' & POOH.
- 4) Land SN at 3730'. Run producing equipment & place on test. For further information contact Jay Vashler at 397-5866.

RECEIVED
SEP 15 1988

18. I hereby certify that the foregoing is true and correct

SIGNED **[Signature]** **DF FINNEY** TITLE **Administrative Supervisor** DATE **9/15/88**

APPROVED BY **[Signature]** TITLE _____ DATE **9-22-88**

CONDITIONS OF APPROVAL, IF ANY:

*See instructions on Reverse Side

Section 102 of the Espionage Act, makes it a crime for any person knowingly and willfully to make to any department or agency of the United States any false, fictitious or fraudulent statements or representations as to any matter within its jurisdiction.

BLM-Cadestad (1) Area (2) Amoco (2) (Personal) 7 P.

RECEIVED

SEP 26 1988

OCD
HOBBS OFFICE

1980' FSL & 1980' FEL
 Sec 33, T-22S, R-36E
 Elev: 3496' DF; 0': 10' AGL


Completion History:

8-10-57: Perf 3663'-3779'
 Frac w/ 26,000 gals crude + 1^{1/2} gal sd
 11-6-67: Pump chg
 8-9-80: Pump chg

8^{5/8}" 24^{3/4} J-55
 @ 391' w/ 300 SA
 (circ)

Top Salt : 1460'
 Base Salt : 3044'
 Yates : 3192'
 7R : 3396'
 Queen :

117 jets 2^{3/8}" rbg w/ SM @ 3657'



Made By JDU
 Checked By
 Date 9-3-87
 Page of

Calculation Sheet

South Eunice Unit No 59

Operator NMPU
 State NM