

OIL CONSERVATION DIVISION

P. O. BOX 2088

SANTA FE, NEW MEXICO 87501

Form C-101  
Revised 10-1-79

NO. OF COPIES RECEIVED	
DISTRIBUTION	
SANTA FE	
FILE	
U.S.G.S.	
LAND OFFICE	
OPERATOR	

5a. Indicate Type of Lease  
 State  Fee   
 5. State Oil & Gas Lease No.

SUNDRY NOTICES AND REPORTS ON WELLS  
(DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A DIFFERENT RESERVOIR. USE "APPLICATION FOR PERMIT - L" (FORM C-101) FOR SUCH PROPOSALS.)

1.  OIL WELL  GAS WELL  OTHER-

2. Name of Operator  
Exxon Corporation

3. Address of Operator  
P. O. Box 1600, Midland, TX 79702

4. Location of Well  
 UNIT LETTER A 660 FEET FROM THE North LINE AND 660 FEET FROM  
 THE East LINE, SECTION 11 TOWNSHIP 22-S RANGE 37-E NMPM.

15. Elevation (Show whether DF, RT, GR, etc.)  
3359

7. Unit Agreement Name

8. Farm or Lease Name  
Paddock Unit

9. Well No.  
57

10. Field and Pool, or Wildcat  
Paddock

12. County  
Lea

16. Check Appropriate Box To Indicate Nature of Notice, Report or Other Data

NOTICE OF INTENTION TO:		SUBSEQUENT REPORT OF:	
PERFORM REMEDIAL WORK <input type="checkbox"/>	PLUG AND ABANDON <input type="checkbox"/>	REMEDIAL WORK <input type="checkbox"/>	ALTERING CASING <input type="checkbox"/>
TEMPORARILY ABANDON <input type="checkbox"/>	CHANGE PLANS <input type="checkbox"/>	COMMENCE DRILLING OPNS. <input type="checkbox"/>	PLUG AND ABANDONMENT <input checked="" type="checkbox"/>
PULL OR ALTER CASING <input type="checkbox"/>	OTHER <input type="checkbox"/>	CASING TEST AND CEMENT JOBS <input type="checkbox"/>	
		OTHER _____	

17. Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work) SEE RULE 1103.

1. Pulled rods and tubing.
2. Set CIBP @ 4950', w/10 sx cmt plug on top.
3. Cut 5 1/2" csg at 2655'. Spot 20 sx plug at 3800; 20 sx plug at 3300', and 75 sx plug at 2850'. Tag cmt at 2500'. Spot 70 sx plug at 1200'.
4. Cut and pulled 8 5/8" csg at 500', spot 75 sx plug at 550', top of plug at 440'.  
S Spot 10 sx plug at surface.
5. Install dry hole marker as required by NMOCC.
6. FRW 9-20-79.

18. I hereby certify that the information above is true and complete to the best of my knowledge and belief.

SIGNED C. J. Jackson TITLE Unit Head DATE 11-6-79

APPROVED BY E. W. [Signature] (AAP) TITLE OIL & GAS INSPECTOR DATE AUG 10 1983

CONDITIONS OF APPROVAL, IF ANY: