OIL CONSERVATION COMMISSION

HOBBS, NEW MEXICO

April 12, 1957

R. Olsen Oil Co. Box 691 Jal, New Mex.

Gentlemen:

We are returning Form C-103 showing remedial work on your Danglade No. 2 in Unit P of Section 13, T-22-S, R-37-E without approval because the work outlined on this form does not correspond with the proposed work outlined on Form C-102 which was approved on February 28, 1957.

Further, we would like to have you clarify the following points:

- (1) Were the perforations to 6672*-6740* squeezed off? (shows only 6060*-6333*)
- (2) Is 6060° or 6070° the correct top of perforations?

Yours very truly,

OIL CONSERVATION COMMISSION

E. J. Fischer Engineer, District 1

mc

OIL CONSERVATION COMMISSION

HOBES NEW MEXICO

and the second of the second

1. užje. Br. užž Jaj. Saj

തെ വിശ

insan kundin si ngalak isan dan kanaka kundin sa kabawa kundak, kadi Kabadan

- Commission of the set of the commission of the set of t
- Section for the second report of the second section ()

Contract to Victor

i de la filiation de

n nacht eine Leise Eine ausgroßen generalische

50