

Submit 3 Copies To Appropriate District  
Office  
District I  
1625 N. French Dr., Hobbs, NM 87240  
District II  
811 South First, Artesia, NM 87210  
District III  
1000 Rio Brazos Rd., Aztec, NM 87410  
District IV  
2040 South Pacheco, Santa Fe, NM 87505

State of New Mexico  
Energy, Minerals and Natural Resources

Form C-103  
Revised March 25, 1999

OIL CONSERVATION DIVISION  
2040 South Pacheco  
Santa Fe, NM 87505

WELL API NO. 30-025-10502
5. Indicate Type of Lease STATE <input type="checkbox"/> FEE <input checked="" type="checkbox"/>
6. State Oil & Gas Lease No. LC-058626-A
7. Lease Name or Unit Agreement Name: LANGLIE-MATTIX PENROSE SAND UNIT TRACT 26

<b>SUNDRY NOTICES AND REPORTS ON WELLS</b> (DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A DIFFERENT RESERVOIR. USE "APPLICATION FOR PERMIT" (FORM C-101) FOR SUCH PROPOSALS.)	
1. Type of Well: Oil Well <input checked="" type="checkbox"/> Gas Well <input type="checkbox"/> Other	
2. Name of Operator Anadarko Petroleum Corp.	
3. Address of Operator P.O. Box 2497 Midland, TX 79702	
4. Well Location Unit Letter <u>G</u> : <u>2310</u> feet from the <u>NORTH</u> line and <u>2310</u> feet from the <u>EAST</u> line Section <u>28</u> Township <u>22S</u> Range <u>37E</u> NMPM County <u>LEA</u>	
10. Elevation (Show whether DR, RKB, RT, GR, etc.) N/A	

11. Check Appropriate Box to Indicate Nature of Notice, Report, or Other Data

NOTICE OF INTENTION TO:		SUBSEQUENT REPORT OF:	
PERFORM REMEDIAL WORK <input type="checkbox"/>	PLUG AND ABANDON <input checked="" type="checkbox"/>	REMEDIAL WORK <input type="checkbox"/>	ALTERING CASING <input type="checkbox"/>
TEMPORARILY ABANDON <input type="checkbox"/>	CHANGE PLANS <input type="checkbox"/>	COMMENCE DRILLING OPNS. <input type="checkbox"/>	PLUG AND ABANDONMENT <input type="checkbox"/>
PULL OR ALTER CASING <input type="checkbox"/>	MULTIPLE COMPLETION <input type="checkbox"/>	CASING TEST AND CEMENT JOB <input type="checkbox"/>	
OTHER: <input type="checkbox"/>		OTHER: <input type="checkbox"/>	

12. Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work). SEE RULE 1103. For Multiple Completions: Attach wellbore diagram of proposed completion or recompilation.

1. MIRUPU. KILL WELL. NDWH. NU & TEST BOPE. PU 2-7/8" WS.
2. RIH W/WS TO 3250'. TAG PLUG. CIRC HOLE W/MUD.
3. PUH TO 2550'. PUMP 25 SX CL C PLUG. (BASE OF SALT).
4. PUH TO 1325'. PUMP 25 SX CL C PLUG. (TOP OF SALT).
5. PERFORATE CSG @ 170'. EST CIRC. PUMP 100 SX CL C AND CIRC TO SURF. TAG PLUG.
6. FILL CSG WITH CMT TO SURFACE. CUT OFF & INSTALL P&A MARKER.

RECOMPLETION MUST BE NOTICED 24  
HOURS BEFORE THE BEGINNING OF  
PLUGGING OPERATIONS BY THE C-103  
TO BE APPROVED.

I hereby certify that the information above is true and complete to the best of my knowledge and belief.

SIGNATURE Sabra Woody TITLE ENGR TECH III DATE 01/25/01

Type or print name SABRA WOODY Telephone No. 915/683-0534

(This space for State use)

APPROVED BY \_\_\_\_\_ TITLE \_\_\_\_\_ DATE \_\_\_\_\_  
Conditions of approval, if any:

Je

dx