

Submit 3 Copies
to Appropriate
District Office
District I
P.O. Box 1980, Hobbs, NM 88240
District II
P.O. Drawer DD, Artesia, NM 88210
District III
1000 Rio Brazos Rd. Aztec, NM 87410

State of New Mexico
Energy, Minerals and Natural Resources Department
OIL CONSERVATION DIVISION
P.O. Box 2088
Santa Fe, New Mexico 87504-2088

Form C-103
Revised 1-1-89

WELL API NO.	30 - 025 - 10543
5. Indicate Type of Lease	STATE <input checked="" type="checkbox"/> FEE <input type="checkbox"/>
6. State Oil & Gas Lease No.	B2320
7. Lease Name or Unit agreement Name	SKELLY PENROSE B UNIT
8. Well No.	5
9. Pool name or Wildcat	LANGLIE MATTIX 7 RVR Q-GB

SUNDRY NOTICES AND REPORTS ON WELLS (DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A DIFFERENT RESERVOIR. USE "APPLICATION FOR PERMIT" (FORM C-101) FOR SUCH PROPOSALS.)	
1. Type of Well: OIL WELL <input type="checkbox"/> GAS WELL <input type="checkbox"/> OTHER INJECTION	
2. Name of Operator OXY USA INC.	
3. Address of Operator P.O. Box 50250 Midland, TX 79710	
4. Well Location Unit Letter <u>F</u> : <u>1,980</u> Feet From The <u>NORTH</u> Line and <u>2,310</u> Feet From The <u>WEST</u> Line Section <u>32</u> Township <u>22 S</u> Range <u>37 E</u> NMPM LEA County	
10. Elevation (Show whether DF, RKB, RT, GR, etc.) 3,353	

11. Check Appropriate Box to Indicate Nature of Notice, Report, or Other Data

NOTICE OF INTENTION TO: PERFORM REMEDIAL WORK <input type="checkbox"/> PLUG AND ABANDON <input type="checkbox"/> TEMPORARILY ABANDON <input checked="" type="checkbox"/> CHANGE PLANS <input type="checkbox"/> PULL OR ALTER CASING <input type="checkbox"/> OTHER: <input type="checkbox"/>		SUBSEQUENT REPORT OF: REMEDIAL WORK <input type="checkbox"/> ALTERING CASING <input type="checkbox"/> COMMENCE DRILLING OPNS. <input type="checkbox"/> PLUG AND ABANDONMENT <input type="checkbox"/> CASING TEST AND CEMENT JOB <input type="checkbox"/> OTHER: TEMPORARILY ABANDON <input checked="" type="checkbox"/>	
---	--	--	--

12. Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work) SEE RULE 1103.

TD - 3800' PBTD - 3740' PERFS - 3594' - 3709'

MIRU PU 5/12/93, NDWH, NUBOP, POOH W/ JUNK TBG, RIH & TAG @ 3594'. DIG OUT CELLAR, 8-5/8" CSG PARTED BELOW WH. REMOVE & INSTALL NEW 5-1/2" & 8-5/8" CSG HEAD & CSG RISER. RIH & TEST CSG TO 500# - HELD OK, RIH W/ CIBP & SET @ 3550', CIRCULATE HOLE W/ CORR INHIB, POOH W/ TBG, NDBOP, NUWH, TEST CSG TO 500# - 15MIN - HELD OK, RDPU 5/17/93. WELL IS TA'D.

I hereby certify that the information above is true and complete to the best of my knowledge and belief.

SIGNATURE David Stewart TITLE Production Accountant DATE 06 09 93
TYPE OR PRINT NAME David Stewart TELEPHONE NO. 915 685-5717

(This space for State Use)

ORIGINAL SIGNED BY JERRY BEXTON
DISTRICT I SUPERVISOR

APPROVED BY _____ TITLE _____ DATE JUN 15 1993

CONDITIONS OF APPROVAL, IF ANY:

This Approval of Temporary Abandonment Expires

6-1-98

JUN 14 1993

COD HOBBS OFFICE