

| | | |
|------------------------|--|--|
| NO. OF COPIES RECEIVED | | |
| DISTRIBUTION | | |
| SANTA FE | | |
| FILE | | |
| U.S.G.S. | | |
| LAND OFFICE | | |
| OPERATOR | | |

NEW MEXICO OIL CONSERVATION COMMISSION

Form C-103
Supersedes Old
C-102 and C-103
Effective 1-1-65

5a. Indicate Type of Lease
State Fee

5. State Oil & Gas Lease No.

SUNDRY NOTICES AND REPORTS ON WELLS
(DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A DIFFERENT RESERVOIR. USE "APPLICATION FOR PERMIT -" (FORM C-101) FOR SUCH PROPOSALS.)

| | |
|--|---|
| 1. OIL WELL <input type="checkbox"/> GAS WELL <input type="checkbox"/> OTHER <input type="checkbox"/> | 7. Unit Agreement Name |
| 2. Name of Operator TEXAS PACIFIC OIL COMPANY | 8. Farm or Lease Name Ella Drinkard |
| 3. Address of Operator P. O. Box 1069 - Hobbs, New Mexico 88240 | 9. Well No. 2 |
| 4. Location of Well UNIT LETTER E , 1650 FEET FROM THE North LINE AND 660 FEET FROM THE West LINE, SECTION 25 TOWNSHIP 22-S RANGE 37-E NMPM. | 10. Field and Pool, or Wildcat Undesignated |
| 15. Elevation (Show whether DF, RT, GR, etc.) 3326.8' GR | 12. County Lea |

16. Check Appropriate Box To Indicate Nature of Notice, Report or Other Data

| NOTICE OF INTENTION TO: | | SUBSEQUENT REPORT OF: | |
|--|---|---|---|
| PERFORM REMEDIAL WORK <input type="checkbox"/> | PLUG AND ABANDON <input type="checkbox"/> | REMEDIAL WORK <input checked="" type="checkbox"/> | ALTERING CASING <input type="checkbox"/> |
| TEMPORARILY ABANDON <input type="checkbox"/> | CHANGE PLANS <input type="checkbox"/> | COMMENCE DRILLING OPNS. <input type="checkbox"/> | PLUG AND ABANDONMENT <input type="checkbox"/> |
| PULL OR ALTER CASING <input type="checkbox"/> | OTHER <input type="checkbox"/> | CASING TEST AND CEMENT JOB <input type="checkbox"/> | OTHER <input type="checkbox"/> |

17. Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work) SEE RULE 1103.

1. Open well to flow & test. (Brunson Granite Wash)
2. Moved in, rigged up, pulled rods and tubing.
3. Perf. Abo 6834-40-76-86-89-6900-13-20-35-51-89-7011-31-37-50-59-73-7133-52-61-89 & 93' w/1/4" holes.
4. Ran tubing and packer @6734' and acidized w/7500 gal. 15% acid / ball sealers.
5. Swabbed to flow & test.
6. Well was temporarily abandoned 9-24-68 for further study.

18. I hereby certify that the information above is true and complete to the best of my knowledge and belief.

Original Signed by
SIGNED Sheldon Ward TITLE Area Superintendent DATE 12-3-68

APPROVED BY [Signature] TITLE SUPERVISOR DATE _____

CONDITIONS OF APPROVAL, IF ANY: